STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL DIVISION OF AIR & WASTE MANAGEMENT 391 LUKENS DRIVE NEW CASTLE, DELAWARE 19720-2774



WASTE MANAGEMENT SECTION
TANK MANAGEMENT BRANCH

TELEPHONE: (302) 395-2500 FAX No.: (302) 395-2555

January 27, 2006

Mr. John Willey Penisula Oil Company 405 Market Street Seaford DE 19973

RE:

No Further Action Required - Tank Removal

Facility ID:

5-000209

Uncle Willies # 18

330 West Stein Highway

File Code:

30

Seaford DE 19973

Dear Mr. Willey:

On July 19, 2005 five (5) underground storage tanks (USTs) were removed at this facility. Soil samples were collected and analyzed for petroleum contamination.

The analytical results are as follows:

Analyte (action level, mg/kg)	Shallow Composite Sample (mg/kg)	Deep Grab Sample (mg/kg)
DERBCAP* Tier 0	Tank 1: 4000 gallon gasoline	
BTEX (10)	BDL**	BDL
Benzene (0.230)	DDI	BDL
TPH-GRO (100)	DDI	BDL
Lead (400)	2.93	BDL
EDB (0.010)	BDL	BDL
EDC (0.400)	BDL	BDL
MTBE (0.130)	BDL	BDL

Tank 2: 4000 gallon gasoline			
BTEX (10)	BDL	BDL	
Benzene (0.230)	BDL	BDL	
TPH-GRO (100)	BDL	BDL	
Lead (400)	3.54	BDL	
EDB (0.010)	BDL	BDL	
EDC (0.400)	BDL	BDL	
MTBE (0.130)	BDL	BDL	

Tank 3: 4000 gallon gasoline			
BTEX (10)	BDL	BDL	
Benzene (0.230)	BDL	BDL	
TPH-GRO (100)	BDL	BDL	
Lead (400)	BDL	BDL	
EDB (0.010)	BDL	BDL	
EDC (0.400)	BDL	BDL	
MTBE (0.130)	BDL	BDL	

Mr. John Willey January 27, 2006 Page Two

Tank 4: 4000 gallon gasoline			
BTEX (10)	BDL	BDL	
Benzene (0.230)	BDL	BDL	
TPH-GRO (100)	BDL	BDL	
Lead (400)	2.69	2.87	
EDB (0.010)	BDI.	BDI.	
EDC (0.400)	BDL	BDL	
MTBE (0.130)	BDL	BDL	
Tank 5: 1000 gallon heating fucl			
TPH_DRO (1000)	BDL	BDI.	

	Dispenser Island: 1 deep grab sample	Dispenser Island: 2 deep grab sample
BTEX (10)	BDL	BDL
Benzene (0.230)	j BDÏ.	BDL
JPH- GRO (100)	BDL	BDL
Lead (400)	3.6	2.36
EDB (0.010)	BDL	BDL
EDC (0.400)	BDL	BDL
MTBE (0.130)	BDI.	BDI.

Dispenser Island: 3 deep grab sample		Dispenser Island: 4 deep grab sample
BTEX (10)	BDL	BDL
Benzene (0.230)	BDI.	BDL
TPH-GRO (100)	BDL	BDL
Lead (400)	BDL	BDL
EDB (0.010)	BDL	; BDL
EDC (0.400)	BDL	BDL
MTBE (0.130)	BDL	BDI.

^{*}Delaware Risk-Based Corrective Action Program

Based on these results, it appears that any residual contamination at this location poses no threat to human health and safety, and to the environment, and no further action is required at the present time. The site may be used without restriction. This No Further Action (NFA) letter relates only to liability under 7 <u>Del.C.</u>, Chapter 74 and does not represent a determination under any other State or Federal law.

In addition, pursuant to Delaware's Regulations Governing Underground Storage Tank Systems (the Regulations) and 7 Del.C., Chapter 74, this letter does not release Penisula Oil Company from liability for any future problem related or unrelated to the UST's removed at this location. If any new releases are identified, immediate action must be taken to eliminate any threat to public health and safety, and to the environment, and the Department of Natural Resources and Environmental Control, Tank Management Branch (the Department) must be notified. In all cases, the Department reserves the right to re-assess the site in the future if new information comes to light regarding possible petroleum contamination.

^{**}BD1.- Below the Detection Limit of the Analyses Preformed

Mr. John Willey January 27, 2006 Page Three

If you have any further questions about your facility please call (302) 395-2500.

Sincerely,

Suzanne Halter

Environmental Scientist Tank Management Branch

DB:SAII\ dpc sah2006-005