



*COMMONWEALTH of VIRGINIA*  
*DEPARTMENT OF ENVIRONMENTAL QUALITY*

Molly Joseph Ward  
Secretary of Natural Resources

PIEDMONT REGIONAL OFFICE  
4949-A Cox Road, Glen Allen, Virginia 23060  
(804) 527-5020 Fax (804) 527-5106  
[www.deq.virginia.gov](http://www.deq.virginia.gov)

David K. Paylor  
Director

Jeffery A. Steers  
Regional Director

April 26, 2017

Ms.. Gail Rhodes  
Southside General 2  
613 Hicks St  
Lawrenceville, VA 23868

RE: UST Compliance at Southside General 2 (4001017)  
18096 Christiana Hwy, Lawrenceville, VA 23868

Dear Ms.. Rhodes,

The Department of Environmental Quality (DEQ) conducted an inspection on March 21, 2017 of the underground storage tank (UST) facility referenced above. This inspection did not reveal any compliance issues under 9 VAC 25-580-10 et seq. that need to be addressed at this time. Please note that this inspection and letter do not address compliance with financial responsibility requirements. Therefore, additional information may be requested to demonstrate compliance with 9 VAC 25-590 (Virginia Petroleum UST Financial Responsibility Requirements). This information will be requested by DEQ's Office of Financial Responsibility and Data Management (OFRDM). If you have any questions regarding the UST financial responsibility requirements or how to prepare the documentation, please contact Josiah Bennett, OFRDM, at (804) 698-4205. Please contact me at if you have any questions regarding the inspection.

Sincerely,  
  
Michael Kelly  
Petroleum Facility Inspector

CC: Facility ID # 4001017