

|                   | S | U | REMARKS                                              |
|-------------------|---|---|------------------------------------------------------|
| Exterior Front    |   | X | Scrape & paint door frame                            |
| Side (in)         | ✓ |   |                                                      |
| Rear              |   | X | repair or remove old sheds & platform                |
| Rear deck         |   | X | repaint deck                                         |
| Basement          |   | X | remove light & wire from top of stairs               |
|                   |   | X | install Blank in open slot of Service panel          |
|                   |   | X | needs C.O. Alarm                                     |
|                   |   | X | outlet at wash Area needs GFCI                       |
|                   |   | X | remove carpet 36" around stove, or remove wood stove |
| Kitchen           |   | X | (2) outlets at sink need GFCI                        |
| Dinning/living rm |   | X | secure heater to wall (at door)                      |
|                   |   | X | Smoke Alarm                                          |
| 1/2 Bath          |   | X | outlet needs GFCI                                    |
| Stairs & Hall     | ✓ |   |                                                      |
| Bath              | ✓ |   |                                                      |
| Bed #1 (Front)    |   | X | repair or replace windows (must stay up)             |
|                   |   | X | Smoke Alarm                                          |
|                   |   | X | restore power to outlet behind door, or remove       |

C. Beck  
Public Officer

9/16/20  
Inspection Date

[Signature]  
Owner/Agent/Manager

9/16/2020  
Inspection Date

Public Officer

Re-Inspection Date

Owner/Agent/Manager

Re-Inspection Date

**CITY OF ALLENTOWN  
BUILDING STANDARDS & SAFETY**

**INSPECTION REPORT**

Owner: Nereida Ortiz

Address: 811 S Armour St

|                  | S | U | REMARKS                                                                |
|------------------|---|---|------------------------------------------------------------------------|
| Bed # 2 (rear S) | + |   | Smoke Alarm                                                            |
|                  | + |   | replace outlet (Behind door)                                           |
|                  | + |   | outlet at window ungrounded<br>(ground, or replace with 121 plug type) |
|                  | + |   | repair or replace window                                               |
| Bed # 3 (rear N) | + |   | Smoke Alarm                                                            |
|                  | + |   | repair or replace outlet at door, no<br>power to Bottom plug           |
|                  | + |   | repair or replace window                                               |
| note {           | + |   | repair <del>all</del> or replace All windows as<br>needed,             |
|                  | + |   | Install All smoke Alarms within 10 days                                |
|                  | + |   | Contact Inspector within 30 days of sale                               |

B. Beck  
Public Officer

9/16/20  
Inspection Date

[Signature]  
Owner/Agent/Manager

9/16/2020  
Inspection Date

Public Officer

Re-Inspection Date

Owner/Agent/Manager

Re-Inspection Date