

Lot Number	Title	Description
0	Preview & Removal Information	<p>**All purchases will be subject to a 13% buyer's premium.**</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, February 14, 2019 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.)</p> <p>Location: 200 N. Station Street, Port Aransas, Tx 78373 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Wednesday, February 20, 2019/Thursday, February 21, 2019/Friday, February 22, 2109 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.)</p> <p>Preview & Removal Contacts: Pete Cowen, (361)749-1211 or (361)816-5932 Jessie Charles, (361)658-0269</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p>
1	(1) 2001 International Bluebird School Bus Vin #3666 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 67 - Conventional Style - Passengers: 71 - Engine Size/Type: V8 T444E - Engine In Front - Engine Problems: Oil Leak, Would Recommend Towing - Diesel - Battery: Yes - Runs - Automatic - Transmission Type /Condition: Allison/Fair Condition, No Issues - Air Brakes - Inspection Sticker Date: 11/18 - Approx. Mileage Reads: 155,468**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning - Body Condition: Fair - Body Problems: Minor Dents, Ding, Scratches & Rust, Paint Is Faded & Peeling In Some Areas - Tires Condition: Fair - Tire Problems: Minor Cracks On Tires, Tread Is Good - Air Condition Systems Are (1) Year Old, New</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
2	(1) 2001 International Bluebird School Bus Vin #3684 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 70 - Conventional Style - Passengers: 71 - Engine Size/Type: V8 T444E - Engine In Front - Engine Problems: No Power Steering, Pump Is Not Working, Would Recommend Towing - Diesel - Battery: Yes - Runs - Automatic - Transmission Type/Condition: Allison/No Issues - Air Brakes - Inspection Sticker Date: 10/18 - Approx. Mileage Reads: 158,677**Unknown Actual Mileage** - Interior Condition: Fair - Interior Condition: Needs Cleaning - Body Condition: Fair - Body Problems: Minor Dents, Dings, Scratches & Rust, Paint Is Fading & Peeling In Areas - Tires Condition: Fair - Tire Problems: Minor Cracking, Tread Is Good - Air Condition Systems (1) Year Old, Complete Systems New</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
3	(1) 2001 International Bluebird School Bus Vin #3621	<p>Bus #: 71 - Conventional Style - Passengers: 71 - Engine Size/Type: V8 T444E - Engine In Front - Diesel - Battery: Yes - Runs - Automatic - Transmission Type/Condition: Allison/No Issues - Air Brakes - Inspection Sticker Date: 10/18 - Approx. Mileage Reads: 165,441**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning - Body Condition: Fair - Body Problems: Minor Dents, Dings, Scratches & Rust, Paint Is Fading & Peeling In Areas - Tires Condition: Fair - Tire Problems: Minor Cracking, Tread Is Good - Air Conditioning Systems Are (1) Year Old, Completely New - Instrument Cluster Is Faulty, Works Sporadically</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>