

Lot Number	Title	Description
0	Preview & Removal Information	<p>**There Will Be A 13% Buyer's Premium Added To All Buyer's Total For Each Item Purchased.**</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, April 2, 2019 (Hours Of Operation: 7:00 a.m. - 3:30 p.m.)</p> <p>Location 1: (Lots 1-20) Magnolia ISD Maintenance, 31138 Nichols Sawmill Rd., Magnolia, Tx 77355 - Behind Magnolia Jr. High/Tan Metal Warehouse Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions)Friday, April 5, 2019/Monday, April 8, 2019/Tuesday, April 9, 2019 (Hours Of Operation: 7:00 a.m. - 3:30 p.m.)</p> <p>Preview & Removal Contact: Rachel Collins, (281)252-2186 X1305</p> <p>No Lifting Equipment Will Be Available. Buyer Solely Responsible For Removal.</p> <p>Location 2: (Lots 100-117) Transportation Department, 315 Sanders St., Magnolia, Tx 77355 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions)Friday, April 5, 2019/Monday, April 8, 2019/Tuesday, April 9, 2019 (Hours Of Operation: 7:00 a.m. - 3:30 p.m.)</p> <p>Preview & Removal Contact: Rachel Collins, (281)252-2186 X1305</p> <p>Magnolia ISD Will Be Handling All Title Work For This Auction. Please Contact Seller For Title Information. Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed.</p>
1	(1) Serving Line	4 Well - Custom Made - One Side Is Cut Out For Removal - 115" Long X 45" Wide - Has Tray Shelf - Current Condition Unknown
2	(Lot) Refrigerator & Warmer	Including: (1) Refrigerator, (1) Warmer, Parts Only Units - No Compressor - Missing Parts - Current Condition Unknown
3	(1) Amana Side By Side Refrigerator	ASD2522URS01 - Worked At Time Of Removal - Missing Some Shelves - Current Condition Unknown
4	(1) GE Electric Double Oven	Missing Wire Rack On Top Oven - Current Condition Unknown
5	(Lot) Speakers	Stadium Style - Including: (Approx. 8) PD60AT - Atlas Sound LP, Ennis, Tx, (Approx. 2) Altec/Atlas Sound LP - Model: PD60AT - Current Condition Unknown
6	(1) GE Electric Stove	Model: JBS27BC1WH - Works - Current Condition Unknown
7	(1) Glastender	Approx. Size: 60" Long X 24" - Works - Model: ST60-B - Single Phase - Portable - Current Condition Unknown
8	(Lot) Freezer Racks	(Approx. 4) Some Are Missing Uprights - Current Condition Unknown
9	(1) Traulsen Double Sided Refrigerator	Model: RHT132WPUT-HHS - Single Phase - Works - Current Condition Unknown
10	(1) Scotsman Ice Machine	C0530MA-1A - Single Phase - Not Working - Needs Repair - Current Condition Unknown
11	(1) Hobart Electric Fryer	Model: 1HFD50 - 3 Phase - Stationary - Works - Current Condition Unknown
12	(1) Hobart Electric Fryer	Model:1HFD50 - 3 Phase - Stationary - Works - Current Condition Unknown
13	(1) Cleveland Steamer	24CGA10-2 - Single Phase - Stationary - Works - Current Condition Unknown
14	(1) Roper Refrigerator	Model: RT18DKXBL01 - Type: 18TFA94 - Worked At Time Of Removal - Current Condition Unknown

15	(1) Whirlpool Refrigerator	Model: ET18TK - 18 Cubic Ft. - Worked At Time Of Removal - Current Condition Unknown
16	(1) Crescor Proofing Warming Cabinet	Model: 121PHUA11D - 120 Volts - 1920 Watts - 60 Hz - Phase 1 - Needs Repair - Will Not Hold Head - Glass Front - Portable - Current Condition Unknown
17	(Lot) Merco Warming Display Shelves	(Approx. 2) Model Unknown - Current Condition Unknown
18	(1) Cabinet Shop Fan	Wall Type - Dayton - Approx. 42" - 3 Phase - 6D578 - Current Condition Unknown
19	(1) Paint Stripper	EZ-Linder Ind. - Worked When Last Used Several Years Ago - Current Condition Unknown - Tires Need Air - W/ (1) Metal Cart - Current Condition Unknown
20	(1) Metal Serving Line	Approx. Size: 169" Long X 63" Widest Width - W/ (4) Well Steam Table - W/ Cold Storage - Atlas Metal Industries & Misc. - Current Condition Unknown
100	(1) 1993 International Thomas School Bus Vin #6567 - Will Possibly Need To Be Towed	Will Possibly Need To Be Towed - Bus #: 4086 - Conventional Style - Passengers: 71 - Engine Size/Type: 7.3 - Engine In Front - Engine Problems: Smoking, Worn Out Motor, Ran When Parked - Diesel - Battery: Yes/Dead - Runs - Automatic - Air Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Reads: 249,731**Unknown Actual Mileage** - Approx. Hub Reads: 250,523 - Interior Condition: Fair - Interior Problems: Some Torn Seats, Drivers Seat Torn, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Some Surface Rust, Surface Scratches, Peeling On Cowl - Tire Problems: Good In Rear, Fair To Poor In Front - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
101	(1) 1991 International Thomas School Bus Vin #0871 - Runs	Bus #: 4082 - Conventional Style - Passengers: 20 Passengers W/ (1) Wheel Chair Space - Engine Size/Type: 7.3L - Engine In Front - Engine Problems: Runs, Removed Due To Wheel Chair Lifts Are To Small - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic - Hydraulic Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Reads": 390,503**Unknown Actual Mileage** - Interior Condition: Fair - Wheel Chair Lift, Condition Unknown - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Some Peeling Paint, Peeling On Hood & Cowl - Tire Problems: Good In Rear & Front - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
102	(1) 1995 International 3800 School Bus Vin #1235 - Will Need To Be Towed	Will Need To Be Towed - Recommend Salvage Or Parts Use - Bus #: 4093 - Conventional Style - Passengers: 71 - Engine Size/Type: T444E - Engine Problems: Bad Engine, Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic - No Transmission - Air Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Reads: 306,032**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rear Bumper Has Large Dent, Peeling On Cowl & Hood, Slight Indention On Left Rear - Tire Condition: Poor To Fair - Large Notch Broken Off On Left Front Wheel Well - Current Condition Unknown There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**

103	(1) 1992 International School Bus Vin #8076 - Runs	<p>Bus #: 4083 - Passengers: 22 Passengers & (1) Wheel Chair - Engine Size/Type: 7.3L - Engine In Front - Engine Problems: Runs, Worn Engine, Wheel Chair Lift Is Too Small - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic - Hydraulic Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Reads: 323,941**Unknown Actual Mileage** - Interior Condition: Fair - Wheel Chair Lift, Condition Unknown - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Peeling On Cowl & Hood - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
104	(1) 1997 International 3800 Thomas School Bus Vin #8096 - Runs	<p>Bus #: 4112 - Conventional Style - Passengers: Unknown - Engine Size/Type: 444E - Engine Problems: Runs, Bus & Wheel Chair Lift Too Small - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic - Hydraulic Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 362,902**Unknown Actual Mileage** - Interior Condition: Fair - Wheel Chair Lift, Condition Unknown - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Drivers Side Window Is Loose Inside Bus, Peeling On Cowl & Hood, Missing (1) Mirror - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
105	(1) 1990 International Thomas School Bus Vin #3882 - Runs	<p>Bus #: 4073 - Passengers: 71 - Engine Size/Type: 7.3L - Engine Problems: Runs, Rotted Roof Around Hatch - Diesel - Battery: Yes/Dead - Runs - Automatic - Air Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Reads: 247,468 **Unknown Actual Mileage** - Interior Condition: Fair To Poor - Interior Problems: Torn Seats, Needs Cleaning, Roof Hatch Is Missing In Rear - Body Condition: Fair - Body Problems: Oxidized Paint, Rub Rail Paint Worn, Some Peeling Paint, Rust Spot On Left Rear, Surface Scratches, (Approx. 2) Machined Holes On Hood - Tires Condition: Poor On Right Rear</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
106	(1) 1994 International Thomas School Bus Vin #9008 - Runs	<p>Bus #: 4091 - Engine Size/Type: DT360 - Engine Problems: Bad Head & Overheats, Needs Repair, Do Not Drive Very Far Before Repairing, Long Haul Suggest Wrecking - Diesel - Battery: Yes/Dead - Runs - Automatic - Air Brakes - Inspection Sticker Date: 07/19 - Approx.. Mileage Reads: 309,893**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Needs Cleaning, Peeling On Cowl, Rock Chip On Windshield, Large Indention Left Side Lower Panel, Surface Rust - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

107	(1) 2001 Thomas School Bus Vin #6096 - Runs	<p>Bus #: 4133 - Transit Style - Passengers: 84 - Engine Size/Type: 5.9L Cummins - Engine In Front - Engine Problems: Worn Out Engine, Will Run - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic - Air Brakes - Inspection Sticker Date: 07/19 - Dead Battery - Interior Condition Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint - Tires Condition: Poor On Right Rear, Fair On Remainder Tires - Has Lower Storage Compartments</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
108	(1) 2001 Thomas School Bus Vin #6100 - Runs	<p>Bus #: 4137 - Transit Style - Passenger: 84 - Engine Size/Type: 5.9L Cummins - Engine In Front - Engine Problems: Wore Out Engine - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic - Air Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Unknown - Interior Condition: Fair - Interior Problems: Missing Roof Hatch, Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Some Peeling Paint, Scratch On Left Rear Upper Panel, Surface Scratches, Scratches - Tires Condition: Fair - Has Storage On Lower Panels</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
109	(1) 1987 International S1700 School Bus Vin #7440 - Runs	<p>Bus #: 4063 - Conventional Style - Passengers: 71 - Engine Size/Type: 7.3L - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic - Air Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 245,907**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Poor, Seats Torn Throughout Bus, Floor Will Need Replacing In Future - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Surface Rust On Right Side Along W/ Peeling Paint, Rust On Rear Door - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
110	(1) 1999 Freightliner School Bus Vin #6771 - Will Possibly Need To Be Towed/Starts	<p>Will Possibly Need To Be Towed -Bus #: 4113 - Conventional Style - Passengers: 39 Passengers W/ (1) Wheel Chair Space - Engine Size/Type: 5.9 Cummins/24 Valve - Engine Problems: Will Start, Wore Out, Running Condition Unknown - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Unknown If Running/Starts - Automatic - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 481,974**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Dents, Missing Front Mirror - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

111	(1) 1987 International S1700 School Bus Vin #7439 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 4062 - Conventional Style - Passengers: 71 - Engine Problems: Bad Motor, Bad Transmission - Diesel - Battery: Yes/Dead - Does Not Run - Automatic - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 207,387**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats All Over, Floor Soft - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rust Hole On Rear Door, Rock Chip On Windshield, Peeling On Hood - Tires Condition: Fair To Poor</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
112	(1) 1990 International Thomas School Bus Vin #0841 - Will Possibly Need To Be Towed	<p>Will Possible Need To Be Towed - Bus #: 4077 - Conventional Style - Passengers: 72 - Engine Size/Type: 7.3 - Runs/Bad Motor - Diesel - Battery: Yes - Runs - Bad Motor - Automatic - Air Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 252,614**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats All Over, Needs Cleaning, Floor Soft & Will Need Repair - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rock Chip On Windshield, Broken Entry Door Window - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
113	(1) 1990 International 3800 School Bus Vin #3880 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 4071 - Conventional Style - Passengers: 71 - Engine Size/Type: 7.3 - Engine In Front - Diesel - Battery: Yes/Dead - Runs - Automatic - Air Brake - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 295,032**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Minor Torn Seats, Fading, Minor Rust On Front Dash - Body Condition: Fair - Body Problems: Minor Scratches & Dents All Over, Large Scratch Near Passenger Side, Heavy Rust Rear Of bus, Cracked Rear Window On Door - Tires Problems: Need Air - Oxidized Paint</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
114	(1) 1987 International S1700 School Bus Vin #7441 - Runs	<p>Bus #: 4064 - Conventional Style - Passengers: 71 - Engine Size/Type: 7.3 - Engine In Front - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic - Air Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 272,300**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Torn Seats, Fading Seats, Minor Rust On Dash - Body Condition: Fair - Body Problems: Minor Scratches & Dents, Rust Hole On Back Door & Side Panel, Rust Spot Drivers Side - Tires Condition: Fair - Tire Problems: Need Air - Roof Hatch Broken</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

115	(1) 2000 Freightliner School Bus Vin #3568 - Runs	<p>Bus #: 4124 - Conventional Style - Passengers: 39 - Engine In Front - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic - Air Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 226,252**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Torn Seats, Mismatched Seats, Fading - Body Condition: Fair - Body Problems: Minor Scratches & Dents All Over, Oxidized Paint - Tires Condition: Fair - Tire Problems: Need Air - Front Windshield Has Cracks, Drivers Side Rear Has Several Dents, Missing Covers On Lights</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
116	(1) 2001 Thomas School Bus Vin #6098 - Runs	<p>Bus #: 4135 - Transit Style - Passengers: 84 - Engine In Rear - Diesel - Battery: Yes/Dead - Runs - Automatic - Air Brakes - Inspection Sticker Date: 06/19 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Faded Seats - Body Condition: Fair - Body Problems: Some Cracked Fiberglass On Front, Dent Passenger Side Storage Area, Peeling Paint, Oxidized Paint, Minor Scratches & Dents, Dent On Drivers Side Rear - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
117	(1) 1988 International School Bus Vin #7621 - Will Need To Be Towed	<p>Will Need To Be Towed- Bus #: 4068 - Conventional Style - Passengers: 71 - Engine Size/Type: S1700/7.3 - Engine In Front - Engine Problems: Bad Motor - Diesel- Battery: Yes - Does Not Run - Automatic - Air Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 255,412**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Torn Seats, Fading - Body Condition: Fair - Body Problems: Peeling Paint, Oxidized - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>