

Lot Number	Title	Description
0	Preview & Removal Information	<p>All purchases will be subject to a 13% buyer's premium.</p> <p>Preview: (By Appointment Only - No Exceptions) Monday, April 8, 2019 (Hours of Operation: 8:00 a.m. - 4:00 p.m.) Location: Willis ISD, 215 Philpot, Willis, Tx 77378 Driving Directions Removal: (By Appointment Only - No Exceptions) Thursday, April 11, 2019/Friday, April 12, 2019/Monday, April 15, 2019 (Hours of Operation: 9:00 a.m. - 12:00 p.m./3:00 p.m. - 5:00 p.m.) Preview & Removal Contact: Michael Maiorano, (936)890-8751 Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p>
1	(1) 1999 Ford F250 Pickup Truck Vin #4270 - Runs	<p>Unit #: M9 - Engine Size/Type: V8-4.66 - Engine In Front - Engine Problems: Needs New Battery - Gas - Battery: Yes /Needs New Battery - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Runs - Automatic - Transmission Condition: Fair - Hydraulic Brakes - Inspection Sticker Date: 05/19 - Approx. Mileage Reads: 168,828**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Broken Down Seats, Rust - Body Condition: Poor - Body Problems: Dents, Scratches, Rust</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
2	(1) 2000 Ford Ranger Pickup Truck Vin #9418 - Runs	<p>Unit #: M12 - Engine Size/Type: V6-3.0L - Engine In Front - Engine Problems: Missing Cylinder - Gas - Battery: Yes - Runs - Automatic - Hydraulic Brakes - Transmission Condition: Fair - Inspection Sticker Date: 05/19 - Approx. Mileage Reads: 152,025**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Moldy - Body Condition: Fair - Body Problems: Scratches, Dents, Rust - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
3	(1) 2006 Chevy Impala Vin #7729 - Runs	<p>Unit #: 501 - Engine Size/Type: V6 Gas - Engine In Front - Gas - Battery: Yes - Runs - Automatic - Transmission Type: Fair - Hydraulic Brakes - Inspection Sticker Date: 06/18 - Approx. Mileage Reads: 152,192**Unknown Actual Mileage** - Interior Condition: Fair - Body Condition: Fair - Body Problems: Driver Door Won't Unlock With Key - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
4	(1) 2007 Chevy Impala Vin #4219 - Runs	<p>Unit #: 502 - Engine Size/Type: V6 - Engine In Front - Gas - Battery: Yes - Runs - Automatic - Transmission Type: Fair - Hydraulic Brakes - Inspection Sticker Date: 09/18 - Approx. Mileage Reads: 68,934**Unknown Actual Mileage** - Interior Condition: Fair - Body Condition: Fair - Body Problems: No Back Seat, Has K9 Cage Built In Instead Of Backseat - Former K9 Unit - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

5	(1) 2000 International School Bus Vin #3064 - Runs	<p>Bus #: 3064 - Conventional Style - Passengers: 71 - Engine Size/Type: 444E-V8 - Engine In Front - Diesel - Battery: Yes - Runs - Automatic - Transmission Condition: Fair - Air Brakes - Inspection Sticker Date: 08/18 - Approx. Mileage Reads: 204,885**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Moldy Seats, Weak Floor - Body Condition: Fair - Body Problems: Scratches, Faded Paint - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
6	(1) 1999 International School Bus Vin #9425 - Runs	<p>Bus #: 9424 - Conventional Style - Passengers: 71 - Engine Size/Type: 444E-V8 - Engine In Front - Diesel - Battery: Yes - Runs - Automatic - Transmission Condition: Fair - Air Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Reads: 187,740**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Rust & Weak On Floor - Body Condition: Fair - Body Problems: Scratches, Faded Paint - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
7	(1) 2000 International School Bus Vin #3067 - Runs	<p>Bus #: 3067 - Conventional Style - Passengers: 71 - Engine Size/Type: 444E-V8 - Engine In Front - Diesel - Battery: Yes - Runs - Automatic - Transmission Condition: Fair - Air Brakes - Inspection Sticker Date: 08/18 - Approx. Mileage Reads: 191,492.5**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Weak Floor, Moldy - Body Condition: Fair - Body Problems: Scratches, Faded Paint - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
8	(1) 2003 International School Bus Vin #6884 - Bus	<p>Bus #: 6884 - Conventional Style - Passengers: 71 - Engine Size/Type: 444E-V8 - Engine In Front - Diesel - Battery: Yes - Runs - Automatic - Transmission Condition: Fair - Air Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Reads: 211,379**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Moldy Seats, Weak Floor - Body Condition: Fair - Body Problems: Scratches, Faded Paint - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
9	(1) 1999 International School Bus Vin #9424 - Runs	<p>Bus #: 9425 - Conventional Style - Passengers: 71 - Engine Size/Type: V8 444E - Engine In Front - Diesel - Battery: Yes - Runs - Automatic - Transmission Condition: Fair - Hydraulic Brakes - Inspection Sticker Date: 09/18 - Approx. Mileage Reads: 176,186**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Moldy Seats, Rust, Weak Floor - Body Condition: Fair - Body Problems: Scratches, Faded Paint - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

10	(1) 2001 International School Bus Vin #1573 - Runs	<p>Bus #: 1573 - Conventional Style - Passengers: 71 - Engine Size/Type: 444E-V8 - Engine In Front - Diesel - Battery: Yes - Runs - Automatic - Transmission Condition: Fair - Air Brakes - Inspection Sticker Date: 08/18 - Approx. Mileage Reads: 208,553**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Moldy Seats, Weak Floor - Body Condition: Fair - Body Problems: Scratches, Faded Paint - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
----	--	--