

Lot Number	Title	Description
0	Preview & Removal Information	<p>**All purchases at will be subject to a 13% buyer's premium.**</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, May 14, 2019 (Hours Of Operation: 8:00 a.m. - 1:00 p.m.)</p> <p>Location: Pridgeon Stadium, 11355 Falcon Rd. A, Houston, Tx 77065 Driving Directions</p> <p>Removal: One Day Removal-No Exceptions (Manned Location-No Appointment Necessary) Friday, May 17, 2019/Monday, May 20, 2019/Tuesday, May 21, 2019/Wednesday, May 22, 2019/Thursday, May 23, 2019/Friday, May 24, 2019 (Hours of Operation: 8:00 a.m. - 1:00 p.m.)</p> <p>Removal Contact: Kristi Giron, 281-517-6367</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed No Cash Payments Accepted On Site</p>
1	(1) 1997 Chevy Lumina LTZ 4 Door Vin #2671 - Runs	<p>Unit #: 1730 - Conventional Style - Passengers: 5 - Engine Size/Type: 3.1L V6 - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic Transmission - Transmission Condition: Unknown - Hydraulic Brakes - Inspection Sticker Date: 01/19 - Approx. Mileage Reads: 109,765**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seat Worn, Dash Seams Pulling, Some Stains On Upholstery, Steering Wheel Worn - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Large Dents On Hood - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
2	(1) 1997 Chevy Lumina LTZ 4 Door Vin #2901 - Runs	<p>Unit #: 1731 - Conventional Style - Passengers: 5 - Engine Size/Type: 3.1L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Reads: 126,966**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Worn Upholstery, Headliner Needs Reattaching In Places, Seams On Dash Are Pulling Apart, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Peeling Paint, Rock Chip On Windshield, Dent On Right From Wheel Well, Scrape On Right Front Wheel Well, Right Mirror Damaged, Surface Rust, Minor Dents, Chipped Paint On Rear Bumper - Tires Condition: Good To Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
3	(1) 2000 Chevy Impala Vin #3152 - Runs	<p>Unit #: 1740 - Conventional Style - Passengers: 5 - Engine Size/Type: 3.4L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 167,165**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Normal Wear, Needs Minor Cleaning, Upholstery Appears In Good Condition - Body Condition: Fair - Body Problems: Oxidized Paint, Some Chipped Paint, Rock Chip On Windshield, Peeling Paint On Hood, Chipped Paint On Various Places - Tires Condition: Good To Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

4	(1) 2008 Ford Crown Victoria Vin #5758 - Runs	<p>Unit #: 1759 - Conventional Style - Passengers: 5 - Engine Size/Type: 4.6L - Gas - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Automatic Transmission - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 126,482**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Worn Seats, Has Police Console As Arm Rest, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 04/19 - Body Problems: Light Bar & Police Equipment Will Be Removed Prior To Unit's Removal, Oxidized Paint, Some Chipped Paint, Some Surface Rust, Surface Scratches - Tires Condition: Good To Fair - No Hub Caps</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
5	(1) 2008 Ford Crown Victoria Vin #9717 - Runs	<p>Unit #: 1752 - Conventional Style - Passengers: 5 - Engine Size/Type: 4.6L - Gas - Battery: Yes - Engine In Front - Engine Problems: Unknown - Run - Automatic Transmission - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 111,864**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Worn Upholstery, Police Console In Unit, All Police Equipment Will Be Removed, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 03/18 - Body Problems: Police Lights & Police Equipment Will Be Removed Prior To Removal, Oxidized Paint, Surface Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
6	(1) 2006 Ford Crown Victoria 4 Door Vin #3255 - Runs	<p>Unit #: 1748 - Passengers: 5 - Engine Size/Type: 4.6L - Gas - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Reads: 90,323**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Worn Upholstery, Needs Cleaning, Police Equipment Will Be Removed Prior To Removal - Body Condition: Fair - Inspection Sticker Date: 01/18 - Body Problems: Oxidized Paint, Surface Scratches, Some Peeling Paint, Scratch On Right Side Rear Bumper, Surface Rust, Hood Has Major Peeling - Tires Condition: Fair To Poor - Tire Problems: Right Front Tire Is Poor & Needs Air, No Hub Cap</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
7	(1) 2003 Chevy Impala Vin #6057 - Runs	<p>Unit #: 1746 - Passengers: 5 - Engine Size/Type: 3.8L - Gas - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Reads: 117,454**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Worn Upholstery, Police Equipment Will Be Removed Prior To Removal - Body Condition: Fair - Inspection Sticker Date: 08/18 - Body Problems: Oxidized Paint, Surface Scratches, Chipped Paint, Police Equipment Will Be Removed Prior To Removal - Tires Condition: Good To Fair - Tire Problems: Tire Will Need Air On Front Left</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

8	(1) 2009 Ford Crown Victoria 4 Door Vin #3071 - Runs	<p>Unit #: 1756 - Conventional Style - Passengers: 5 - Engine Size/Type: 4.6L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic - Transmission Condition: Unknown - Hydraulic Brakes - Inspection Sticker Date: 04/19 - Approx. Mileage Reads: 76,804**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Worn Upholstery, Police Equipment Will Be Removed Prior To Removal, Needs Cleaning, Prior Smoker In Unit - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Some Chipped Paint All Over Unit, Peeling Paint On Hood Of Car - Tires Condition: Fair - Tire Problems: No Hub Caps</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
9	(1) 2008 Ford Crown Victoria 4 Door Vin #9715 - Runs	<p>Unit #: 1753 - Passengers: 5 - Engie Size/Type: 4.6L - Gas - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Reads: 110,500**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Worn Upholstery, Needs Cleaning, Police Equipment Will Be Removed Prior To Removal - Body Condition: Fair - Inspection Sticker Date: 04/19 - Body Problems: Oxidized Paint, Some Chipped Paint, Surface Scratches, Peeling On Roof, Peeling All Over - Tires Condition: Good To Fair - Tire Problems: No Hub Caps</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
10	(1) 2008 Ford Crown Victoria 4 Door Vin #5756 - Runs	<p>Unit #: 1761 - Passengers: 5 - Engine Size/Type: 4.6L - Gas - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Reads: 96,672**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Worn Upholstery, Needs Cleaning, Police Equipment Will Be Removed Prior To Removal - Body Condition: Fair - Body Problems: Oxidized Paint, Peeling Paint, Surface Rust, Scratches, Police Equipment Will Be Removed Prior To Removal - Tires Condition: Fair - Tire Problems: No Hub Caps</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
11	(1) 2008 Ford Crown Victoria 4 Door Vin #9718 - Runs	<p>Unit #: 1754 - Passengers: 5 - Engine Size/Type: 4.6L - Gas - Battery: Yes - Engine Problems: Unknown - Runs - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Reads: 126,593**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Worn Upholstery, Needs Cleaning, Police Equipment Will Be Removed Prior To Removal - Body Condition: Fair - Inspection Sticker Date: 03/19 - Body Problems: Oxidized Paint, Surface Scratches, Some Chipped Paint, Police Equipment Will Be Removed Prior To Removal - Tires Condition: Good To Fair - Tire Problems: No Hub Caps</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

12	(1) 2012 Chevy Impala Vin #7449 - Will Need To Be Towed	<p>Will Need To Be Towed - Wrecked In Front - Conventional Style - Unit #: 4014 - Passengers: 5 - Engine Size/Type: V6 VUT Direct Injection - Gas - Battery: Yes/Dead - Engine In Front - Engine Problems: Wrecked, Condition Unknown - Does Not Run - Transmission Condition: Damage Unknown - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Unknown/Digital Unable To Read - Interior Condition: Poor - Interior Problems: Air Bag Is Open, Needs Cleaning, Police Equipment Will Be Removed Prior To Removal - Body Condition: Poor - Inspection Sticker Date: 01/19 - Body Problems: Police Equipment Will Need To Be Removed Prior To Removal, Front Wrecked, Auctioneer Recommends Preview - Tires Condition: Fair - In Back Seat There Area (2) Front Light Assemblies</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
13	(1) 2013 Ford Taurus 4 Door Vin #4724 - Will Need To Be Towed	<p>Will Need To Be Towed - Wrecked In Front - Unit #: 4007 - Conventional Style - Police Interceptor - Passengers: 5 - Engine Size/Type: 3.5L - Gas - Battery: Yes/Dead - Engine In Front - Engine Problems: Does Not Run/Wrecked/Damage Unknown - Does Not Run - Transmission Condition: Damage Unknown - Hydraulic Brakes - Automatic - Approx. Mileage Unable To Read/Digital - Interior Condition: Poor - Interior Problems: All Air Bags On Left Side Area Engaged, Needs Cleaning, Police Equipment Will Be Removed Prior To Removal - Body Condition: Poor - Inspection Sticker Date: 11/18 - Body Problems: Wrecked In Front, Recommend Preview For Full Inspection, Several Dents & Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
14	(1) 2014 Ford Taurus Police Interceptor 4 Door Vin #9726 - Will Need To Be Towed	<p>Will Need To Be Towed - Flooded Unit (Harvey) - Conventional Style - Unit #: 4026 - Passengers: 5 - Engine Size/Type: 3.7L - Gas - Battery: Yes/Dead - Engine In Front - Engine Problems: Problem Unknown, Air Cleaner Cover Missing, Vacuum Lines Missing, Missing Exhaust, Parts Missing - Does Not Run - Transmission Condition: Unknown - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Digital Unable To Read - Interior Condition: Fair - Interior Problems: Needs Cleaning, Police Equipment Will Be Removed Prior To Removal - Body Condition: Fair - Inspection Sticker Date: 01/18 - Body Problems: Surface Scratches, License Plate Lights Loose - Tires Condition: Fair To Poor - Tire Problems: Right Rear Tire Flat, All Tires Are Poor</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
15	(1) 1998 Chevy 3500 Van Vin #6770 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 1824 - Conventional Style - Passengers: 2 - Engine Size/Typ3: 350 5.7 LTN - Engine In Front - Engine Problems: Does Not Run, No Starter, Engine Issues Unknown - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Transmission Condition: Unknown - No Brakes/Master Cylinder Leaking - Inspection Sticker Date: 03/19 - Approx. Mileage Reads: 154,000+ **Unknown Actual Mileage/Unable To Read, Dead Battery** - Interior Condition: Poor - Interior Problems: Torn Seats, Holes In Floor, Rust, Needs Cleaning - Body Condition: Poor - Body Problems: Dents, Scratches, Rust, Broken Lights, Parts Missing, Peeling Paint, Surface Rust, Missing Right Rear Panel Near Door, Scratch/Dent On Right Rear, Major Peeling Paint In Front - Tires Condition: Fair - Has Headache Rack</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

16	(1) 1997 Chevy 1 Ton Cargo 3500 Van Vin #7750 - Will Need To Be Towed	<p>Will Need To Be Towed - Recommend Salvage Use - Fire Damage - Unit #: 1811 - Conventional Style - Passengers: 2 - Engine Size/Type: Unknown - Engine In Front - Engine Problems: Parts Missing, Fire On Motor, Damage Needs To Be Accessed By Bidder, Recommend Salvage Use - Gas - Battery: No - Does Not Run - Automatic - Hydraulic Brakes - Inspection Sticker Date: 10/17 - Approx. Mileage Unknown - Interior Condition: Poor - Interior Problems: Fire Damage In Front Cab Area, Shop Made Cabinets In Cargo Area - Body Condition: Poor - Body Problems: Oxidized Paint, Fire Damage Under Hood, Chipped Paint, Scratches, Dents, Peeling Paint - Tires Condition: Good To Fair - Has Headache Rack</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
17	(1) 1997 Chevy 3500 Van Vin #3900 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Unit #: 1806 - Passengers: 2 - Engine Size/Type: 5.7L - Gas - Battery: Yes /Dead - Engine In Front - Does Not Run - Engine Problems: Unknown - Does Not Run - Transmission Condition: Unknown - Hydraulic Brakes - Automatic - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Seat Cover Poor, Drivers Seat, Needs Cleaning, Worn Upholstery, Arm Rest Missing Passenger Side - Body Condition: Fair - Inspection Sticker Date: 07/18 - Body Problems: Oxidized Paint, Rock Chip On Windshield, Peeling Paint, Surface Rust, Scratches, Front Right Head Light Loose On Unit - Tires Condition: Fair To Poor</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
18	(1) 1998 Chevy 3500 Van Vin #5831 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 1819 - Conventional Style - Passengers: 2 - Engine Size/Type: 350 5.7 Liter - Engine In Front - Engine Problems: Failed Engine, Parts Missing, Bad Motor - Gas - Battery: Yes/Dead - Does Not Run - Automatic - Hydraulic Brakes - Inspection Sticker Date: 08/16 - Approx. Mileage Unable To Read - Interior Condition: Poor - Interior Problems: Door Panels Missing, Dash Missing, Seats Poor, Parts Missing - Body Condition: Poor - Body Problems: Peeling Paint, Oxidized Paint, Scratches, Missing Rear Door/Damaged, Parts Missing, Recommend Inspection - Tires Condition: Poor - Has Protection Cage, Shop Built Cabinets In Cargo Area</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
19	(1) 2000 Chevy Express 3500 Van Vin #6165 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 1852 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Not Running, Engine Problem Unknown - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 11/18 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Torn Drivers Seat, Worn Steering Wheel, Needs Cleaning, Shop Made Cabinets In Cargo Area, Damage On Door Panel Drivers Side - Body Condition: Fair - Body Problems: Peeling Paint All Over, Surface Scratches, Minor Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

20	(1) 1991Chevy 30 Van Vin #9714 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 1420 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Not Running, Problems Unknown - Gas - Battery: Yes - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 01/19 - Approx. Mileage Reads: 161,703**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Needs Cleaning, Worn, Some Surface Rust - Body Condition: Poor - Body Problems: Oxidized Paint, Chipped Paint, Surface Rust All Over - Rust On Roof - Tires Condition: Poor - Has Headache Rack</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
21	(1) 2001 Chevy Express 3500 Van Vin #6566 - Runs	<p>Unit #: 1864 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7 Liter - Engine In Front - Engie Problems: Unknown - Gas - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 11/18 - Approx. Mileage Reads: 69,848**Unknown Actual Mileage** - Interior Condition: Fair - Interior problems: Minor Tear On Drivers Seat, Needs Cleaning, Steering Wheel Worn - Body Condition: Fair - Body Problems: Surface Scratches, Oxidized Paint, Chipped Paint, Peeling On Roof Area, Peeling On Rear Door, Surface Rust On Roof, Dents On Front Bumper - Tires Condition: Fair To Poor - Tire Problems: Fair On Rear, Poor In Front</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
22	(1) 2001 Chevy 3500 Express Van Vin #8068 - Runs	<p>Unit #: 1860 - Conventional Style - Passengers: 2 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 09/18 - Approx. Mileage Reads: 99,633**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Upholstery Worn, Needs Cleaning - Body Condition: Fair - Body Problems: Peeling Paint All Over, Scratches, Surface Rust, some Dents, Peeling Paint On Rear Doors - Tires Condition: Fair To Poor - Tire Problems: Front Tires Poor, Rear Tires Fair - Has Protection Cage In Cargo Area, Has Headache Rack</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
23	(1) 1990 GMC Busette Van Vin #7702 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 52 - Conventional Style - Passengers: 22 - Engine Size/Type: 5.7 - Engine In Front - Gas - Battery: Yes - Does Not Run, Ran When Parked - Automatic - Hydraulic Brakes - Approx. Mileage Reads: 218,521**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Oxidized Paint, Seats Need Cleaning, Worn, Torn Seats, Glass On Floor - Body Condition: Fair - Body Problems: Some Rust, Oxidized Paint, Minor Dents & Scratches - Tires Condition: Good - Tire Problems: Need Air - Rear Suspension Issues, Electrical Issues</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

24	(1) 1994 Chevy Silverado Pickup Truck Vin #8729 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 1384 - Conventional Style - Passengers: 3 - Engine Size/Type: 5.0 - Engine In Front - Gas - Battery: Yes - Does Not Run - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Reads: 135,243 **Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Top Of Dash Heavily Damaged - Body Condition: Fair - Body problems: Rust, Surface Scratches, Oxidized Paint, Large Crack Drivers Side Window Front, Vehicle Possible Missing Parts, Peeling Paints</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
25	(1) 1999 Chevy LS 3500 Pickup Truck Vin #6645 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 1306 - Conventional Style - Passengers: 6 - Engine Size/Type: 8 Cylinder - Engine In Front - Engine Problems: Thrown Rod, Bad Engine - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Reads: 69,158**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning - Body Condition: Fair - Body Problems: Large Dent/Drivers Door, Minor Rust, Peeling Paint, Gash, Oxidized Paint, Minor Scratches - Tires Condition: Fair - Tire Problems: Needs Air</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
26	(1) 1996 Ford F150 XLT Pickup Truck Vin #1226 - Will Need To Be Towed	<p>Will Need to Be Towed - Unit #: 1388 - Conventional Style - Passengers: 3 - Engine Size/Type: 8 Cylinder - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/19 - Approx. Mileage Reads: 110,254**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Dash Has Cracks, Seats Torn - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches All Over, Peeling Paint, Rust On Bed, Dent Rear Passenger Panel, Scratches Dents All Over Bed, Bumper Dent, Drivers Side Rear Large Scratch & Dent - Tires Condition: Fair - Tire Problems: Need Air</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
27	(1) 2016 Ford Explorer SUV Vin #2797 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 4252 - Engine Size/Type: 3.7 - Gas - Passengers: 5 - Battery: Yes - Engine In Front - Engine Problems: Does Not Run - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Unknown - Interior Condition: Poor - Interior Problems: Interior Door Panels Missing, Air Bags Released, Missing Part Of Dash - Body Condition: Poor - Inspection Sticker Date: 07/18 - Body Problems: Wrecked Right Passenger Panel, Large Damage, Right Rear Light Has Been Removed - Tires Condition: Fair - Tire Problems: Need Air</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

28	(1) 2008 Cargo Trailer Vin #0498	<p>Approx. Size: 14' - Unit #: 3056 - Body Condition: Fair - Body Problems: Surface Scratches, Dents All Over - Axel Broken - Bottom Rusting - Approx. Size: 2 5/16" Ball</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
29	(1) 2001 International 4T Box Truck Vin #2766 - Will Need To Be Towed	<p>Will Need To Be Towed - 4700 Model - 4 X 2 - WB: 236 - Unit #: 1595 - Conventional Style - Passengers: 2 - Engine Size /Type: DTA 466E - Engine In Front - Engine Problems: Will Not Start, Possible Starter Or Electrical Issue, Unknown Problems - Diesel - Battery: (1) Only - GVWR: 14,969 lbs. - Does Not Run - Automatic Transmission - Air Brakes - Approx. Mileage Reads: 105,136**Unknown Actual Mileage** - Approx. Hours Read: 009383 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Normal Wear - Body Problems: Box Is Kold King XL Mfg. By Supreme Dual Wheel In Rear, Has Hydraulic Lift Gate/6000 lb. Corp. Capacity - (1) Fuel Tank, Dent On Front Bumper - Tires Condition: Good To Fair - Supreme Corp Box Bed Size: 24' W/ Lift</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
30	(1) 1995 International 4T Box Truck Vin #1602 - Will Need To Be Towed	<p>Will Need To Be Towed - Approx. Size: 24' - Unit #: 1576 - Conventional Style - Passengers: 2 - Engine Size/Type: DT466 - Engine In Front - Engine Problems: Problems Unknown, Will Not Run - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Approx. Hours Read: 015,247**Unknown Actual Hours** - Inspection Sticker Date: 01/18 - Approx. Mileage Reads: 184,113**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Normal Wear - Body Condition: Fair - Body Problems: Some Scratches, Oxidized Paint, Has Refer Condition Unknown, Hood Has Cuts & Damage On Fiberglass, Has A Lift Gate/Condition Unknown, Some Scratches On Box, (1) Rock Chip On Windshield - Tires Condition: Good To Fair - Has (1) Fuel Tank - Box Is A Kold King XL By Supreme Corp - Approx. Size: 24' Box W/ Lift</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
31	(1) 1992 Chevy Box Truck Vin #0319 - Will Need To Be Towed	<p>Will Need To Be Towed - Model: Kodiak - Unit #: 1570 - Conventional Style - Passengers: 2 - Engine Size/Type: 6.6 Liter Cat/Cat Diesel Power - Engine In Front - Engine Problems: Engine Problem Is Unknown/Not Running - Gas - Battery: Yes /Dead - Does Not Run - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 04/18 - Approx. Mileage Reads: 139,626**Unknown Actual Mileage** - Interior Condition: Fair To Poor - Has Hydraulic Lift Gate/Lift Works - Interior Problems: Seat Is Far, Dash Is Poor/Cracked, Needs Cleaning - Body Condition: Fair - Body Problems: (1) Fuel Tank, Needs Cleaning, Dual Wheel In Rear, Peeling Paint On Hood, Oxidized Paint, Some Scratches On Box, Supreme Corp Bed - Tires Condition: Good To Fair - Box Approx. Size: 23' W/ Lift</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

32	(1) 1995 International Box Truck Vin #: 1601 - Runs	<p>4700 4X2 - Unit #: 1577 - Conventional Style - Passengers: 2 - Engine Size/Type: DT466E - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: NA - Approx. Hours Read: 012,809 - Approx. Mileage Reads: 155,658**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Upholstery Worn, Seat Torn, Box W/ Lift - Body Condition: Fair - Body Problems: Bed: Kold King XL By Supreme Corp - Approx. 24' Box W/ Lift, Oxidized Paint, Surface Scratches, (1) Fuel Tank, Has Refer /Condition Unknown, Dual Wheel In Rear - Has Hydraulic Lift Gate/Condition Unknown</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
33	(1) 2000 International Dump Truck Vin #0664 - Will Need To Be towed	<p>Will Need To Be Towed - Model: 4700 4X2 - WB: 152 - Unit #: 1588 - Conventional Style - Passengers: 2 - Engine Size /Type: 6 Cylinder - Engine In Front - Engine Problems: Unknown Problem/Does Not Run - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 11/18 - Approx. Hours Reads: 008,686 - Approx. Mileage Reads: 135,087**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Okay, Needs Cleaning, Worn Upholstery - Body Problems: Weight: Approx. 33,000 - Rock Chip On Windshield, Scratches, Oxidized Paint, Surface Rust On Front Bumper, Peeling Paint, Rock Chip On Windshield - Tires Condition: Good - Dump Bed: McClain - Model: 4020 - Capacity: 6.4-7.7</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>