

Lot Number	Title	Description
0	Preview & Removal Information	<p>* There Will Be A 13% Buyer's Premium Added To The Buyer's Total For Each Item Purchased. There Will Be A 3% Convenience Fee On All Credit Card Purchases*</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Monday, Monday, July 8, 2019 (Hours Of Operation: 7:30 a. m. - 3:00 p.m.)</p> <p>Location: Medina ISD, 1 Bobcat Lane, Medina, Tx 78055 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Thursday, July 11, 2019/Monday, July 15, 2019/Tuesday, July 16, 2019 (Hours Of Operation: 7:30 a.m. - 3:00 p.m.)</p> <p>Preview & Removal Contact: Pam Keese, (830)589-2855</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed. Buyer Solely Responsible For Removal, No Assistance Provided</p>
1	(1) 1992 International School Bus Vin #0765 - Runs	<p>Bus #: 3 - Passengers: 47-70 - Engine Type: Intl - Diesel - Battery: Yes - Engine In Front - Engine Problems: Oil Leaks - Runs - Transmission Type: Allison - Air Brakes - Automatic - Approx. Mileage Reads: 246,344**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Drivers Seat In Poor Condition, Seat Repairs Needed, Floor Rotted - Body Condition: Fair - Inspection Sticker Date: 06/19 - Body Problems: Needs Roof Vents, Roof Leaks, Scratches/Dents - Tires Condition: Fair</p> <p>- Current Condition Fair</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
2	(1) 1995 International School Bus Vin #3954 - Runs	<p>Bus #: 7 - Passengers: 49-74 - Engine Size/Type: Int DT 466 - Diesel - Battery: Yes - Engine In Front - Oil Leaks - Runs - Transmission Type: Allison - Air Brakes - Automatic - Approx. Mileage Reads: 144,033**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Floor Rotted, Seats Ned Repair - Body Condition: Fair - Inspection Sticker Date: 06/19 - Body Problems: Roof Vents Need Replaced, Several Windows Inoperable, Dents/Scratches - Tires Condition: Fair</p> <p>- Current Condition Fair</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
3	(1) 1997 International School Bus Vin #4865 - Runs	<p>Bus #: 6 - Passengers: 27-54 - Engine Size/Type: Intl DT 466E - Diesel - Battery: Yes - Engine In Front - Engine Problems: Oil Leaks - Runs - Transmission Type: Allison - Air Brakes - Automatic - Approx. Mileage Reads: 48,889**Unknown Actual Mileage** - Interior Problems: Some Seat Repairs Needed, Floor Repair Required - Body Condition: Fair - Inspection Sticker Date: 06/19 - Body Problems: Several Dents/Scratches, Roof Leaks - Tires Condition: Fair</p> <p>- Current Condition Fair</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
4	(1) 1994 International School Bus Vin #0087 - Runs	<p>Bus #: 4 - Passengers: 14-21 - Engine Size/Type: Int DTA360 - Diesel - Battery: Yes - Engine In Front - Engine Problems: Excessive Oil Leaks - Runs - Transmission Type: Allison - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 182,144**Unknown Actual Mileage** - Interior Condition: Poor - Wheel Chair Lift, Condition Unknown - Interior Problems: Needs Floor Replaced, Wheel Chair Area Unusable - Body Condition: Fair - Inspection Sticker Date: 06/19 - Body Problems: Scratches/Dents - Tires Condition: Fair - Needs Steering Box</p> <p>- Current Condition Fair</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

5	(1) 1995 Ford E37 School Bus Vin #8756 - Will Possibly Need To Be Towed	Will Possibly Need To Be Towed - Bus #: 10 - Passengers: 9-15 - Engine Size/Type: 7.3L - Diesel - Battery: Yes - Engine In Front - Engine Problems: Runs Good, Need Alternator - Runs - Transmission Type: Ford - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 94,337**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seat Repairs Required, Floor In Good Shape - Body Condition: Poor - Inspection Sticker Date: 2017 - Body Problems: Collision Damage To Passenger Loading Door/Inoperable, Paint In Fair Condition - Tires Condition: Fair - Bus Has Been Parked For Approx. 2 Years - Lighting & Warning System Problems - Current Condition Fair There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**
6	(1) Craftsman Lathe	115 Volts - 60 Hz - 1/2 HP - Needs Repair - Current Condition Poor
7	(1) Proimage /Varitronics Poster Maker	Electric - 120 Volts - 60 Hz - 3.2 Amps - Needs Repair - Includes All Accessories & (2) Rolls Of Power Paper - Current Condition Fair
8	(1) Metal Desk W/ Return	 - Current Condition Fair
9	(Lot) Metal Desks	(Approx. 2) - Current Condition Fair
10	(1) Band Saw	Mfg: Delta - Needs Repair - Current Condition Fair
11	(1) Matador Floor Buffer	Needs Cleaning & Maintenance, But Runs - Current Condition Fair
12	(1) Rockwell Unisaw Table Saw	Needs Cleaning & Maintenance But Runs - Current Condition Fair
13	(1) Paragon Kiln	Model: DTC 100C - Working Condition Unknown - Current Condition Fair
14	(Lot) Chairs	(Approx. 3) Needs Cleaning - Current Condition Fair
15	(Lot) Computer Tables	(Approx. 15) - Current Condition Fair
16	(1) Rockwell Stand Grinder	Needs Repair - Current Condition Unknown
17	(1) Viore 46" TV	Includes Mounting Bracket - Current Condition Fair
18	(1) Insignia 46" TV	Includes Mounting Bracket - Current Condition Fair
19	(1) Water Worker Pressure Tank	Model: HT86B - 75 PSI - 100 PSI Maximum - Current Condition Fair
20	(1) Wheel Chair	Rolls Easily - Needs New Cushions - Current Condition Fair
21	(1) Desk	 - Current Condition Fair

22	(1) Metal Desk	- Current Condition Fair
23	(1) Metal Desk	- Current Condition Fair
24	(1) Bernina Sewing Machine	Model: 1001 - Includes Cabinet - Current Condition Fair
25	(1) Bernina Sewing Machine	Model: 1008 - Includes Cabinet - Current Condition Fair
26	(1) Bernina Sewing Machine	Model: 1001 - Includes Cabinet - Current Condition Fair
27	(1) Bowman School Series Sewing Machine	Model: Pro Line - Includes Cabinet - New - Current Condition Good
28	(Lot) Roll Towel Dispensers	(Approx. 4) - Current Condition Fair
29	(1) Rifton Adaptative Stander	Rolls Easily - Needs Cleaning - Current Condition Fair
30	(Lot) Cleaning Solution Dispensers	(Approx. 5) Mfg: Diversey Quattro - Current Condition Fair
31	(1) Industrial Air Air Compressor	Needs Repair - Current Condition Poor
32	(Lot) Metal Clad Doors	(Approx. 2) Model: 36" X 83 1/4" - Current Condition Fair
33	(1) Rigid Kollman Drain Opener	Needs Repair - Current Condition Poor
34	(1) Metal Cabinet	Doors Work Properly - Some Rust & Dents - Current Condition Fair
35	(1) Metal File Cabinet	- Current Condition Fair
36	(1) Metal File Cabinet	- Current Condition Fair
37	(1) Table	Approx. Size: 30" X 72" - Current Condition Fair
38	(1) Vintage Turntable	Mfg: Audiotronics - Model: 400 - Current Condition Unknown
39	(1) Apple Vintage Computer	- Current Condition Unknown Buyer Must Preview This Lot-We Do Not Know The Current Condition - We Are Selling This Lot As Is (Parts Missing), This Could Mean Hard Drives, Memory, Etc. Medina ISD And Lemons Auctioneers Are Not Responsible For Current Condition, It Is The Buyers Responsibility To Preview - No Refunds - No Exceptions.
40	(Lot) Cubicle Components	(Approx. 2) Makes (2) Cubicles W/ Desks & Filing Cabinets - Current Condition Fair

41	(Lot) Student Desks & Chairs	(Approx. 11) Needs Cleaning - Including: (Approx. 6) Chairs, (Approx. 5) Desks - Current Condition Fair
42	(1) Shelf Unit	- Current Condition Fair
43	(1) John Deere Vintage Mower	Needs Repair - Current Condition Poor
44	(1) Remcor Sprayer W/ Trailer	Sprayer Motor Needs Repair - Current Condition Poor
45	(1) DR Yard Grass/Leaf Vacuum W/ Trailer	Needs Repair - Current Condition Poor
46	(1) Metal Desk	- Current Condition Fair
47	(1) Metal Desk	- Current Condition Fair
48	(1) 72" Commercial Mower	Mfg: John Deere - Model: 1435 - Diesel - Runs - Headliner Needs Replaced - Current Condition Fair
49	(1) 46" TV	Mfg: Westinghouse - Works - Current Condition Fair
50	(1) Portable Room Air Conditioner	Mfg: Amana - AP077R - Electric - 115 Volts - 60 Hz - 8 Amps - Air Conditioner Works - Current Condition Unknown