

Lot Number	Title	Description
0	Preview & Removal Information	<p>**All purchases at will be subject to a 13% buyer's premium.**</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Monday, July 8, 2019 (Hours Of Operation: 8:00 a.m. - 1:00 p.m.)</p> <p>Location: Pridgeon Stadium, 11355 Falcon Rd. A, Houston, Tx 77065 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Thursday, July 11, 2019/Friday, July 12, 2019/Monday, July 15, 2019/Tuesday, July 16, 2019/Wednesday, July 17, 2019 (Hours of Operation: 8:00 a.m. - 1:00 p.m.)</p> <p>Removal Contact: Kristi Giron, 281-517-6367</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed No Cash Payments Accepted On Site</p>
1	(1) 2001 International 24' Box Truck /4700 Vin #2768 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 1596 - Conventional Style - Passengers: 3 - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes - Runs - Has (1) Fuel Tank - Automatic - Air Brakes - Inspection Sticker Date: 03/19 - Approx. Mileage Reads: 91,166**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Torn Seats, Needs Cleaning, Normal Wear - Body Condition: Fair - Body Problems: Oxidized Paint, Minor Scratches, Damage On Hood, Rust On Front Bumper - Tires Condition: Good - Waltco Liftgate, Has Thermoing KD-II SR/Not Working - Has a Supreme Box Bed</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
2	(1) 1997 International 24' Box Truck /4700 Vin #4762 - Runs	<p>Unit#: 1581 - Conventional Style - Passengers: 3 - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes - Runs - Automatic - Air Brakes - Inspection Sticker Date: 03/19 - Approx. Mileage Reads: 168,514**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Normal Wear, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches - Tires Condition: Good - Has A Kold King X4 Refrigerator/Not Working - Has Supreme Box - Has (1) Fuel Tank - Has A Maxon Lift Gate</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
3	(1) 2001 International Bluebird School Bus Vin #0199 - Runs	<p>Bus #: 887 - Conventional Style - Passengers: 3 - Engine In Front - Engine Problems: Engine Worn - Diesel - Battery: Yes - Runs - Automatic - Air Brakes - Inspection Sticker Date: 02/19 - Approx. Mileage Reads: 151,944**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Tears On Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Large Dent/Scratch On Right Rear, Broken Reflector Right Rear - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

4	(1) 2000 International Bluebird 3800 Handy School Bus Vin #4337 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 0830 - Conventional style - Passengers: 16 Passengers & (2) Wheel Chair Spaces - Engine Problems: Not Running/Parts Missing - Diesel - Battery: No - Does Not Run - Automatic - Air Brakes - Inspection Sticker Date: 02/19 - Approx. Mileage Reads: 162,539**Unknown Actual Mileage** - Interior Condition: Fair - Wheel Chair Lift, Condition Working - Interior Problems: Missing (2) Roof Escape Doors/Hatches, Missing Covers Off A/C, Missing Parts, Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rock Chip On Windshield, Peeling On Hood & Cowl - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
5	(1) 1998 International Thomas 3800 School Bus Vin #4123 - Runs	<p>Bus #: 713 - Conventional Style - Passengers: 24 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes - Runs - Automatic - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Reads: 136,979**Unknown Actual Mileage** - Approx. Hub Reads: 137,901 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Torn Drivers Seat, Soft Spot In Middle Of Isle Inside Bus, Seats Are Worn - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Peeling On Cowl, Rock Chip On Windshield - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
6	(1) 2000 International Bluebird Handy School Bus Vin #4334 - Runs	<p>Bus #: 829 - Conventional Style - Passengers: 16 Passengers W/ (2) Wheel Chair Spaces - Engine Size/Type: DT446E - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes - Runs - Automatic - Air Brakes - Inspection Sticker Date: 03/19 - Approx. Mileage Reads: 145,697**Unknown Actual Mileage** - Approx. Hub Reads: 146,477 - Wheel Chair Lift, Condition: Unknown - Interior Condition: Fair - Interior Problems: Tears On Seats, Normal Wear - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Long Scratch On Right Rear On Handy Door, Wear On Paint On Cowl & Hood, Some Peeling On Hood - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
7	(1) 2001 International Bluebird 3800 School Bus Vin #0193 - Runs	<p>Bus #: 879 - Conventional Style - Passengers: 36 - Engine Size/Type: DT466E - Engine In Front - Engine Problems: Water In Oil - Diesel - Battery: Yes - Runs - Automatic - Air Brakes - Inspection Sticker Date: 11/19 - Approx. Mileage Reads: 137,000**Unknown Actual Mileage** - Approx. Hub Reads: 138,281 - Interior Condition: Fair - Interior Problems: Normal Wear, Some Tears On Seats/Minor - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rock Chip On Windshield - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

8	(1) 2001 International Bluebird 3800 Handy Bus vin #0185 - Runs	<p>Bus #: 895 - Conventional Style - Passengers: 16 Passengers & 2 Wheel Chair Spaces - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes - Runs - Automatic - Air Brakes - Inspection Sticker Date: 05/19 - Approx. Mileage Reads: 187,747**Unknown Actual Mileage** - Approx. Hub: 189,216 - Wheel Chair Lift, Condition Unknown - Interior Condition: Fair - Interior Problems: Some Torn Seats, Normal Wear, Needs Minor Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
9	(1) 2000 International Bluebird 3800 Handy School Bus Vin #4330 - Runs	<p>Bus #: 828 - Conventional Style - Passengers: 16 W/ (2) Wheel Chair Spaces - Engine Size/Type: DT466E - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes - Runs - Automatic - Air Brakes - Inspection Sticker Date: 05 /19 - Approx. Mileage Reads: 203,678**Unknown Actual Mileage** - Approx. Hub Reads: 203,653 - Wheel Chair Lift, Condition Unknown - Interior Condition: Fair - Interior Problems: Normal Wear, Minor Tears, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Long Rub On Right Lower Panel Behind Rear Wheel Well, Peeling On Cowl & Hood, Rock Chip On Windshield - Tires Condition: Fair In Front, Good In Rear</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
10	(1) 2000 International Bluebird Handy School Bus Vin #4335 - Runs	<p>Bus #: 832 - Conventional Style - Passengers: 16 W/ (2) Wheel Chair Spaces - Engine Size/Type: DT466 - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes - Runs - Automatic - Air Brakes - Approx. Mileage Reads: 153,629 **Unknown Actual Mileage** - Approx. Hub Reads: 155,655 - Wheel Chair Lift, Condition Unknown - Interior Condition: Fair - Interior Problems: Minor Torn Seats, Normal Wear - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rock Chip On Windshield, Peeling On Cowl & Hood - Tires Condition: Good To Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
11	(1) 2000 International 3800 Bluebird Handy School Bus Vin #5536 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 777 - Passengers: 16 W/ (2) Wheel Chair Spaces - Engine Size /Type: DT466 - Engine In Front - Engine Problems: Bad Engine - Diesel - Battery: No - Does Not Run - Automatic - Air Brakes - Inspection Sticker Date: 03/18 - Approx.. Mileage Reads: 181,163**Unknown Actual Mileage** - Approx. Hub Not Readable - Wheel Chair Lift, Condition Unknown - Interior Condition: Poor - Interior Problems: Torn Seats, Needs Cleaning, Normal Wear - Body Condition: Fair - Body Problems: (1) Broken Passenger Window, Oxidized Paint, Surface Scratches, Rear Door Needs Replacing/Adhered By Tape - No Hinges - No Glass, Peeling On Cowl - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

12	(1) 2000 International Bluebird 3800 School Bus Vin #5491 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 762 - Passengers: 71 - Engine Size/Type: DT466E - Engine Problems: Unknown, Will Not Run, Possible Engine Problems - Diesel - Battery: No - Does Not Run - Automatic - Air Brakes - Approx. Mileage Reads: 147,449**Unknown Actual Mileage** - Approx. Hub Reads: 152,097 - Interior Problems: Some Torn Seats, Normal Wear, Entry Door Panel Off/Needs Repair - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches - Tires Condition: Fair In Front/Good In Rear</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
13	(1) 2000 International Thomas 4700 School Bus Vin #0150 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 796 - Passengers: 71 - Engine Size/Type: DT466E - Engine In Front - Engine Problems: Not Running, Will Not Run, Possible Engine Problems - Diesel - Battery: No - Does Not Run - Automatic - Ari Brakes - Approx. Mileage Reads: 140,350**Unknown Actual Mileage** - Approx. Hub Reads: 142,771 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Some Torn Seats, Normal Wear - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rock Chip On Windshield, Peeling Cowl, Missing (1) Front Mirror - Tires Condition: Good In Rear/Fair In Front</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
14	(1) 2000 International Thomas 3800 School Bus Vin #0162 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 793 - Passengers: 71 - Engine Size/Type: DT466E - Engine In Front - Engine Problems: Unknown, Will Not Run, Possible Engine Problem - Diesel - Battery: No - Does Not Run - Automatic - Air Brakes - Inspection Sticker Date: 05/17 - Approx.. Mileage Reads: 160,261**Unknown Actual Mileage** - Approx. Hub Reads: 167,309 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Some Torn Seats, Floor Soft At Entry & Various Other Locations Inside Bus - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, (1) Broken Passenger Window, Peeling On Cowl & Hood, Missing (1) Front Mirror - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
15	(1) 2000 International Bluebird 3800 School Bus Vin #5509 - Will Need To Be Towed	<p>Will Need To Be Towed- Conventional Style - Bus #: 760 - Passengers: 71 - Engine Size/Type: DT466E - Engine In Front - Engine Problems: Not Running, Problem Unknown, Possible Engine Problem - Diesel - Battery: No - Does Not Run - Automatic - Air Brakes - Inspection Sticker Date: 10/17 - Approx. Mileage Reads: 179,207**Unknown Actual Mileage** - Approx. Hub Reads: 163,688 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Torn Seats, Normal Wear, Parts Missing Off A/C Units/Entry Door Control - Body Condition: Fair - Body Problems: (1) Passenger Entry Door Removed, Oxidized Paint, Surface Scratches, Rock Chip On Windshield - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

16	(1) 2000 International Bluebird 3800 Handy School Bus Vin #4331 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 825 - Passengers: 16 W/ (2) Wheel Chair Spaces - Engine Size /Type: DT466 - Engine In Front - Engine Problems: Unknown, Will Not Run, Possible Engine Problems - Diesel - Battery: No - Does Not Run - Automatic - Air Brakes - Inspection Sticker Date: 04/17 - Approx. Mileage Unknown/Dash Removed /No Speedometer - Approx. Hub Reads: 149,443 - Wheel Chair Lift, Condition Unknown - Interior Condition: Fair - Interior Problems: Normal Wear, Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Bus Needs Cleaning, Peeling On Cowl - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
17	(1) 1997 International Bluebird 3800 School Bus Vin #9777 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 663 - Passengers: 71 - Engine Size/Type: 3800/DT466E - Engine In Front - Engine Problems: Bad Engine, Engine Knocking - Diesel - Battery: Yes/Dead - Will Start, Does Not Run - Automatic - Air Brakes - Approx. Mileage Reads: 143,342**Unknown Actual Mileage** - Approx. Hub Reads: 160,499 - Interior Condition: Fair - Interior Problems: Some Torn Seats, Worn Seats, Needs Cleaning, Dash Is Loose & Possible Parts Missing - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rub On Right Side Rear Bumper, Broken Front Windshield, Peeling Cowl & Hood - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
18	(1) 1998 International Bluebird 3800 School Bus Vin #1500 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 675 - Passengers: 71 - Engine Size/Type: DT66E - Engine In Front - Engine Problems: Will Not Run, Unknown Problems, Possible Bad Engine - Diesel - Battery: Yes- Does Not Run - Automatic - Transmission Type: Allison - Air Brakes - Approx. Mileage Reads: 163,310**Unknown Actual Mileage** - Approx. Hub Reads: 133,038 - Interior Condition: Fair - Interior Problems: Torn Seats, Needs Cleaning, Worn Interior, Missing (1) Roof Hatch - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Peeling On Cowl & Hood - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
19	(1) 1998 International Bluebird 3800 School Bus Vin #1485 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 685 - Passengers: 71 - Engine Size/Type: DT466E - Engine In Front - Engine Problems: Broken Fly Wheel, Will Need To Be Towed, Will Start - Diesel - Battery: Yes - Runs - Automatic - Air Brakes - Inspection Sticker Date: 04/20 - Approx. Mileage Reads: 174,460**Unknown Actual Mileage** - Approx. Hub Reads: 183,577 - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning, Normal Wear - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Peeling On Hood - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

20	(1) 2002 International IC Amtran School Bus Vin #6855 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 852 - Passengers: 71 - Engine Size/Type: DT466E - Engine In Front - Engine Problems: Unknown, Will Not Run - Diesel - Battery: Yes/Dead - Does Not Run - Automatic - Allison Transmission - Air Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Reads: 168,556**Unknown Actual Mileage** - Approx. Hub Reads: 146,466 - Interior Condition: Fair - Interior Problems: Some Torn Seats, Normal Wear - Body Condition: Fair - Body Problems: Surface Scratches, Missing (1) Mirror In Front, Oxidized Paint - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
21	(1) 2002 International IC Amtran School Bus Vin #6865 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 841 - Passengers: 71 - Engine Size/Type: DT466E - Engine In Front - Engie Problems: Will Not Run, Problem Unknown - Diesel - Battery: Yes/Dead - Does Not Run - Automatic - Allison Transmission - Air Brakes - Inspection Sticker Date: 08/18 - Approx. Mileage Reads: 131,180**Unknown Actual Mileage** - Approx. Hub Reads: 163,197 - Interior Condition: Fair - Interior Problems: Some Tron Seats, Needs Cleaning, Worn, Future floor Issues On Isle Inside Bus - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rub On Left Side Rub Rail - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
22	(1) 1998 IHC 3800 Bluebird School Bus Vin #1467 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 676 - Passengers: 71 - Engine Size/Type: DT466E - Engine In Front - Engine Problems: Will Not Run, Problem Unknown - Diesel - Battery: No - Does Not Run - Automatic - Air Brakes - Inspection Sticker Date: 02/20 - Approx. Mileage Reads: 135,348**Unknown Actual Mileage** - Approx. Hub Reads: 137,485 - Interior Condition: Fair - Interior Problems: Missing Several Passenger Seats In Rear, Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rock Chip On Windshield, Peeling On Cowl & Hood- Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
23	(1) 1997 International 3800 Bluebird School Bus Vin #9795 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 661 - Passengers: 71 - Engine Size/Type: DT466E - Engine In Front - Engine Problems: Will Not Run, Unknown Problem - Diesel - Battery: No - Does Not Run - Automatic - Air Brakes - Inspection Sticker Date: 08/19 - Approx. Mileage Reads: 17,286**Unknown Actual Mileage** - Approx. Hub Reads: 164,825 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Some Torn Seats, Upholstery Worn, Missing Several Passenger Seats In Rear - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rear Entry Door Glass Broken/Door Is Damaged, Peeling On Cowl & Hood, Rock Chip On Hood - Tires Condition: Fair - Both Front Mirrors Are Missing</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

24	(1) 2002 International 3800 School Bus Vin #6847 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 860 - Passengers: 71 - Engine Size/Type: 466 - Engine Size/Type: 466 - Engine In Front - Engine Problems: Will Not Run, Unknown Problem - Diesel - Battery: No - Does Not Run - Automatic - Air Brakes - Inspection Sticker Date: 02/19 - Approx. Mileage Reads: 158,889**Unknown Actual Mileage** - Approx. Hub Reads: 184,095 - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Surface Scratches, Oxidized Paint, Rock chip On Windshield, Slight Damage On Front Grill - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
25	(1) 2013 4 Door Ford Explorer Vin #0584 - Will Need To Be Towed /Wrecked	<p>Will Need To Be Towed - Wrecked - Unit #: 4219 - Conventional Style - Passengers: 4 Door - Engine Size/Type: 3.7 Liter - Engine In Front - Engine Problems: Unknown Damage, Front Wrecked - Gas - Battery: Yes/Dead - Does Not Run - Automatic - Transmission Condition Unknown Due To Wreck - Hydraulic Brakes - Inspection Sticker Date: 12/19 - Approx. Mileage Estimate: 35,000**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Loose Parts Inside Unit - Body Condition: Poor - Body Problems: Wrecked In Front, Wreck On Right Door Also, Drivers Side Window Broken/Missing - Tires Condition: Fair - Front Impact Accident - Auctioneer Recommends Preview</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>