

Lot Number	Title	Description
0	Preview & Removal Information	<p>All purchases will be subject to a 13% buyer's premium.</p> <p><b>Preview:</b> (By Appointment Only-Mandatory-No Exceptions) Thursday, August 15, 2019 (Hours Of Operation: 7:30 a.m. - 2:00 p.m.)</p> <p><b>Location:</b> 14703 FM 2100, Crosby, Tx 77532 <a href="#">Driving Directions</a></p> <p><b>Removal:</b> (By Appointment Only-Mandatory-No Exceptions) Wednesday, August 21, 2019/Thursday, August 22, 2019 /Friday, August 23, 2019 (Hours Of Operation: 7:30 a.m. - 2:30 p.m.)</p> <p><b>Preview &amp; Removal Contacts:</b> Lisa Wiginton, (281)328-9247, James Thomas, (832)894-0354, or Brian Weisinger, (281)384-4001</p> <p><b>Buyer Solely Responsible For Removal. No Assistance Will Be Provided. Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</b></p>
1	(1) 1987 Ford F600 Box Truck Vin #3358 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 202 - Passengers: 3 - Engine Size/Type: 370/4V - Gas - Battery: No - Engine In Front - Engine Problems: Ran When parked, Current condition Unknown - Unknown If Running - Hydraulic Brakes/No Brakes - Standard - Approx. Mileage Reads: 035,431**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Needs Cleaning, Worn Upholstery, Worn Door Panels, Damage/Hole On Dash, Hole/Rust On Inside From Roof Leak - Body Condition: Poor - Approx. Hub Reads: 001,046 - Inspection Sticker Date: 08/16 - Body Problems: Oxidized Paint, Rust On Roof/Hole On Roof, Rear Door Damaged &amp; Needs Repair Or Replacing, Rust On Hood, General Truck Body Mfg. Co., Has Scratches, Dents, Has 1 Fuel Tank - Tires Condition: Fair - Tire Problems: Unit Has Been Sitting Up Several Years, Recommend Check For Dry Rot</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
2	(1) 1994 Chevy 3500 Crew Cab Pickup Truck Vin #8027 - Will Possibly Need To Be Towed	<p>Will Possible Need To Be Towed - Unit #: 502 - Passengers: 6 - Engine Size/Type: 6.5L/Turbo Power - Diesel - Battery: No - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Engine In Front - Engine Problems: Ran When Parked, Has A New Clutch, Current Condition Unknown - Ran When Parked - Hydraulic Brakes - Standard Transmission - Approx. Mileage Reads: 132,683**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seat, Needs Cleaning, Cracks On Dash, Parts Broken /Missing On Floor Panels, Clutch Foot Pad Rubber Is Deteriorated, Visors Need Replacing - Body Condition: Fair - Inspection Sticker Date: 03/20 - Body Problems: Oxidized Paint, Surface Scratches, Cracks On Windshield, Minor Dents, Headlight Needs Replacing On Right Side - Tires Condition: Fair - Tire Problems: Flat Tire Right Rear</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
3	(1) 2005 Thomas School Bus Vin #5057 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 53 - Passengers: 71 - Engine Size/Type: C7 Acert/CAT - Diesel - Battery: Non - Engine Problems: Bad Motor, Ran When Parked, Will Lock Up - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Unable To Read/Dead Battery/No Battery - Interior Condition: Fair - Interior Problems: Minor Tears On Seats, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 08/19 - Body Problems: Oxidized Paint, Surface Scratches, Scratch On Right Rear, Headlights Missing Trim That Goes Around Lights - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

4	(1) 1998 International 3800 Bluebird School Bus Vin #1710 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 32 - Passengers: 71 - Engine Size/Type: T444E - Diesel - Battery: No - Engine In Front - Engine Problems: Fuel Problem, Will Not Run - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 264,330**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Minor Torn Seats, Needs Cleaning, Normal Wear - Body Condition: Fair - Inspection Sticker Date: 08/19 - Body Problems: Oxidized Paint, Minor Surface Scratches, Dent On Right Rear, (1) Light Rear Needs Replacing, Peeling On Hood &amp; Cowl - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
5	(1) 1993 International Navistar School Bus Vin #7545 - Runs	<p>Bus #: 7 - Conventional Style - Passengers: 7 - Engine Size/Type: DTA 36 - Diesel - Battery: No - Engine In Front - Engine Problems: Unknown - Runs - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 233,679**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Tears On Seat, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 08/19 - Body Problems: Oxidized Paint, Dent On Left Lower Panel Under Window 5&amp;6, Some Dents &amp; Scratches, Peeling On Cowl, Notable Surface Rust On Roof, Scratches On Roof - Tires Condition: Fair To Poor - Tire Problems: (1) Questionable Condition On Right Rear - Rub Guards Paint Is Rubbed Off All Over Bus &amp; Peeling</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
6	(1) 1994 Ford F250 XL Pickup Truck Vin #8728 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 201 - Passengers: 3 - Engine Size/Type: 5.8L - Gas - Battery: No - Engine In Front - Engine Problems: No Battery, Not Running, Bad Timing Belt - Does Not Run - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Unknown/No Battery/Unable To Read - Interior Condition: Fair - Interior Problems: Needs Cleaning, Normal Wear, Minor Cracks On Dash - Body Condition: Fair - Inspection Sticker Date: 08/18 - Body Problems: Minor Surface Rust, Oxidized Paint, Surface Scratches, Dent On Rear Bumper, Crack On Windshield, Small Crack On Dash/Near Windshield - Tires Condition: Fair - Dual Fuel Tanks/Both Operable Condition Unknown/Has Kobal Tool Box</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
7	(1) 2002 Thomas Freightliner School Bus Vin #1782 - Will Need To Be Towed	<p>Will Need To Be Towed - Recommend Salvage - Conventional Style - Bus #: 38 - Engine Size/Type: Hood Loose On Unit /Unable To View Engine - Passengers: 47 Passengers Size/30 Passengers &amp; (2) Wheel Chair - Diesel- Battery: No - Engine In Front - Engine Problems: Not Running/Parts Missing - Does Not Run - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Unable To Read/Dash Removed/Missing - Interior Condition: Fair - Wheel Chair Lift, Condition Unknown - Interior Problems: Panels Loose On Dash/Parts Missing, Some Torn Seats - Body Condition: Fair - Inspection Sticker Date: 08/18 - Body Problems: Oxidized Paint, Surface Scratches, Rub Rail Scratches On Left Rear, Surface Rust On Roof, Parts Missing, Missing Front Bumper, (1) Light Cover Missing On Front - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

8	(1) 1996 Ford Amtran Series School Bus Vin #1127 - Runs	<p>Bus #: 16 - Conventional Style - Passengers: 71 - Engine Size/Type: Unknown - Engine In Front - Engine Problems: Ran When Parked - Diesel - Battery No - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed - Automatic Transmission - Ran When Parked - Air Brakes - Inspection Sticker Date: 08/17 - Approx. Mileage Reads: 248,034**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning, Some Worn Seats - Body Condition: Fair - Body Problems: Oxidized Paint, Some Surface Rust On Roof, Surface Rust On Rub Guard, Needs Cleaning - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
9	(1) 1995 International Wayne 3800 School Bus Vin #8513 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 70 - Passengers: 71 - Diesel - Engine Size/Type: T444E - No Battery - Engine In Front - Engine Problems: Not Running/Fuel Problem - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 198,791**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Seat Repairs In Seats Due To Tears - Body Condition: Fair - Inspection Sticker Date: 09/19 - Body Problems: Some Rust, Peeling Paint, Crack In Back Right Passenger Window, Oxidization, Scratches, Some Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
10	(1) 1995 International Navistar 3800 School Bus Vin #8515 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 13 - Passengers: 71 - Engine Size/Type: T444E - No Battery - Engine In Front - Engine Problems: Not Running/Fuel Issues - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 195,820**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Tear/Damage/Repairs On Seats - Body Condition: Fair - Inspection Sticker Date: 09/19 - Body Problems: Rust On Roof, Dents, Peeling Paint, Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
11	(1) 1993 International AmTran SS-31 School Bus Vin #7546 - Runs	<p>Conventional Style - Bus #: 8 - Passengers 71 - Engine Size/Type: DTA360 - Diesel - Battery: No - Engine In Front - Runs - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 231,329**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Tears In Seats, Rust, Bad Spots On Middle Flooring - Body Condition: Poor - Inspection Sticker Date: 08/19 - Body Problems: Oxidizing Paint, Peeling Paint, Rust On Body, Cracks, Fading, Major Rust On Roof, Repairs On Body - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

12	(1) 1999 International Bluebird 3800 School Bus Vin #6193 - Runs	<p>Conventional Style - Bus #: 30 - Passengers: 71 - Engine Size/Type: T444E - Diesel - Battery: No - Engine In Front - Runs - Air Brakes - Automatic Transmission - Approx. Mileage Reads: 60,281**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Tears In Seats, Seat Repair, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 08/19 - Body Problems: Peeling Paint, Fading, Oxidization, Rust, Scratches, Some Rust, Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
13	(1) 2005 Freightliner Business Chassis M2 Box Truck Vin #5627 - Will Possible Need To Be Towed	<p>Will Possibly Need To Be Towed -Unit #: 207 - Passenger: 3 - Engine Size/Type: CAT C7 Acert - Diesel - Battery: No - Engine In Front - Engine Problems: No Batteries, Ran When Parked, Needs General Engine Maintenance/Fuel Filter Replaced, Etc. - Ran When Parked - Unknown If Running - Air Brakes - Automatic Transmission - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Normal Wear - Body Problems: Side Panels Are Loose On Box &amp; Need Replacing - Tires Condition: Fair - Box: Morgan/Sides On Box Will Need Repair/Has Lift Gate - Worked When Parked</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
14	(1) 1997 Ford Econoline 150 Cargo Van Vin #2815 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 602 - Passengers: 2 - Engine Size/Type: 4.2L - Gas - Battery: No - Engine Problems: Ran When Parked/Current Condition Unknown - Unknown If Running - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 198,941**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Needs Cleaning, Has Been Sitting Up For Awhile - Body Condition: Poor - Inspection Sticker Date: 09/15 - Body Problems: Oxidized Paint, Needs Cleaning, Surface Rust On Roof &amp; All Over, Drivers Side Door Is Damaged &amp; Hard To Open, Damage On Left Rear Panel, Long Scratch/Rust On Right Rear, Dent/Scratch On Front Right Panel, Missing Lock On Door On Passenger: Side - Tires Condition: Fair To Poor - Tire Problems: Rear Tires Poor/Possible Dry Rot</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
15	(1) 2000 Chevrolet Silverado 1500 Vin #2919 - Runs	<p>Unit #: 428 - Passengers: 3 - Engine Size/Type: 4.8L - Gas - Battery: Yes - Engine In Front - Runs - Transmission Condition: Fair - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Reads: 122,185**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Cracks On Dash, Ceiling Liner Peeling On Sides, Glover Compartment Broken, Needs Cleaning - Body Condition: Poor - Inspection Sticker Date: 03/20 - Body Problems: Peeling Paint, Scratches, Dents, Missing Chevy Emblem In Front, Some Rust - Tires Condition: Fair - VWS Tool Truck Bed In Bed Of Truck</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

16	(1) 2000 Chevy Silverado 1500 Vin #429 - Runs	<p>Unit #: 429 - Passengers: 3 - Engine Size/Type: 4.8L - Gas - Battery: Yes/Dead - Engine In Front - Runs - Hydraulic Brakes - Automatic Transmission - Approx. Mileage Unknown - Interior Condition: Poor - Interior Problems: Rips In Middle Passenger Seat, Major Cracks &amp; Holes On Dash, Steering Wheel Cover Cracked, Ceiling Liner Peeling - Body Condition: Fair - Inspection Sticker Date: 05/19 - Body Problems: Dents, Scratches, Rust, Truck Tailgate Damaged &amp; Dents, Oxidization - Tires Condition: Fair - Has (3) Tool Cabinets In Bed, Type: Owens Products</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
17	(1) Ford F250 Super Duty Truck Bed	<p>Taken From A 2013 - Damage/Large Gash On Left Rear IN Front Of Light Assembly - Taken Off M-4 - Truck Bumper In Bed</p> <p>- Current Condition Unknown</p>
18	(Lot) Tablet Charging Cabinets	<p>(Approx. 2) Mfg: Tripp-Lite - Portable - This Lot Is Located Outside &amp; Is Susceptible To Weather Conditions, (Approx. 50) Tablets - Tyler Technologies Tablets - Stored Inside Cabinets</p> <p>- Current Condition Unknown</p>