

Lot Number	Title	Description
0	Preview & Removal Information	<p>All purchases will be subject to a 13% buyer's premium.</p> <p><b>Preview:</b> (By Appointment Only-Mandatory-No Exceptions) Thursday, October 3, 2019 (Hours Of Operation: 8:00 a.m. - 2:00 p.m.)</p> <p><b>Location:</b> Transportation Department, 6150 Synott, Houston, Tx 77083 <a href="#">Driving Directions</a></p> <p><b>Removal:</b>(By Appointment Only-Mandatory-No Exceptions) Wednesday, October 9, 2019/Thursday, October 10, 2019 /Friday, October 11, 2019 (Hours Of Operation: 9:00 a.m. - 1:00 p.m.)</p> <p><b>Preview &amp; Removal Contact:</b> Dennis Comacho, (281)983-8400 Ext: 29914</p> <p><b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</b></p>
1	(1) 2009 Bluebird School Bus Vin #4049 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 123 - Conventional Style - Passengers: 71 - Engine Size/Type: CAT ACERT/C7/7.2 - Diesel - Battery: No - Engine In Front - Engine Problems: Not Running, Various Issues, Unit Has Been Sitting Up Several Years - Does Not Run - Air Brakes - Automatic Transmission - Unable To Read Mileage/Dead Battery - Interior Condition: Poor - Interior Problems: Needs Major Cleaning, Exposed To Elements, Some Damage To Upholstery - Body Condition: Fair - Inspection Sticker Date: 07/17 - Body Problems: Oxidized Paint, Rock Chip On Windshield, Needs Cleaning, Surface Scratches, Dents - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
2	(1) 2009 Bluebird School Bus Vin #4051 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 124 - Passengers: 71 - Engine Size/Type: CAT ACERT/C7/7.2 - Diesel - Battery: No - Engine In Front - Engine Problems: Not Running, Various Issue, Has Been Sitting Up Several Years - Does Not Run - Air Brakes - Automatic Transmission - Unable To Read Mileage/Dead Battery - Interior Condition: Poor - Interior Problems: Exposed To Elements, Needs Deep Cleaning, Some Damage To Seats - Body Condition: Fair - Inspection Sticker Date: 02/18 - Body Problems: Needs Cleaning, Oxidized Paint, Surface Scratches, Dents, Has Been Sitting Up Several Years - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
3	(1) 2009 Bluebird School Bus Vin #4046 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 121 - Passengers: Unknown - Engine Size/Type: C7/7.2 CAT Engine - Diesel - Battery: No - Engine In Front - Engine Problems: Has Been Sitting Up 2 Years, Various Issues, Not Running - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Unknown/Dead Battery - Interior Condition: Poor - Interior Problems: Needs Cleaning, Has Been Exposed To Elements - Body Condition: Fair - Inspection Sticker Date: 09/17 - Body Problems: Oxidized Paint, Dents, Scratches, Needs Cleaning, Rock Chip On Windshield - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

4	(1) 2009 Bluebird School Bus Vin #4048 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 125 - Passengers: 71 - Engine Size/Type: CAT ACERT/C7/7.2 - Diesel - Battery: No - Engine In Front - Engine Problems: Sitting Up 2 Years, Various Issues, Not Running - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Needs Cleaning, Exposed To Elements - Body Condition: Fair - Inspection Sticker Date: 08/17 - Body Problems: Oxidized Paint, Surface Scratches, Dents, Needs Cleaning, Rear Left Light Missing Lens - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
5	(1) 2009 Bluebird School Bus Vin #4053 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 128 - Passengers: 71 - Engine Size/Type: CAT ACERT/C7/7.2 - Diesel - Battery: No - Engine In Front - Engine Problems: Has Been Sitting Up For Several Years, Not Running, Various Issues - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Needs Cleaning, Exposed To Elements - Body Condition: Fair - Inspection Sticker Date: 08/17 - Body Problems: Oxidized Paint, Missing (1) Mirror, Surface Scratches &amp; Dents, Peeling Paint On Bus - Tires Condition: Fair To Poor</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
6	(1) 2009 Bluebird School Bus Vin #4052 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 127 - Passengers: 71 - Engine Size/Type: CAT ACERT/C7/7.2 - Diesel - Battery: No - Engine In Front - Engine Problems: Has Been Sitting For 2 Years, Various Issues, Not Running - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Exposed To Elements, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 08/17 - Body Problems: Dent By Passenger Entry Door, Surface Scratches, Dents - Tires Condition: Poor - Tire Problems: Flat Right Front Tire</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
7	(1) 2009 Bluebird School Bus Vin #4050 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 126 - Passengers: 71 - Engine Size/Type: CAT/ACERT C7/7.2 - Diesel - Battery: No - Engine In Front - Engine Problems: Been Sitting For 2 Years, Various Issues, Not Running - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Exposed To Elements, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 08/17 - Body Problems: Oxidized Paint, Surface Scratches, Some Dents, Cracked Glass Passenger Entry Door, Rock Chip On Windshield - Tires Condition: Fair - Tire Problems: Rear Right Are Questionable, Front Tires Look Good</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

8	(1) 2009 Bluebird School Bus Vin #4054 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 129 - Passengers: 71 - Engine Size/Type: CAT Acert/7.2 C7 - Engine Problems: No ECM/Not Running, Sitting Up For Several Years, Various Issues - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Unable To Read - Interior Condition: Fair - Interior Problems: Due To Elements /Exposed Needs Cleaning, Broken Glass Inside - Body Condition: Fair - Inspection Sticker Date: 02/18 - Body Problems: Oxidized Paint, Large Dent/Scratch On Right Side Panel, Entry Door Missing Glass On Entry Door &amp; Cracked Glass On Entry Door, (3) Broken Passenger Windows, Needs Cleaning, Missing (1) Front Mirror - Tires Condition: Poor In Rear, Fair In Front</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
9	(1) 2008 Bluebird School Bus Vin #8993 - Will Need To Be Towed	<p>Will Need To Be Towed - Conventional Style - Bus #: 96 - Passengers: 71 - Engine Size/Type: CAT ACERT/C7 7.2 - Diesel - Battery: No - Engine In Front - Engine Problems: Has Been Sitting Up Several Years, Not Running, Various Issues - Does Not Run - Air Brakes - Automatic Transmission - Approx. Mileage Unable To Read - Interior Condition: Poor - Interior Problems: Needs Cleaning, Exposed To Elements - Body Condition: Fair - Inspection Sticker Date: 07/17 - Body Problems: Oxidized Paint, Surface Scratches, Some Dents, Needs Cleaning, Rock Chip On Windshield, Hood Worn - Tires Condition: Fair In Front, Poor In Rear</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
10	(1) 1993 Ford F150 XL Pickup Truck Vin #3228 - Runs	<p>Unit #: 509 - Conventional Style - Passengers: 3 - Engine Size/Type: 4.9L - Engine In Front - Engine Problems: Has Been Sitting For Approx. 3 Years, Muffler Is Falling Off - Gas - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/or Removed - Runs - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Unable To Read - Interior Condition: Poor - Interior Problems: Torn Seats, Cracks On Dash, Headliner, Needs Replacing, Upholstery Worn, Damage On Door Rest, Carpet Needs Replacing, Dash Covers Damaged Or Missing - Body Problems: Oxidized Paint, Scratches, Dents, Used For Work Truck, Surface Rust On Front Bumper - Tires Condition: Poor - Tire Problems: Has Dual Tanks, Operable Unknown</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
11	(1) 2003 Ford 4 Door Crown Victoria Vin #5843 - Runs	<p>Engine Size/Type: 4.6/V8 - Engine Problems: Cracked Intake Manifold, Suggest Towing - Gas - Battery: Yes - Runs, Auctioneer Recommends Towing - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 12/19 - Approx. Mileage Reads: 87,889**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: When Inspected It Was Raining &amp; Puddle Of Water On Passenger Side Floorboard, Seats Need Cleaning, Drivers Seat Torn - Body Condition: Fair - Body Problems: Peeling Paint, Surface Scratches, Hole On Roof &amp; Trunk Where Lights Where Attached, Peeling Paint, Damaged Left Rear Bumper - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

12	(1) 2003 Ford Crown Victoria Vin #8939 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 546 - Conventional Style - Passengers: 5 - Engine Size/Type: 4.6L - Engine In Front - Engine Problems: Various Issues Including Trane Problem, Brake Problem, AC Compressor Needs Replacing, Sitting Up 3 Years - Gas - Battery: Yes/Dead - Runs - Automatic - Hydraulic Brakes - Inspection Sticker Date: 11/15 - Approx. Mileage Reads: 140,208**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Rear Seat/Police Issue, Drivers Seat Torn, Needs Cleaning, Stains, Steering Wheel Cover Damaged - Body Condition: Fair - Body Problems: Peeling Paint, Hole On Roof &amp; Trunk Where Lights Where Mounted, Scratches - Tires Condition: (3) Are Good, (1) Poor</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
13	(1) 2006 International School Bus Vin #7356 - Runs	<p>Bus #: 201 - Conventional Style - Passengers: 47 Passenger Size/10 Passengers &amp; (3) Wheel Chair Spaces - Engine Size /Type: T444 - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/or Removed - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Unable To Read/Dead Battery - Wheel Chair Lift, Condition Unknown - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Passengers Have Some Wear &amp; Tear, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Dented Light Cover, Back Bumper Pushed In On Left Side, Rock Chip On Windshield - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
14	(1) 2005 International School Bus Vin #5340 - Runs	<p>Bus #: 32 - Conventional Style - Passengers: 72 - Engine Size/Type: T444 - Engine In Front - Engine Problems: Unknown, Engine Worn, Sitting Up 1 1/2 Years - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/or Removed - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Poor - Interior Problems: Needs Major Cleaning, Some Torn Seats, Drivers Seat Torn - Body Condition: Fair - Body Problems: Scratches On Left Side Rub Rail, Oxidized Paint, Dent On Left Rear Corner Above Bumper, Rear Door In Dented, Rear Bumper Is Pushed Down, Dented/Scratch Under Window #5 On Right Side - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
15	(1) 2003 International Bluebird 3800 School Bus Vin #0660 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 273 - Conventional Style - Passengers: 71 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Bad Engine - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 08/19 - Approx. Mileage Reads: 177,768**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Possible Parts Missing, Hand Rail Broken - Body Condition: Fair - Body Problems: Right Rear Scratch/Dent, Right Top Panel Near Rear Door Dent, Missing Rear Bumper, Hole On Hood, Chips On Windshield - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

16	(1) 1999 International 3800 Thomas School Bus Vin #5865 - Runs	<p>Bus #: 179 - Conventional Style - Passengers: 71 - Engine Size/Type: T444E - Engine In Front - Diesel - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 09/19 - Approx. Mileage Reads: 193,887  <b>**Unknown Actual Mileage**</b> - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning, Possible Parts Missing - Body Problems: Chips On Windshield, Surface Scratches, Small Indention On Back Left, Peeling On Cowl &amp; Hood, Damage On Hood, Holes On Hood - Tires Condition: Good - Lens Cover Reflector Cracked, Missing (1) Front Cover</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
17	(1) 2001 International 3800 Thomas School Bus Vin #2832 - Runs	<p>Bus #: 20 - Conventional Style - Passengers: 71 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 09/19 - Approx. Mileage Reads: 203,157<b>**Unknown Actual Mileage**</b> - Interior Condition: Fair - Interior Problems Needs Cleaning, Some Torn Seats, Drivers Seat Tron - Body Problems: Rock Chips On Windshield, Surface Scratches, Front Fender Behind Entry Door Bent, Gash In Front Of Right Side Wheel Well, Dent Rear Bumper, Large Rub On Right &amp; Left Side, Peeling On Cowl &amp; Hood, (1) Mirror Needs Repair On Front</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>