

Lot Number	Title	Description
0	Preview & Removal Information	<p>All purchases will be subject to a 13% buyer's premium.</p> <p>Preview: (By Appointment Only - Mandatory - No Exceptions) Wednesday, October 9, 2019 (Hours Of Operation: 9:00 a.m. - 11:30 p.m./2:00 p.m. - 4:00 p.m.)</p> <p>Location: Auto Mechanics Facility Parking Lot, 1200 Amburn Rd., Texas City, Tx 77591 Driving Directions.</p> <p>Removal: (By Appointment Only - Mandatory - No Exceptions) Tuesday, October 15, 2019/Wednesday, October 16, 2019 /Thursday, October 17, 2019 (Hours Of Operation: 9:00 a.m. - 11:30 p.m./2:00 p.m. - 4:00 p.m.)</p> <p>Preview & Removal Contacts: Sonja Blinka, (409)933-8473 or (409)933-8474, Email: sblinka@com.edu</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p>
40	(1) 2010 Ford Explorer XLT Vin #7154 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 53 - Conventional Style - Passengers: 5 - Engine Size/Type: 4.0L - Engine In Front - Engine Problems: Bad Timing Chain, Not Running - Gas - Battery: No - Does Not Run - Automatic - Hydraulic Brakes - Inspection Sticker Date: 03/17 - Approx. Mileage Reads: 60,000 +/- - Interior Condition: Fair To Poor - Interior Problems: Retrofitted Console, Needs Cleaning, Tear On Drivers Seat, Worn Panels & Upholstery, Arm Rest Needs To Be Refurbished Drivers Side- Body Condition: Fair - Body Problems: Some Surface Scratches, Holes In Roof Where Lights Were Mounted - Tires Condition: Fair - Police Package & Decals Equipment Will Be Removed Prior To Removal</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
41	(1) 1995 Ford Crown Victoria Vin #6062 - Will Need To Be Towed	<p>Will Need To Be Towed - No Brakes - Unit #: 45 - Conventional Style - Passengers: 5 - Engine Size/Type: 4.6L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic - No Brakes - Inspection Sticker Date: 09/17 - Approx. Mileage Reads: 85,787**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Worn Panels & Upholstery, Needs Cleaning, Cracks On Dash - Body Condition: Fair - Body Problems: Surface Scratches, Oxidized Paint, Dent/Rust , Scratch On Rear Left, Rear Right Peeling Paint & Surface Rust, Holes On Roof Where Light Was Mounted, Some Peeling Paint - Tires Condition: Fair - Police Package & Decals Will Be Removed Prior To Removal</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
42	(1) 1998 Ford Passenger Club Wagon Van Vin #0456 - Runs	<p>Unit #: 35 - Conventional Style - Passengers: 5/Missing Several Passenger Seats - Engine Size/Type: 5.4L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 06/19 - Approx. Mileage Reads: 157,965**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Are Stained, Used As Maintenance Vehicle, Some Tears On Seats, Needs Cleaning, Worn Upholstery - Body Condition: Fair - Body Problems: Needs Cleaning, Oxidized Paint, Surface Scratches, Surface Rust On Rear Bumper, Surface Rust On Roof, Rust On Rear Wheel Well Right Side, Surface Rust In Various Locations, Chipped Paint, Rock Chip, Roof Leaks</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

43	(1) 1989 Ford F600 Fire Dept. Equipment Truck Vin #5616 - Runs	<p>Unit #: "Girty" - Conventional Style - Passengers: 3 - Engine Size/Type: 6.6L/Engine Family KFM078EPC8 Model: 165F - Engine In Front - Engine Problems: Unknown - GVWR 21000 - Diesel - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/19 - Approx. Mileage Reads: 21,197**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Normal Wear - Body Condition: Fair - Body Problems: Surface Scratches, (1) Diesel Fuel Tank - Tires Condition: Good - Has A Hackney Bed, Size Of Bed Approx. 16'5" Long - 4 Roll Up Door On Each Side Of Bed - Starting Vehicle: Ask Jerri Glen For Instructions: (409)933-8473</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
----	--	---