

Lot Number	Title	Description
0	Preview & Removal Information	<p><b>**There will be a 13% Buyer's Premium Added to All Buyer's Total for Each Item Purchased.**</b></p> <p><b>Preview:</b> (By Appointment Only-Mandatory-No Exceptions) Tuesday, December 3, 2019 (Hours Of Operation: 9:30 a.m. - 1:30 p.m.)</p> <p><b>Location:</b> SAISD Transportatoin, 418 Roland, Rd., San Antonio, Tx 78210 <a href="#">Driving Directions</a></p> <p><b>Removal:</b> (By Appointment Only-Mandatory-No Exceptions) Monday, December 9, 2019/Tuesday, December 10, 2019/Wednesday, December 11, 2019 (Hours Of Operation: 9:30 a.m. - 1:30 p.m.)</p> <p><b>Preview &amp; Removal Contact:</b> Richard Cavazos &amp; Adam Longoria, (210)354-9314</p> <p><b>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</b></p>
1	(1) 1995 GMC Bluebird School Bus Vin #1173 - Runs	<p>Bus #: C-007 - Conventional Style - Passengers: 47 - Engine Size/Type: 47 - Engine Size/Type: 6.0 - Engine In Front - Engine Problems: Unknown - Gas - Propane Unit Was Converted To Gas - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Stickler Date: 07/20 - Approx. Mileage Reads: 222,546**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Needs Cleaning, Minor Torn Seats - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Scratches Right Rear Near Bumper, Peeling Paint On Rear Bumper - Tires Condition: Fair - Tire Chalks Not Included</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
2	(1) 1995 GMC Bluebird School Bus Vin #1571 - Runs	<p>Bus #: C-009 - Conventional Style - Passengers: 62 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic Transmission - Propane Unit Was Converted To Gas - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 234,468**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Needs Cleaning, Passenger Seats Worn &amp; Some Tears - Body Condition: Fair - Body Problems: Oxidized Paint, Rub Blotches On Right Side, Surface Scratches, Some Peeling Paint On Left Side, Minor Peeling On Door - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
3	(1) 1995 GMC Bluebird School Bus Vin #1196 - Runs	<p>Bus #: C-013 - Conventional Style - Passengers: 47 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown - Gas - Propane Unit Was Converted To Gas - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 299,304**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Are Worn, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Paint Fading On Roof, Rear Door Is Bent &amp; Will Need Replacing, Some Peeling &amp; Cracks On Cowl - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
4	(1) 1999 International 3800 Crown School Bus Vin #3860 - Runs	<p>Bus #: B-226 - Conventional Style - Passengers: 71 - Engine Size/Type: T444E - Engine In Front - Engie Problems: Unknown - Diesel - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 193,221**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Normal Wear, Seats Have Some Torn Seats &amp; Noticeable Repairs, Needs Cleaning - Body Condition: Fair To Poor - Body Problems: Oxidized Paint, Some chips &amp; Cracks On Cowl, Some Peeling On Rear, Peeling &amp; Cracks On Rear Right Panel, (Approx. 3) Small Gashes &amp; (1) Large Hole On Left Rear Panel, Scratches, Peeling On Front Left Rear Wheel Well, Peeling On Hood - Tires Condition: Good - Tire Chalks Not Included</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

5	(1) 1995 GMC Bluebird School Bus Vin #1307 - Runs	<p>Bus #: C-005 - Conventional style - Passengers: 47 - Engine Size/Type: 6.0 - Engine In Front - Engine Problems: Unknown - Gas - Propane Unit Was Converted To Gas Unit - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 251,586**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Minor Tears On Seats, Seats Worn, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Graffiti On Right Side By Entry Door, Scratches &amp; Chip/Damaged Small Panel Near Bumper, Peeling On Cowl &amp; Hood - Tires Condition: Good - Tire Chalk Not Included</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
6	(1) 1993 Bluebird School Bus Vin #0685 - Runs	<p>Bus #: C-004 - Conventional Style - Passengers: 71 - Engine Size/Type: 366/6.0L - Engine In Front - Engine Problems: Unknown - Gas - Propane Unit Was Converted To Gas unit - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 187,883**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Minor Tears, Some Noticeable Repair, Minor Surface Rust - Body Condition: Fair - Body Problems: Oxidized Paint, Scratch On Right Side, Surface Rust On Roof, Some Chips On Cowl, Peeling On Hood, Hole On Left Side With A He From Prior Pipe - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
7	(1) 1994 Bluebird School Bus Vin #9747 - Runs	<p>Bus #: C-017 - Conventional Style - Passengers: 13 Passengers &amp; (2) Wheel Chair Spaces - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Propane Unit Has Been Converted To Gas Unit - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 149,206 **Unknown Actual Mileage** - Wheel Chair Lift, Condition Unknown - Interior Condition: Fair - Interior Problems: Needs Cleaning, Upholstery Worn, Noticeable Repairs, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Peeling On Cowl, Missing (1) Light Lens Cover - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
8	(1) 1994 GMC Bluebird School Bus Vin #9776 - Runs	<p>Bus #: C-006 - Conventional Style - Passengers: 71 - Engine Size/Type: 6.0 - Engine In Front - Engine Problems: Unknown - Gas - Propane Unit Was Converted To Gas Unit - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 08/20 - Approx. Mileage Reads: 165,478**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Torn Drivers Seat, Needs Cleaning, Some Minor Torn Passenger Seats - Body Condition: Fair - Body Problems: Missing Front Mirror, Oxidized Paint, Surface Scratches, Slight Indention &amp; Scratch On Left Rear, Rock Chip On Windshield, Peeling On Hood, Some Damage On Cowl - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
9	(1) 1995 GMC Bluebird School Bus Vin #1160 - Runs	<p>Bus #: C-015 - Conventional Style - Passengers: 467 - Engine Size/Type: 6.0 - Engine In Front - Engine Problems: Unknown - Gas - Propane Unit Was Converted To Gas Unit - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 181,198**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Seats Are Worn, Some Minor Tears - Body Condition: Fair - Body Problems: Graffiti On Right Side Near Fuel Door, Oxidized Paint, Surface Scratches, Minor Stress Cracks On Cowl, Hood Oxidized - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

10	(1) 1995 GMC Bluebird School Bus Vin #1251 - Runs	<p>Bus #: C-010 - Conventional Style - Passengers: 47 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown - Gas - Propane Bus Was Converted To Gas Unit - Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 188,956**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Minor Tear On Drivers Seat, Needs Cleaning, Worn Upholstery - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Peeling On Hood, Small Hole On Roof - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
11	(1) 1993 Bluebird School Bus Vin #0180 - Runs	<p>Bus #: C-003 - Conventional Style - Passengers: 71 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown - Gas - Propane Unit Was Converted To Gas Unit - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 232,713**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Upholstery In Various Conditions - Body Condition: Fair - Body Problems: Oxidized Paint, Major Peeling On Right Side Lower Panel &amp; Slight Indention, Dent On Right Rear Corner &amp; Peeling, Peeling On Left Rear Corner, Minor Dust On Right Rear Near Corner, Peeling On Hood, Emblem Missing On Hood</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
12	(1) 2008 International BE200 Handy School Bus Vin #6759 - Runs	<p>Bus #: B-259 - Conventional Style - Passengers: 17 - Engine Size/Type: VT 365 Engine Family - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes/Dead - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 148,356**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Are Worn &amp; Some Minor Tears - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
13	(1) 1993 GMC Bluebird School Bus Vin #6451 - Runs	<p>Bus #: C-008 - Conventional style - Passengers: 35 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown - Gas - Propane Unit Was Converted To Gas -Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Reads: 291,840**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Graffiti On Left Side Under Windows 2-4, Minor Chips On Cowl, Peeling On Hood - Tires Condition: Good To Fair</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
14	(1) 2001 Chevy Bluebird School Bus Vin #8371 - Runs	<p>Bus #: B-362 - Conventional Style - Passengers: 71 - Engine Size/Type: 495/8.1 - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes/Dead - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 097,723**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Minor Tears On Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Crack On Windshield, Oxidized Paint, Surface Scratches, Dents On Right Rear Corner Panel, Dent On Rear Bumper, Dent On Left Rear Corner Panel, Scratches, Peeling On Cowl &amp; Hood - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

15	(1) 1996 GMC Bluebird School Bus Vin #0466 - Runs	<p>Bus #: C-002 - Conventional Style - Passengers: 71 - Engine Size/Type: 7.0 - Engine In Front - Engine Problems: Unknown - Gas - Propane Unit Was Converted To Gas - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 02/20 - Approx. Mileage Reads: 170,797**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seats Are 2 Colors/Brown &amp; Gray, Some Are Torn, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Prior Graffiti On Right Side Of Bus Noticeable, Graffiti On Left Side Bus Under Window 1&amp;2, Peeling On Hood</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
16	(1) 1994 GMC Bluebird School Bus Vin #9621 - Runs	<p>Bus #: C-016 - Conventional Style - Passengers: 71 - Engine Size/Type: 6.0 - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 188,280**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Minor Tears On Passenger Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Large Indention/Damage On Right Rear In Front Of Wheel Well, Large Scratch On Right Rear Panel, Large Dent On Right Corner Panel, Scratches, Peeling On Hood - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
17	(1) 1995 GMC Bluebird School Bus Vin #1566 - Runs	<p>Bus #: C-014 - Conventional Style - Passengers: 62 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown - Gas - Propane Converted To Gas Unit - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 201,232**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Some Torn Passenger Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Graffiti Covered Over With Yellow Paint On Left Front Panel Under Windows 1-3, Hole On Hood &amp; Peeling Paint, Some Chips On Couch - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
18	(1) 1996 Carpenter School Bus By Crown Vin #8967 - Runs	<p>Bus #: B-211 - Transit Style - Passengers: 19 Passengers W/ 1-2 Wheel Chair Spaces - Engine Size/Type: 5.9L Cummins - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Yes - Runs - Automatic Transmission - Transmission Condition: AT 545 - Unknown Brake Type - Inspection Sticker Date: 09/20 - Approx. Mileage Unknown - Interior Condition: Fair - Wheel Chair Lift Unknown - Interior Problems: Needs Cleaning, Some Seats Are In Poor Condition, Floor Needs Repairs, Step Needs Repair - Body Condition: Fair - Body Problems: Oxidized Paint, Scratches, Dent Under Window #5, Surface Rust On Rear, Peeling Paint, Crack On Front Grill, Rock Chip On Windshield, Rubber Molding Loose On Entry Door - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
20	(1) 1994 GMC Bluebird School Bus Vin #9951 - Runs	<p>Bus #: C-001 - Conventional Style - Passengers: 71 - Engine Size/Type: 6.0 - Engine In Front - Engine Problems: Unknown - Gas - Propane Converted To Gas Unit - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 190,534**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Front Bumper Damaged, Oxidized Paint, Surface Scratches, Minor Dent On Left Rear - Tires Condition: Good</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>

21	(1) 1994 GMC Bluebird School Bus Vin #9881 - Runs	<p>Bus #: C-011 - Conventional Style - Passengers: 71 - Engine Size/Type: 6.0L - Engine In Front - Engine Problems: Unknown - Gas - Propane Converted To Gas Unit - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 205,670**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Roof Paint Worn &amp; Faded, Scratches On Right Rear Corner Panel - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
22	(1) 2002 Chevy Mid Bus Vin #5073 - Runs	<p>Bus #: B365 - Conventional Style - Passengers: 23 - Engine Size/Type: 5.7L- Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes/Dead - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 10/20 - Approx. Mileage Reads: 237,870**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Some Seats Are Worn &amp; Torn, Crack On Dash - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Some Peeling Paint, Small Dent Behind Right Wheel Well, Scratches - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
23	(1) 2001 GMC Bluebird 3500 Mid Bus Vin #0493 - Runs	<p>Bus #: B-363 - Conventional Style - Passenger: 16 - Engine Size/Type: 5.7L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes/Dead - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 288,339**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Crack On Dash, Minor Tears, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Dent On Front Left Side Of Cab, Vent Panel Above Hood Damaged &amp; Broken - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>
24	(1) 2009 International CE300 School Bus Vin #0642 - Will Need To Be Towed	<p>Will Need To Be Towed - No Key - Bus #: B-314 - Conventional Style - Passengers: 60 - Engine Size/Type: Maxx Force /Model: GDT210 - Engine In Front - Engine Problems: Overheated Engine, Bad Cam, Parts Missing - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Unable To Read/No Battery - Interior Condition: Fair - Interior Problems: Many of The Seats Are Torn Or Have A Noticeable Repair, Panels Loose On Bus - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Slight Indention On Rear Bumper, Dent On Left Rear Corner Panel, Dent On Battery Door, Missing Headlights On (1) Mirror - Exempt Plate &amp; Name Will Be Removed Prior To Removal</p> <p>- Current Condition Unknown</p> <p><b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>