

Lot Number	Title	Description
0	Preview & Removal Information	<p>All purchases will be subject to a 13% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Wednesday, December 11, 2019 (Hours Of Operation: 9:00 a.m. - 11:30 a.m./1:00 p.m. - 3:00 p.m.)</p> <p>Location 2: (Lots 200-202) 4550 FM 1329, San Diego, Tx 78384 Driving Directions</p> <p>Removal:(By Appointment Only - Mandatory - No Exceptions) Monday, December 16, 2019/Tuesday, December 17, 2019/Wednesday, December 18, 2019 (Hours Of Operation: 9:00 a.m. - 11:30 a.m./1:00 p.m. - 3:00 p.m.)</p> <p>Preview & Removal Contacts: Robert S. Gonzales Jr., (361)279-3382 X2622 or email: Robert3@aramark.com Angelica Smithwick, (361)279-3382 X2229 or email: asmithwick@sdisd.us</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p>
200	(1) 2000 International Thomas 3800 School Bus Vin #3349 - Runs	<p>Bus #: 46 - Conventional Style - Passengers: 71 - Engine Size/Type: T444E - Engine In Front - Diesel - Battery: Yes - Runs - Automatic Transmission - Air Brakes - Inspection Sticker Date: 08/18 - Approx. Mileage Reads: 148,023**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Drivers Seat Torn, Surface Rust, Seats Torn Throughout Bus, Floor Soft Toward Rear Of Bus - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Rust On Right Rear Panel & Scratches, Surface Rust, Rust On Cowl, Windshield Scratched From Poor Windshield Wiper, Peeling On Cowl, Peeling On Hood, Rock Chop On Windshield - Tires Condition: Fair - A/C Did Work At Time Of Demonstration</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
201	(1) 2000 International Thomas 3800 School Bus Vin #3399 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 45 - Conventional Style - Passengers: 71 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Bad Engine/Parts Missing - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 08/17 - Approx. Mileage Reads: 146,348**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Are Rusty & Torn, Needs Cleaning, Parts Missing - Body Condition: Fair - Body Problems: Oxidized Paint, Scratches, Surface Scratches, Surface Rust, Needs Cleaning, Panels Missing, Broken Passenger Window, Rust On Roof Near Front Windshield, Cracked Windshield & Rock Chip, Rust On Cowl, Peeling On Cowl, Peeling On Hood, Missing (1) Mirror In Front</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
202	(1) 1997 Chevy Lumina 4 Door Vin #0922 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 2 - Conventional Style - Passengers: 5 - Engine Problems: Needs A Fuel Pump, Current Condition Unknown, Ran When Parked, Sitting Up For Several Years - Gas - Battery: Yes - Does Not Run - Automatic Transmission - Hydraulic Brakes - Approx. Mileage Reads: 169,357**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Needs Cleaning, Seats & Carpet Stained, Dash Pulling & Curling Up - Body Condition: Poor - Body Problems: Oxidized Paint, Surface Rust On Hood, Chipped Paint, Needs Cleaning, Molding ON Sides Of Vehicle Are Worn & Dry Rot, Cracked Windshield, Rust ON Cowl On Vehicle, Missing Water Reservoir Cap, Rust Under Hood On Mounts, Rust On Hood On Passenger Side, Peeling Paint On Doors, Rear Bumper Worn, Needs Cleaning - Tires Condition: Fair - Tire Problems: All Tires Flat</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>