

Lot Number	Title	Description
0	Preview & Removal Information	<p>All purchases will be subject to a 13% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, January 28, 2020 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.)</p> <p>Location : Southside ISD Warehouse, 3105 S. Loop 1604 E, San Antonio, TX 78264 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) (Hours Of Operation: 8:00 a.m. - 3:00 p.m.)</p> <p>Preview & Removal Contact: Robert Garcia, (210)529-1797 email: roberto.garcia@southsideisd.org</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p>
2	(1) 2012 International CE School Bus Vin #5883 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 4 - Conventional Style - Passengers: 27 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: Bad Engine, Needs An Alternator, A/C Parts Missing - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 02/18 - Approx. Mileage Unable To Read/Dead Battery - Wheel Chair Lift, Condition: Not Working - Interior Condition: Fair - Interior Problems: Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Needs Hood Spring Hinges, Drive Is IN Rear Inside Bus, Oxidized Paint, Surface Scratches, Scratches On Hood - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
5	(1) 2010 International CE School Bus Vin #6143 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 41 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: Not Running, Engine Problem Unknown - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 04/18 - Approx. Mileage Unable To Read/No Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning, Missing (2) A/C Vents On Dash - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Dents On Right Rear, Lights Missing On Rear - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
6	(1) 2010 International School Bus Vin #6162 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 42 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: No ECM, Not Running - Diesel - Battery: No - Does Not Run - Air Brakes - Inspection Sticker Date: 02/18 - Approx. Mileage Unable To Read/No Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Scratch On Right Rear, Missing Passenger Window On Left Rear - Tires Condition: Fair</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

8	(1) 2003 Freightliner Thomas School Bus Vin #9451 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 36 - Conventional Style - Passenger: 77 - Engine Size/Type: Cummins 24 Valve - Engine In Front - Engine Problems: Ran When Parked, Current Condition Unknown, Unit Was Retired - Diesel - Battery: No - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 10/18 - Approx. Mileage Reads: 206,872 **Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Worn Upholstery, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Some Dents, Missing Front Mirrors - Tires Condition: Good In Front, Fair On Rear</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
10	(1) 2012 International School Bus Vin #7578 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 50 - Conventional Style - Passengers: 77 - Engine Size/Type: Maxx Force 7 - Engine In Front - Engine Problems: Not Running, Engine Was Rebuilt & Still Is Not Running, Problem Unknown, Engine Parts Inside Bus - Diesel - Battery: Yes/Dead - Does Not Run - Automatic Transmission - Air Brakes - Inspection Sticker Date: 05/18 - Approx. Mileage Unknown/Dead Battery - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning, Some Stained Seats, Engine Parts Loose Inside Bus, Parts Possibly Missing - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Scratch On Right Rear, Front Grill Loose Inside Bus - Tires Condition: Good In Rear, Fair In Front</p> <p>- Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>