












Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>**All purchases will be subject to a 13% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</p> <p>Preview: Wednesday, January 22, 2020 (By Appointment Only - No Exceptions) (Hours 8 a.m. - 5 p.m.) Location: Hallsville ISD Training Center, 300 Willow St., Hallsville, Tx 75650 Driving Directions Removal: (By Appointment Only - No Exceptions) Monday, January 27, 2020/Tuesday, January 28, 2020/Wednesday, January 29, 2020 (Hours 8 a.m. - 5 p.m.) Preview & Removal Contact: Roy Presley (903) 668-5970 rpresley@hisd.com</p> <p>Winning Bidder is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/or Removed.</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	
1	(1) 1997 International Bus Vin#9767	<p>1997 International Bus - Bus #21- DT 466e engine - Diesel - Has Battery - Automatic - Runs - Air Brakes - Passenger: 71 - Mileage Reads - 212533 - Interior Condition: Fair -Body Condition - Fair - Crack in frame near rear axle - No Front Bumper - Engine had in frame overhaul just before pulling off route Ran until pulled off route spins over with no start now. - Tire Condition: Fair</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	
2	(1)1997 International Bus Vin#9766	<p>1997 International Bus - Bus 46 - Conventional Style - DT 466e - 71 Passenger - Diesel - Has Battery - Runs - Automatic - Air Brakes - Mileage Reads: 187080 - Interior Condition: Fair - Crack in frame near rear axle - Body Condition: Fair - Tire Condition: Fair - Cranks and Runs</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	
3	(1)1994 International Bus Vin#2719	<p>1994 International Bus, Unit 27 - Style: Conventional - Passenger:71- DT 360 - Engine: Front - Diesel - Has Battery - Automatic- Air Brakes - Inspection: 7/19 - Mileage Reads: 203551 - Interior Condition: Poor - Plywood Floor needs replaced -Bus Runs and drives good - Body Condition: Fair - Tire Condition: Fair</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	

4	(1)1997 International Bus Vin#9768	1997 International Bus - Bus 20 - Style: Conventional - Passenger: 71 - DT 466e - Engine: Front - Diesel - Has Battery - Cranks and Runs - Automatic - Air Brakes - Inspection: 6/19 - Mileage: 157596 - Interior Condition: Fair - Body Condition: Crack in frame near rear axle. Tire Condition: Fair There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	
5	(1)1993 International Bus Vin#6607	1993 International Bus - Bus 203 - Style: Conventional - Passenger: 71 - Engine Size: DT360 - Engine: Front - Diesel - Has Battery - Runs and drives but needs floor, and cowl repaired There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	
6	(1)1987 International Bus Vin#8195	1987 International Bus - Bus 208 - Style: Conventional - Passenger 71 - 9.0 Liter Diesel - Has Battery - Bus Runs and Drives Good - Automatic- Air Brakes - Mileage Reads: 129654 - Interior Condition: Fair - Body Condition: Fair - Tire Condition: Fair There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	
7	(1)1987 International Bus Vin# 28011	1987 International Bus - Bus 245- 9.0 Liter Diesel Engine - Conventional Style - Passenger: 71 - Has Battery - Cranks and Runs Good - Automatic - Inspection: 7/19 - Mileage: 128155 - Interior: Condition: Fair - Body Condition: Fair - Tire Condition: Fair There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	
8	(1)1995 International Bus Vin#1022	1995 International Bus - Bus 202 - Passenger: 71 - Conventional Style - DT 466 - Cranks and Runs Good - Diesel - Has Battery - Runs - Air Brakes - Inspection: 01/20 - Mileage Reads: 239148 - Interior Condition: Fair - Needs Plywood Floor Repair - Body Condition: Fair - Tire Condition: Fair There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	
9	(1)1996 International Bus Vin#0170	1996 International Bus - Bus 246 - Conventional Style - Passenger: 71 - Dt 466 - Cranks and runs good - Diesel - Has Battery - Automatic - Air Brakes - Inspection: 7/19 - Mileage Reads: 235620 - Interior Condition: Fai - Needs Floor Replaced - Body Condition: Fair - Tire Condition: Fair There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	

10	(1)1994 International Bus Vin# 2718	<p>1994 International Bus - Bus 24 - Passenger: 71 - Conventional Style - DT 360 - Cranks and runs good - Diesel - Automatic - Has Battery - Air Brakes - Inspection Reads: 6/19 - Mileage Reads: 189234 - Interior Condition: Needs plywood floor replaced - Body Condition: Fair - Tire Condition: Fair</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	
11	(1) 1991 International Bus Vin#9755	<p>1991 International Bus - Bus 247 - Conventional Style - Passenger: 71 - DT 360 - Cranks and Runs good - Diesel - Has Battery - Automatic - Inspection Sticker 8/19 - Mileage Reads: 129603 - Interior Condition: Fair - Body Condition: Fair - Tires: Fair</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buvvers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buvvers responsibility once purchased by buver. Buver should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	