

| Thumbnail | Lot Number | Description |
|--|------------|--|
|  | 0 | <p>**All purchases at will be subject to a 13% buyer's premium.**</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, February 11, 2020 (Hours Of Operation: 8:00 a.m. - 1:00 p.m.)</p> <p>Location: Pidgeon Stadium, 11355 Falcon Rd. A, Houston, Tx 77065 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Monday, February 17, 2020/Tuesday, February 18, 2020/Wednesday, February 19, 2020 /Thursday, February 20, 2020/ Friday, February 21, 2020 (Hours of Operation: 8:00 a.m. - 1:00 p.m.) Removal Contact: Kristi Giron, 281-517-6366</p> <p>Buyer Will Need To Pick Up The Key For Their Unit At The Cy-Fair Windfern Location: Windfern Administrative Annex - Delivery Area, 12510 Windfern Rd., Houston, TX 77064 Driving Directions.</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed No Cash Payments Accepted On Site</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> |
|  | 1 | <p>Unit # 1842 - Transit Style - Passengers: 2 - Engine Size/Type: Vortec 6.0L - Engine In Front - Engine Problems: Unknown - Gas - Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 04/20 - Approx. Mileage Reads: 183,432 - Interior Condition: Fair - Interior Problems: Missing Parts On Dashboard, Torn Seats, Inside Drivers Door Panel Damaged, Needs Cleaning - Body Condition: Fair - Body Problems: Some Rust, Dents & Scratches, Dents On Front Bumper - Tires Condition: Fair - Tires Condition: Unknown - Protection Cage - Shop Made Cabinets In Cargo Area - Rack On Top Of Unit - Has Trailer Hitch</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | 2 | <p>Unit # 1312 - Conventional Style - Passengers: 2 - Engine Size/Type: Unknown - Engine In Front - Engine Problems: Bad Motor, WILL NOT START - Gas- Battery: Yes, Dead - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 01/19 - Approx. Mileage Reads: 83, 788 **Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Seat Torn, Drivers Side Handle On Door Is Coming Off & Is Damaged - Body Condition: Fair - Body Problems: Rust & Peeling Paint - Tire Condition: Fair - Tire Problems: Unknown - Lawson-Koenig Headache Rack & Tool Boxes In Bed, Lift Tailgate, Condition Unknown -</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |

| | |
|--|--|
|  | <p>Unit # 1813 - Transit Style - Passengers: 2 - Engine Size/Type: Vortec 5.7L - Engine Problems: "Check Gauges" Light Is On & The Buzzer Is Going Off In Vehicle - Gas - Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 01/20 - Approx. Mileage Reads: 131,269 - Interior Condition: Fair - Interior Problems: Torn Seats, Drivers Side Door Handle Is Missing, Radio Is Missing, Headliner Needs Replacing, Needs Cleaning - Body Condition: Fair - Body Problems: Peeling Paint, Rust, Scratches, Dents In Back Bumper, Dent On Passenger Side Quarter Panel, Crack On Windshield, Some Dents - Tire Condition: Fair - Tire Problems: Unknown - Rack On Top Of Unit, Protection Cage</p> <p>3 There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>Recommend Towing - Unit # 1859 - Transit Style - Passengers: 2 - Engine Size/Type: Vortec 6.7L - Engine In Front - Engine Problems: Overheats, Unit Will Start & Run - Gas - Battery: Yes - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 01/20 - Approx. Mileage Reads: 155,931 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Dashboard Peeling & Damaged, Headline Needs Replaced, Cracked Windshield - Body Condition: Fair - Body Problems: Peeling Paint, Rust, Some Scratches, Surface Rust On Top Of Unit - Tires Condition: Fair - Tires Problems: Unknown - Wooden Shop Made Console With Drink Holders Between Front Seats - Protection Cage - (1) Cabinet & Metal Storage Box In Cargo Area, Proto Tool Box in Cargo Area</p> <p>4 There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>Unit # 1832 - Transit Style - Passengers: 2 - Engine Size/Type: Vortec 5.7L - Engine Problems: Unknown - Gas - Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 05/19 - Approx. Mileage Reads: 152,398 - Interior Condition: Fair - Interior Problems: Rearview Mirror Is Loose, Knob Is Missing On Window Handle On Drivers Side Door Panel, Glove Box Is Not Intact, Torn Seats, Steering Wheel Is Worn, Needs Headliner Replaced, Needs Cleaning - Body Condition: Fair - Body Problems: Scratches, Ruse, Bumper Is Dented On Right Passenger Side, Dent On Driver Side Quarter Panel, Front Bumper Is Dented, Peeling Paint - Tires Condition: Fair - Tires Problems: Unknown - Protection Cage - Shop Made Cabinets In Cargo Area - Rack On Top Of Unit</p> <p>5 There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>Unit # 1809 - Transit Style - Passengers: 2 - Engine Size/Type: Vortec 5.7L - Engine Problems: Unknown - Gas - Battery: Yes, Dead And Needs Jumped - WILL NOT START - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 08/20 - Approx. Mileage Reads: Unknown Due To Dead Battery - Interior Condition: Fair - Interior Problems: Torn Seats, Needs Cleaning, Peeling Paint Steering Wheel Worn, Dashboard Worn, Headliner Needs Replaced - Body Condition: Fair - Body Problems: Dents, Scratches, Rust, Front Bumper Peeling Paint & Dented, Window Tint Is Peeling, Dent On Driver Side Quarter Panel, Back Door Handle Is Broken, Dent On Passenger Side Middle Door - Tire Condition: Fair - Tire Problems: Unknown - Protection Cage - Rack On Top Of Unit - (1) Shop Made Cabinet In Cargo Area</p> <p>6 There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |

| | | |
|--|----|--|
|  | 7 | <p>Unit # 1840 - Transit Style - Passengers: 2 - Engine Size/Type: Vortec 5.7L - Engine Problems: Sounds Like An Exhaust Issue When Unit Is Running - Gas - Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 10/19 - Approx. Mileage Reads: 187,278 - Interior Condition: Fair - Interior Problems: Torn Seats, Needs Cleaning, Headliner Needs Replaced, Peeling Paint On Dashboard - Body Condition: Fair - Body Problems: Peeling Paint, Rust, Front & Back Bumper Is Dented, Rock Chip On Windshield - Protection Cage - Cabinets In Cargo Area</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | 8 | <p>Unit # 1845 - Transit Style - Passengers: 2 - Engine Size/Type: Vortec 5.7L - Engine Problems: Unknown - Gas - Battery: Yes - RUNS - Automatic Transmission - Inspection Sticker Date: 10/19 - Approx. Mileage Reads: 172,710 - Interior Condition: Fair - Interior Problems: Airbag Is On The Dashboard, Needs Cleaning, Torn Seats, Headliner Needs Replaced, Driver Door Panel Is Cracked - Body Condition: Fair - Body Problems: Passenger Door In The Middle Does Not Close, Rust, Dents, Scratches, Peeling Paint, Dented Front Bumper - Tire Condition: Fair - Tires Condition: Unknown - Protection Cage - Shop Made Cabinets In Cargo Area, Rack On Top Of Unit, Shop Made Console With Drink Holders Between Two Front Seats</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | 9 | <p>Unit # 1880 - Transit Style - Passengers: 2 - Engine Size/Type: Vortec 6.0L - Engine Problems: Unknown - Gas - Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 09/19 - Approx. Mileage Reads: 119,954 - Interior Condition: Fair - Interior Problems: Torn Seats, Know Missing On Window Roll Up Handle On Driver Side, Some Wear On Dashboard, Headliner Needs Replaced - Body Condition: Fair - Body Problems: Peeling Paint, Dent On Passenger Side Quarter Panel, Scratches, Rust, Dent On Back Bumper, Rock Chip On Windshield - Tires Condition: Fair - Tires Problems: Unknown - Protection Cage, Rack On Top Of Unit, Shop Made Cabinets In Cargo Area</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | 10 | <p>Unit # 1882 - Transit Style - Passengers: 2 - Engine Size/Type: Unknown - Engine Problems: Unknown - Gas - Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 04/20 - Approx. Mileage Reads: 142,722 - Interior Condition: Fair - Interior Problems: Torn Seats, Headline Needs Replaced, Needs Cleaning, Rearview Mirror Not Attached - Body Condition: Fair - Body Problems: Front Cracked Windshield, Paint Peeling, Some Scratches & Rust - Tires Condition: Fair - Tires Problems: Unknown - Protection Cage - Rack On Top Of Unit</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |

| | | |
|--|-----------|--|
|  | <p>11</p> | <p>Recommend Towing - Unit # 1886 - Transit Style - Passengers: 2 - Engine Size/Type: Vortec 6.0L - Engine Problems: Engine Knocks - "Check Engine" Light & "Check Gauges" light Is On ON The Dashboard - Gas - Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 10/20 - Approx. Mileage Reads - 192,667 - Interior Condition: Fair - Interior Problems: Headliner Needs Replaced - Torn Seats - Worn Driver Side Door Panel & Steering Wheel - Body Condition: Fair - Body Problems: Rock Chip On Windshield, Peeling Paint, Rust, Scratch On Passenger Front Quarter Panel - Tires Condition: Fair - Tires Problem: Unknown - Protection Cage - Rack On Top Of Unit - Shop Made Cabinets In Cargo Area</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>12</p> | <p>Unit # 1884 - Transit Style - Passengers: 2 - Engine Size/Type: Vortec 6.0L - Engine Problems: Unknown - Gas - Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Reads: Unknown - Interior Condition: Fair - Interior Problems: Torn Seats, Headliner Needs Replaced - Body Condition: Fair - Body Problems: Rock Chip On Windshield, Peeling Paint, Scratches, Scratch & Dent On Passenger Side On The Middle Door, Dent On Passenger Side Quarter Panel Behind Door - Tires Condition: Fair - Tires Problems: Unknown - Protection Cage - Rack On Top Of Unit</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>13</p> | <p>Unit # 1396 - Passengers: 2 - Engine Size/Type: Unknown - Engine Problems: Bad Key Cylinder - DOES NOT START - Gas - Battery: Yes - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Reads: 110,288 - Interior Condition: Fair - Interior Problems - Needs Cleaning, Steering Column Has Missing Parts, Driver Side Door Panel Is Damaged - Body Condition: Fair - Body Problems: Peeling Paint, Scratches, Dents & Rust - Tires Condition: Fair - Tires Problems: Unknown - Hydraulic Lift On Tailgate, Unknown Condition - Tool Box In Bed, Unknown Condition</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>14</p> | <p>Unit # 1315 - Passengers: 2 - Engine Size/Type: Unknown - Engine Problems: Unknown - Gas - Battery: Yes - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 02/20 - Approx. Mileage Unknown - Interior Condition: Fair - Interior Problems: Torn Seat, Headliner Needs Replaced - Body Condition: Fair - Body Problems: Rust, Scratches, Dented Rear Bumper, Peeling Paint - Tires Condition: Fair - Tires Problems: Unknown - Toolbox In Bed Is Damaged</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |

| | | |
|--|-----------|---|
|  | <p>15</p> | <p>Unit # 1397 - Passengers: 2 - Engine Size/Type: Unknown - Engine Problems: Unknown - Gas - Battery: Yes - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Reads: 94,186 - Interior Condition: Fair - Interior Problems: Seat Torn, Driver Side Door Panel Damaged & Missing Parts, Needs Cleaning, Side Mirror Controller Is Broken - Body Condition: Fair - Body Problems: Rust, Dent On Passenger Side Behind Door, Scratches, Back Bumper Is Dented - Tires Condition: Fair - Tires Problems: Unknown</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>16</p> | <p>Needs To Be Towed - Unit # 1304 - Passengers: 4 - Engine Size/Type: Unknown - Engine Problems: Cranks But Will Not Start - Gas - Battery: Yes - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 05/20 - Approx. Mileage Reads: 71,518 - **Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Passenger Side Door Panel Is Damaged - Body Condition: Fair - Body Problems: Rust, Peeling Paint, Scratches, Dent On Back By Tail Light, Dent On Driver Side At Bottom Behind Door - Tires Condition: Fair - Tires Problems: Unknown - No Tailgate</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>17</p> | <p>Unit # 1307 - Passengers: 4 - Engine Size/Type: Unknown - Gas- Battery: Yes - Runs - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Reads: 108,555 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Seatbelts Have Some Parts Missing, Driver Side Door Handle Is Loose, Driver Side Door Panel In Back Is Worn, Crack On Dashboard - Body Condition: Fair - Body Problems: Rock Chip On Windshield, Drivers Side Door Handle Is Loose, Drivers Side Door Panel Is Worn & Damaged- Scratches, Peeling Paint, Dent In Tailgate, Dent On Passenger Side Wheel Well - Tire Condition: Fair - Tire Problems: Flat Tire On Rear Passenger Side</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>18</p> | <p>Unit # 1835 - Passengers: 4 - Engine Size/Type: Unknown - Gas- Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 07/19 - Approx. Mileage Reads: 67,113 - **Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Needs Cleaning, Headline Needs Replaced, Some Rust - Body Condition: Fair - Body Problems: Cracked Windshield, Back Bumper Is Dented, Peeling Paint, Scratches, Crack & Damage On Passenger Side Wheel Well, Some Damage on Front Bumper, Missing Mirror On Driver Side - Tires Condition: Fair - Tires Problems: Unknown - Bed Rails On Bed</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |

| | | |
|--|-----------|---|
|  | <p>19</p> | <p>NO KEYS - Unit # 1400 - Passengers: 2 - Engine Size/Type: Vortec 6.0L - Engine Problems: Unknown - Gas - Battery: Yes - RUNS - Automatic Transmission: Hydraulic Brakes - Inspection Sticker Date: 07/20 - Approx. Mileage Reads: 104,432 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Headline Needs Replaced, Cracks In Console, Steering Wheel Worn, Rearview Mirror Unattached - Body Condition: Fair - Body Problems: Rock Chip On Windshield, Back Bumper Dented, Some Scratches & Rust, Peeling Paint, Rust On Roof Of Unit - Tires Condition: Fair - Tires Problems: Unknown - Protection Cage - Rack On Top Of Unit</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>20</p> | <p>NO KEYS - Unit # 1406 - Passengers: 2 - Engine Size/Type: Vortec 6.0L - Engine Problems: Unknown - Gas - Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Reads: 108,330 - Interior Condition: Fair - Interior Problems: Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Some Scratches & Rust, Dent & Scratch On Passenger Side Of Back Quarter Panel, Peeling Paint, Small Rock Chip On Windshield - Tires Condition: Fair - Tires Problems: Unknown - Protection Cage - Rack On Top Of Unit</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>21</p> | <p>NO KEYS - Unit # 1402 - Passengers: 2 - Engine Size/Type: Vortec 6.0L - Engine Problems: Unknown - Gas - Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 11/19 - Approx. Mileage Reads: 60,244 - **Unknown Actual Mileage** Interior Condition: Fair - Interior Problems: Needs Cleaning - Body Condition: Fair - Body Problems: Dent On Front Bumper, Peeling Paint, Passenger Side Door Mirror Is Missing, Steering Wheel Worn, Torn Seat - Tires Condition: Fair - Tires Problem: Unknown - Protection Cage - Rack On Top Of Unit</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>22</p> | <p>NO KEYS - Unit # 1405 - Passengers: 2 - Engine Size/Type: Vortec 6.0L - Engine Problems Unknown: Gas- Battery: Yes - RUNS - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 05/19 - Approx. Mileage Reads: 86,942 - **Actual Mileage Unknown** - Interior Condition: Fair - Interior Problems: Torn Seats, Driver Side Door Panel Damaged, Needs Cleaning, Worn Steering Wheel - Body Condition: Fair - Body Problems: Crack In Windshield, Peeling Paint, Rust, Scratches, Back Bumper Dented - Tires Condition: Fair - Tires Problems: Unknown - Protection Cage - Rack On Top Of Unit</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |

| | | |
|--|-----------|---|
|  | <p>23</p> | <p>DOES NOT START - Unit # 1862 - Passengers: 2 - Engine Size/Type: Vortec 5.7L - Engine Problems: Does Not Start, Battery Cable Is Cut - Gas - Battery: Yes - Automatic Transmission - Hydraulic Brakes - Inspection Sticker Date: 03/20 - Approx. Mileage Reads: Unknown, Battery Is Dead - Interior Contrition: Fair - Interior Problems: Torn Seat, Driver Side Door Panel Is Missing Parts - Body Condition: Fair - Body Problems: Peeling Paint, Dent On Passenger Side Middle Doors & Behind Middle Doors, Dent On Back Door, Rust, Window Tint Is Peeling, Scratches - Tires Condition: Fair - Tires Problems: Unknown - Shop Made Cabinet In Cargo Area</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>24</p> | <p>Unit # 1573 - Passengers: 2 - Engine Size/Type: DT 466 - Engine Problems Unknown - Diesel - Battery: Yes - RUNS - Automatic Transmission - Air Brakes - Inspection Sticker Date: 05/19 - Approx. Mileage Reads: 32,942 - **Actual Mileage Unknown ** - Interior Condition: Fair - Interior Problems: Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint - Box MFG: Supreme Corp - Box Measures Approx. 24' 2" - No Lift Gate - Has Aluminum Ramp - Large Diesel Gas Tank</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |
|  | <p>25</p> | <p>Unit # 1587 - Passengers: 2 - Engine Size/Type: DT466 - Engine Problems: Unknown - Diesel - Battery: Yes - RUNS - Automatic Transmission - Air Brakes - Inspection Sticker Date: 11/19 - Approx. Mileage Reads: 12,508 - **Actual Mileage Unknown ** - Interior Condition: Fair - Interior Problems: Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint - Box MFG: Supreme Box - Tires Condition: Fair - Tires Problems: Unknown - Heavy Duty Lift Gate, MFG: Maxon, Condition Unknown</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p> |