

Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>**All purchases will be subject to a 14% buyer's premium. Buyer's Will Pay A 3% Convenience Fee For Credit Card Purchases**</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Wednesday, February 19, 2020 (Hours Of Operation: 8:00 a.m. - 4:00 p.m.)</p> <p>Location 1: (Lots 1, 2, & 5) Port Aransas ISD, 100 South Station St, Port Aransas TX 78373 Located on parking lot in front of the Softball Field Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, February 25, 2020 /Wednesday, February 26, 2020/Thursday, February 27, 2020 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.)</p> <p>Preview & Removal Contact: Pete Cowen, Office:361-749-1221 (leave a message) (Hours Of Operation: 8:00 a.m. - 4:00 p.m. Monday - Friday)</p> <p>All buses are drivable. Some shop equipment will take a forklift to place in the back of a truck. District cannot supply the loading equipment.</p> <p>Location 2: (Lot 7) Port Aransas ISD, 100 South Station St, Port Aransas TX 78373 Located in parking lot between Admin Building & Elementary School Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, February 25, 2020 /Wednesday, February 26, 2020/Thursday, February 27, 2020 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.)</p> <p>Preview & Removal Contact: Pete Cowen, Office:361-749-1221 (leave a message) (Hours Of Operation: 8:00 a.m. - 4:00 p.m. Monday - Friday)</p> <p>Van has to be towed. Will only drive in reverse.</p> <p>Location 3: (Lots 8-12) Port Aransas ISD, 100 South Station St, Port Aransas TX 78373 Equipment in PA High School HS CTE Shop behind the administration building Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Tuesday, February 25, 2020 /Wednesday, February 26, 2020/Thursday, February 27, 2020 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.)</p> <p>Preview & Removal Contact: Pete Cowen, Office:361-749-1221 or Ryan Piwetz 361-749-1419 or 361-749-1317 (leave a message) (Hours Of Operation: 8:00 a.m. - 4:00 p.m. Monday - Friday)</p> <p>Call to set up an appointment for pick up. The students have class in the Innovation Lab so equipment can be placed outside garage door for pickup. Items will be outside (in front of garage door) for Preview on Wednesday, February 19, 2020.</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	
1	(1) 2001 International 3800 Vin #3626	<p>Unit #68 - Passenger: 71 - Engine Size/Type - T444E/7.3L Diesel 6 Cylinder - Engine Problems: Power Steering Pump Not Functional - Diesel - Battery Does Not Work - Runs - Automatic - Brakes: Air - Inspection Sticker Date: October 2019 - Mileage: (Approx.) 161,317 - Interior Condition: Unknown - Interior Problems: Needs Cleaning - Body Condition: Unknown - Body Problems: Minor Scratches, Paint Faded & Peeling - Tire Condition: Unknown - Tire Problems: - Unknown</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed,</p> <p>- Current Condition Unknown</p>	

2	(1) 1990 BlueBird Transit Bus TL/2000 Vin #6354	<p>Unit #72 - Passenger: 71 - Engine Size/Type: Cummins 5.91 6 cylinder - Engine Problems: Minor Coolant Leak - Diesel - Battery Works - Runs - Automatic - Brakes: Air - Inspection Sticker Date: January 2020 - Mileage: (Approx.) 188,312 - Interior Condition: Unknown - Interior Problems: Needs Cleaning - Body Condition: Unknown - Body Problems: Rust & Minor Fading - Tires condition: Unknown - Tire Problems: Unknown</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
5	(1) 2009 Freightliner Thomas C2 Vin #4614	<p>Unit #75 - Passenger: 71 - Engine Size/Type: Cummins 6.7L Diesel 6 Cylinder - Engine Problems: Oil & Transmission Leaks - Diesel - Battery Works - Runs - Automatic - Brakes: Air - Inspection Sticker Month: June 2020 - Mileage: (Approx.) 115,469 - Interior Condition: Unknown - Interior Problems: Needs Cleaning - Body Condition: Unknown - Body Problems: Minor Scratches & Paint Fading - Tires condition: Unknown - Tire Problems: Unknown</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
7	(1) 2004 Ford Freestar Vin #1915 - Needs To Be Towed	<p>Needs To Be Towed - Cafe Van - Conventional - Engine Size/Type: 3.9L 6 cylinder - Engine Problems: Unknown, When Last Used Everything Was Good - Gas - Battery Does Not Work, Dead - Does Not Run - Transmission Type or Condition: No Reverse - Brakes: Hydraulic - Inspection Sticker Date: April 2019 - Mileage: Unknown - Interior Condition: Unknown - Interior Problems: All Seats Have Been Removed, Passenger Seats Are Dirty - Body Condition: Unknown - Body Problems: Rust Above Front Windshield - Tires Condition: Unknown - Tire Problems: Unknown</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed,</p> <p>- Current Condition Unknown</p>	
8	(1) Miter Saw	<p>DeWalt DW708 (Approx. 12"), Sliding Compound, Saw Works And Is Operational, Has A Broken Handle At Trigger</p> <p>- Current Condition Unknown</p>	
9	(1) Plasma Cutter	<p>Lincoln Cutting Systems, Torchmate 4X4 Growth Series, Does Not Operate, Accumove Controller Inoperable, Controller Was Sent Off To Confirm That It Was Broken, It Was Confirmed By Technicians, Controller Is Not In Our Possession</p> <p>- Current Condition Unknown</p>	
10	(1) Bench Grinder & Stand	<p>Porter Cable (Approx. 8"), Operates, Missing Safety Guards & Guides, Broken Light Fixture</p> <p>- Current Condition Unknown</p>	

11	(Lot) Air Ventilation Unit	(Approx. 2) Smookeeter Model CC-SABIS-M-WM, Both Units Operate - Current Condition Unknown	
12	(1) Table Saw	Rigid, Operates & Is Functional - Current Condition Unknown	