













Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p><b>IMPORTANT NOTICE FOR CY-FAIR ISD: **All purchases will be subject to a 13% buyer's premium.**</b></p> <p><b>*Social distancing will be enforced</b></p> <p><b>*Customers will not be allowed inside to use the restrooms. No Exceptions!</b></p> <p><b>*Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled.</b></p> <p><b>*We recommend wearing gloves and face mask for personal safety and health while on auction location.</b></p> <p><b>Preview:</b> (By Appointment Only – No Exceptions) Tuesday, June 16, 2020(Hours Of Operation: 8:00 a.m. - 1:00 p.m.)</p> <p><b>Location:</b> CyFair ISD Exhibit Center, 11206 Telge Rd., Cypress, TX 77429 <a href="#">Driving Directions</a></p> <p><b>Removal:</b> (By Appointment Only – No Exceptions) Monday, June 22, 2020 /Tuesday, June 23, 2020/Wednesday, June 24, 2020/Thursday, June 25, 2020 /Friday, June 26, 2020 (Hours of Operation: 8:00 a.m. - 12:00 p.m.)</p> <p><b>Removal Contact:</b> Kristi Giron, 281-517-6366 email: <a href="mailto:kristi.giron@cfisd.net">kristi.giron@cfisd.net</a></p> <p><b>Forklift Will Be Available For Removal. No Cash Payments Accepted On Site.</b></p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. <b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p>	
1	(1) 2000 International Bus Vin #5501	<p>Unit #754  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: August 2020  Approx. Mileage (NOT ACTUAL): 11,524  Interior Condition: Fair  Interior Problems: Torn Drivers Seat  Body Condition: Fair  Body Problems: Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. <b>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</b></p> <p>- Current Condition Unknown</p>	



2	(1) 1998 International Bus Vin #1468	<p>Unit #691  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Runs  Automatic  Brakes: Air  Inspection Sticker Month: October 2020  Approx. Mileage (NOT ACTUAL): 10,521  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Fair  Body Problems: Some Dents &amp; Scratches Oxidized Paint  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
3	(1) 1998 International Bus Vin #1475	<p>Unit #689  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: N/A  Approx. Mileage (NOT ACTUAL): 10,316  Interior Condition: Fair  Interior Problems: Needs Cleaning - Torn Drivers Seat  Body Condition: Fair  Body Problems: Some Peeling Paint Dent On Passenger Side Bumper Behind Wheel Well Some Rust &amp; Scratches  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

4	(1) 1998 International Bus Vin #1489	<p>Unit #704  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: October 2021  Approx. Mileage (NOT ACTUAL): 11,871  Interior Condition: Fair  Interior Problems: Needs Cleaning - Torn Drivers Seat  Body Condition: Fair  Body Problems: Oxidized paint Dent On Passenger Side Above Tail Light Dented Bumper Drivers Side Back Bumper Below Taillight  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
5	(1) 1998 International Bus Vin #1469	<p>Unit #693  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: N/A  Approx. Mileage (NOT ACTUAL): 10,025  Interior Condition: Fair  Interior Problems: Needs Cleaning - Torn Drivers Seat  Body Condition: Fair  Body Problems: Peeling &amp; Oxidized Paint - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



6	(1) 1997 International Bus Vin #9779	<p>Unit #659  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: January 2021  Approx. Mileage (NOT ACTUAL): 17,967  Interior Condition: Fair  Interior Problems: Needs Cleaning - Torn Drivers Seat  Body Condition: Fair  Body Problems: Oxidized &amp; Peeling Paint Some Scratches, Dents &amp; Rust Dent On Back Bumper  Scratches Below Last Window On Drivers Side  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
7	(1) 1997 International Bus Vin #9780	<p>Unit #658  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: January 2020  Approx. Mileage (NOT ACTUAL): 20,011  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

8	(1) 1997 International Bus Vin #9775	<p>Unit #664  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: January 2021  Approx. Mileage (NOT ACTUAL): 18,503  Interior Condition: Fair  Interior Problems: Torn Drivers Seat  Body Condition: Fair  Body Problems: Oxidized Paint Some Peeling Paint - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
9	(1) 1997 International Bus Vin #9781	<p>Unit #656  Passenger: 28  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: August 2019  Approx. Mileage (NOT ACTUAL): 20,803  Interior Condition: Fair  Interior Problems: Torn Drivers Seat Needs Cleaning Missing Seats In Back Of Bus  Body Condition: Fair  Body Problems: Some Dents, Scratches &amp; Rust Oxidized Paint Rust On Back Bumper  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



10	(1) 2000 International Bus Vin #5497	<p>Unit #731  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 131,920  Interior Condition: Fair  Interior Problems: Needs Cleaning Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust Dent On Back Passenger Side Wheel Well  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
11	(1) 1998 International Bus Vin #1477	<p>Unit #687  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 11,524  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust Peeling Paint  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



12	(1) 2000 International Bus Vin #5516	<p>Unit #734  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: April 2020  Approx. Mileage (NOT ACTUAL): 166,811  Interior Condition: Fair  Interior Problems: Torn Drivers Seat Some Soft Spots In Floor  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
13	(1) 1998 International Bus Vin #1478	<p>Unit #688  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: March 2021  Approx. Mileage (NOT ACTUAL): 149,869  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust Peeling Paint Dents On Back Bumper  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	







14	(1) 2000 International Bus Vin #0157	<p>Unit #782  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: July 2020  Approx. Mileage (NOT ACTUAL): 151,792  Interior Condition: Fair  Interior Problems: Torn Drivers Seat Needs Cleaning Some Torn Back Seats Sign Missing Above Door Inside  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust Dent In Back Bumper On Passenger Side &amp; Drivers Side  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
15	(1) 2005 IC Bus Vin #5816	<p>Unit #928  Passenger: 71  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: October 2020  Approx. Mileage (NOT ACTUAL): 129,596  Interior Condition: Fair  Interior Problems: Some Torn Seats Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	







16	(1) 2000 International Bus Vin #0149	<p>Unit #809  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: March 2021  Approx. Mileage (NOT ACTUAL): 159,998  Interior Condition: Fair  Interior Problems: Needs Cleaning Floor Has Soft Spot In Front By Drivers Seat &amp; In Back Of Bus  Some Seats Are Fading In Color  Body Condition: Fair  Body Problems: Dent In Back Bumper On Drivers &amp; Passenger Side - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
17	(1) 2005 IC Bus Vin #5831	<p>Unit #904  Passenger: 71  Engine Size/Type: C300  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: August 2020  Approx. Mileage (NOT ACTUAL): 159,006  Interior Condition: Fair  Interior Problems: Needs Cleaning Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



18	(1) 2005 IC Bus Vin #5818	<p>Unit #914  Passenger: 71  Engine Size/Type: C300  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 173,169  Interior Condition: Fair  Interior Problems: Seats Need Deep Cleaning Some Torn Seats  Body Condition: Fair  Body Problems: Some Dents, Scratches &amp; Rust Piece Missing On Back Bumper Rust On Bumper On Passenger Side Oxidized Paint -  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
19	(1) 2000 International Bus Vin #0136	<p>Unit #811  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 145,273  Interior Condition: Fair  Interior Problems: Seats Need Deep Cleaning  Body Condition: Fair  Body Problems: Oxidized paint Dent In Back Bumper On Passenger &amp; Drivers Side  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

20	(1) 1998 International Bus Vin #1492	<p>Unit #677E  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: March 2021  Approx. Mileage (NOT ACTUAL): 11,524  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
21	(1) 2002 International Bus Vin #6848	<p>Unit #870  Passenger: 71  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 11,524  Interior Condition: Fair  Interior Problems: Glass Cracked On Entry Door Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



22	(1) 1998 International Bus Vin #1501	<p>Unit #686  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: August 2020  Approx. Mileage (NOT ACTUAL): 146,255  Interior Condition: Fair  Interior Problems: Needs Cleaning Some Seats Faded  Body Condition: Fair  Body Problems: Oxidized Paint Rust On Bumper - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
23	(1) 1997 International Bus Vin #9790	<p>Unit #665  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: November 2020  Approx. Mileage (NOT ACTUAL): 134,413  Interior Condition: Fair  Interior Problems: Some Rust On Front Floor Board By Drivers Seat Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint Rust On Rear Bumper - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



24	(1) 2002 International Bus Vin #6861	<p>Unit #850  Passenger: 71  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: January 2020  Approx. Mileage (NOT ACTUAL): 11,992  Interior Condition: Fair  Interior Problems: Torn Drivers Seat Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
25	(1) 2000 International Bus Vin #5514	<p>Unit #729  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Runs  Automatic  Brakes: Air  Inspection Sticker Month: March 2021  Approx. Mileage (NOT ACTUAL): 168,522  Interior Condition: Fair  Interior Problems: Small Tear In Drivers Seat Seats Need Deep Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint Peeling Paint On Hood - Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tires Problem: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



26	(1) 2001 International Blue Bird Vin #0202	<p>Unit #889  Passenger: 36  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown: See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: May 2020  Approx. Mileage (NOT ACTUAL): 156,245  Interior Condition: Fair  Interior Problems: Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches  Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
27	(1) 2001 International Blue Bird Vin #0201	<p>Unit #888  Passenger: 36  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: January 2021  Approx. Mileage (NOT ACTUAL): 163,861  Interior Condition: Fair  Interior Problems: Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches  Tires Condition: Good to Poor  Tires Problem: All Tires Are Good Except Front Left Is Poor</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



28	(1) 2001 International Blue Bird Vin #0195	<p>Unit #885  Passenger: 36  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown: See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: January 2021  Approx. Mileage (NOT ACTUAL): 164,661  Interior Condition: Fair  Interior Problems: Normal Wear  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches Slight Dent In Rear Bumper  Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
29	(1) 2001 International Blue Bird Vin #0189	<p>Unit #893  Passenger: 16 + 2 Wheelchair  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown: See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: April 2020  Approx. Mileage (NOT ACTUAL): 203,464  Wheel Chair Lift: Yes Condition: Unknown  Interior Condition: Fair  Interior Problems: Torn Drivers Seat  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches Rock Chip On Windshield  Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	







30	(1) 2001 International Blue Bird Vin #0191	<p>Unit #897  Passenger: 16 + 2 Wheelchair  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown: See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: April 2020  Approx. Mileage (NOT ACTUAL): 156,245  Interior Condition: Fair  Interior Problems: Torn Drivers Seat Passenger Seats Normal Wear  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches Dent On Left Rear Corner Rock Chip On Windshield  Tires Condition: Fair to Poor  Tire Problems: Rear Right Are Overstuffed Remaining Tires: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
31	(1) 2008 International Bus Vin #1439	<p>Unit #1088  Passenger: 25 + 2 Wheelchair  Engine Size/Type: Maxx Force DT/PB10500  Engine In Front  Engine Problems: Unknown: See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 114,491  Interior Condition: Fair  Interior Problems: Normal Wear Some Repaired Tears Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches  Tires Condition: Fair to Poor  Tire Problems: Unknown  Additional Information: A/C Is Cold</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



32	(1) 2008 International Bus Vin #1444	<p>Unit #1086  Passenger: 25 + 2 Wheelchair  Engine Size/Type: Maxx Force DT  Engine In Front  Engine Problems: Unknown: See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: N/A  Approx. Mileage (NOT ACTUAL): 14,532  Wheelchair Lift: Yes Condition: Unknown  Interior Condition: Fair  Interior Problems: Normal Wear  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
33	(1) 2000 International Bus Vin #4327	<p>Unit #821  Passenger: 16 + 3 Wheelchair  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown: See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: February 2021  Approx. Mileage (NOT ACTUAL): 184,582 (Looks Damaged; May Not Work)  Wheelchair Lift: Yes Condition: Unknown  Interior Condition: Fair  Interior Problems: Normal Wear Some Tears  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches Peeling On Cowl &amp; Hood Rock Chip On Windshield  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

34	(1) 2000 International Blue Bird Vin #4328	<p>Unit #823  Passenger: 16 + 3 Wheelchair  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown: See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: February 2021  Approx. Mileage (NOT ACTUAL): 214,111  Wheelchair Lift: Yes Condition: Unknown  Interior Condition: Fair  Interior Problems: Normal Wear  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches Peel On Cowl &amp; Hood  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
35	(1) 2000 International Blue Bird Vin #4329	<p>Unit #824  Passenger: 16 + 3 Wheelchair  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown: See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: February 2021  Approx. Mileage (NOT ACTUAL): 202,217  Wheelchair Lift: Yes Condition: Unknown  Interior Condition: Fair  Interior Problems: Normal Wear  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches Peel On Cowl &amp; Hood Rock Chip On Front Windshield  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



36	(1) 2001 International Blue Bird Vin #0194	<p>Unit #884  Passenger: 36  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown: See Video  Diesel  Has Battery, Dead  Runs  Automatic  Brakes: Air  Inspection Sticker Month: April 2020  Approx. Mileage (NOT ACTUAL): 151,002  Interior Condition: Fair  Interior Problems: Normal Wear Drivers Seat Torn  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches Peel On Cowl &amp; Hood  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
37	(1) 2002 International Bus Vin #6877 - Needs To Be Towed	<p>Needs To Be Towed  Unit #848  Passenger: 71  Engine Problems: Unknown  Diesel  Has Battery  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 148,401  Interior Condition: Fair  Interior Problems: Needs Cleaning Some Seats Torn Slight Tear On Drivers Seat  Body Condition: Fair  Body Problems: Peeling &amp; Oxidized Paint Some Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



38	(1) 2000 International Thomas Bus Vin #0141 - Needs To Be Towed	<p>Needs To Be Towed  Unit #783  Passenger: 71  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 146,174  Interior Condition: Fair to Poor  Interior Problems: Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches Peel On Cowl &amp; Hood Missing Front Mirrors  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
39	(1) 2000 International Thomas Bus Vin #0148 - Needs To Be Towed	<p>Needs To Be Towed  Unit #812  Passenger: 71  Engine Size/Type: DT466E  Engine In Front  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Month: February 2019  Approx. Mileage (NOT ACTUAL): 181,030  Interior Condition: Fair  Interior Problems: Normal Wear &amp; Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches (1) Rear Light Missing Some Peeling On Hood  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



40	(1) 2006 International Bus Vin #9821 - Needs To Be Towed	<p>Needs To Be Towed  Unit #938  Passenger: 71  Engine In Front  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Month: August 2020  Approx. Mileage (NOT ACTUAL): Unable To Read Due To Dead Battery  Interior Condition: Fair  Interior Problems: Normal Wear - Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
41	(1) 2002 IC Bus Vin #9830 - Needs To Be Towed	<p>Needs To Be Towed  Unit #965  Passenger: 71  Engine Size/Type: CE300  Engine In Front  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 141,072  Interior Condition: Fair  Interior Problems: Needs Cleaning Some Torn Seats  Body Condition: Fair  Body Problems: Peeling Paint Some Dents, Scratches &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



42	(1) 2006 International Bus Vin #9822 - Needs To Be Towed	<p>Needs To Be Towed  Unit #939  Passenger: 71  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Month: N/A  Approx. Mileage (NOT ACTUAL): Not Available Dash Removed  Interior Condition: Fair  Interior Problems: Normal Wear Some Torn Seats  Body Condition: Fair  Body Problems: Some Peeling From Decal Removal Surface Scratches Rock Chip On Windshield  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
43	(1) 1998 International Bus Vin #1476 - Needs To Be Towed	<p>Needs To Be Towed  Unit #692  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine In Front  Engine Problems: Unknown  Diesel  Has Battery  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 154,890  Interior Condition: Fair  Interior Problems: Torn Drivers Seat Needs Cleaning Seat Color Fading  Body Condition: Fair  Body Problems: Oxidized Paint Some Dents, Scratches &amp; Rust Peeling Paint  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	







44	(1) 2002 International Bus Vin #6843 - Needs To Be Towed	<p>Needs To Be Towed  Unit #856  Passenger: 71  Engine In Front  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Month: February 2020  Approx. Mileage (NOT ACTUAL): 144,777  Interior Condition: Fair  Interior Problems: Normal Wear Some Torn Seats  Body Condition: Fair  Body Problems: Oxidized Paint Surface Scratches  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
45	(1) 1998 International Bus Vin #1479 - Needs To Be Towed	<p>Needs To Be Towed  Unit #699  Passenger: 71  Engine Size/Type: 3800 DT466E  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Month: December 2020  Approx. Mileage (NOT ACTUAL): 154,890  Interior Condition: Fair  Interior Problems: Torn Drivers Seat Seats Fading Color  Body Condition: Fair  Body Problems: Oxidized Paint Some Dents, Scratches &amp; Rust Scratch On Back Under Last Window On Passenger Side Rust On Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



46	(1) 2005 International Bus Vin #5834 - Needs To Be Towed	<p>Needs To Be Towed  Unit #902  Passenger: 71  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Month: August 2019  Approx. Mileage (NOT ACTUAL): Not Able To Read; Dead Battery  Interior Condition: Fair  Interior Problems: Some Torn Seats Needs Cleaning Normal Wear  Body Condition: Fair  Body Problems: Surface Scratches  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
47	(1) 2002 International Bus Vin #6872 - Needs To Be Towed	<p>Needs To Be Towed  Unit #843  Passenger: 71  Engine In Front  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Inspection Sticker Month: December 2019  Approx. Mileage (NOT ACTUAL): 175,193  Interior Condition: Fair  Interior Problems: Some Torn Seats Needs Cleaning  Body Condition: Fair  Body Problems: Oxidized Paint Some Scratches, Dents &amp; Rust Rust On Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

48	(1) 2005 International Bus Vin #5819 - Needs To Be Towed	<p>Needs To Be Towed  Unit #907  Passenger: 71  Engine In Front  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Inspection Sticker Month: August 2019  Approx. Mileage (NOT ACTUAL): Unable To Read, Dead Battery  Interior Condition: Fair  Interior Problems: Normal Wear Some Torn Seats  Body Condition: Fair  Body Problems: Surface Scratches Hood Is Oxidized  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
49	(1) 2001 International Bus Vin #0184 - Needs To Be Towed	<p>Needs To Be Towed  Unit #890  Passenger: 13  Engine Size/Type: 3800 DT466E  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Brakes: Air  Inspection Sticker Month: April 2020  Approx. Mileage (NOT ACTUAL): 182,451  Wheel Chair Lift: Yes Condition: Unknown  Interior Condition: Fair  Interior Problems: Torn Drivers Seat Seats Need Deep Cleaning Missing Hatch In Back, Open To Weather  Body Condition: Fair  Body Problems: Oxidized Paint Some Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	


50	(1) 2014 IC Bus Vin #9302 - Needs To Be Towed	<p>Needs To Be Towed  Unit #6206  Passenger: 22  Engine Problems: Unknown  Diesel  No Battery  Does Not Run  Automatic  Inspection Sticker Month: April 2020  Approx. Mileage (NOT ACTUAL): Unknown, Dead Battery  Wheel Chair Lift: Yes Condition: Unknown  Interior Condition: Fair  Interior Problems: Some Torn Seats In Back Needs Cleaning  Body Condition: Fair  Body Problems: Some Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
51	(1) 2006 Chevy Van 3500 Vin #2599	<p>Unit #1869  Passenger: 2  Engine Size/Type: Vortec 6.0  Engine Problems: Unknown  Gas  Has Battery  Runs  Automatic  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 84,561  Interior Condition: Fair  Interior Problems: Torn Drivers Seat Needs Cleaning Headliner Needs To Be Replaced  Body Condition: Fair  Body Problems: Peeling Paint Scratches, Dents &amp; Rust Paint On Bumper  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Works Protection Cage Cabinet In Cargo Area Rack On Top</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

52	(1) 2007 Chevy Van Vin #9640	<p>Unit #1883  Passenger: 2  Engine Problems: Unknown  Gas  Has Battery  Runs  Automatic  Inspection Sticker Month: January 2020  Approx. Mileage (NOT ACTUAL): 73,012  Interior Condition: Fair  Interior Problems: Torn Seats Needs Cleaning Headliner Needs To Be Replaced  Body Condition: Fair  Body Problems: Unknown  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: Protection Cage Cabinet In Cargo Area Rack On Top</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
53	(1) 1993 Chevy Beauville Van Vin #2307	<p>Unit #1431  Passenger: 11  Engine Problems: Unknown  Gas  Has Battery  Runs  Automatic  Inspection Sticker Month: April 2020  Approx. Mileage (NOT ACTUAL): 110,583  Interior Condition: Fair  Interior Problems: Parts Of Dash Are Missing Underneath Torn Seats Needs Cleaning Headliner Is Loose  Body Condition: Fair  Body Problems: Unknown  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: A/C Works</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

54	(1) 2006 Chevy Van 3500 Vin #5533	<p>Unit #1873  Passenger: 2  Engine Size/Type: Vortec 6.0  Engine In Front  Engine Problems: Unknown  Gas  Has Battery  Runs  Automatic  Inspection Sticker Month: August 2020  Approx. Mileage (NOT ACTUAL): 73,824  Interior Condition: Fair  Interior Problems: Torn Seats Needs Cleaning  Body Condition: Fair  Body Problems: Peeling Paint Dent &amp; Rust On Passenger Middle Door Dent On Passenger Side Behind Wheel Well Paint On Rear Bumper Some Scratches &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown  Additional Information: Protection Cage Cabinet In Cargo Area Rack On Top</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
55	(1) 1998 Chevy Van Vin #2551 - Needs To Be Towed	<p>Needs To Be Towed  Unit #1821  Passenger: 2  Engine Size/Type: Vortec 5.7L  Engine Problems: Unknown  Gas  Has Battery, Dead  Does Not Run  Automatic  Inspection Sticker Month: May 2020  Approx. Mileage (NOT ACTUAL): Unknown, Dead Battery  Interior Condition: Fair  Interior Problems: Needs Cleaning Middle Seats Laying IN Cargo Area  Body Condition: Fair  Body Problems: Some Scratches, Dents &amp; Rust  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

56	(1) 1999 Chevy Pickup 3500 Vin #6533	<p>Unit #1307  Passenger: 4  Engine Problems: Knocking When Running  Gas  Has Battery  Runs  Automatic  Inspection Sticker Month: March 2020  Approx. Mileage (NOT ACTUAL): 105,555  Interior Condition: Fair  Interior Problems: Needs Cleaning Some Seatbelt Buckles Missing  Body Condition: Fair  Body Problems: Loose door Handle On Drivers Side Peeling Paint Piece Loose On Passenger Side  Wheel Well Scratches, Dents &amp; Rust Paint On Back Bumper  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
57	(1) 2008 Ford Crown Victoria Vin #5759	<p>Unit #4073  Passenger: 4  Engine In Front  Engine Problems: Unknown  Gas  Has Battery  Runs  Automatic  Inspection Sticker Month: October 2019  Approx. Mileage (NOT ACTUAL): 80,611  Interior Condition: Fair  Interior Problems: Needs Cleaning  Body Condition: Fair  Body Problems: Peeling Paint Some Scratches  Tires Condition: Fair  Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.  **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer.  Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



58	(1) 2013 Ford 4 Door Vin #4717 - Needs To Be Towed	<p>Needs To Be Towed Unit #4003 Passenger: 4 Engine Problems: Unknown Gas Has Battery, Dead Does Not Run Automatic Inspection Sticker Month: February 2019 Approx. Mileage (NOT ACTUAL): Unknown, Dead Battery Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Some Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
59	(1) 2008 Ford Crown Victoria Vin #9716	<p>Unit #4025 Passenger: 4 Engine Problems: Unknown Gas Has Battery Runs Automatic Inspection Sticker Month: March 2020 Approx. Mileage (NOT ACTUAL): 84,793 Interior Condition: Fair Interior Problems: Needs Cleaning - Center Console Missing Steering Wheel Column Cover Missing Body Condition: Fair Body Problems: Some Scratches &amp; Dents Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	