Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	**All purchases will be subject to a 13% buyer's premium.** Preview: (By Appointment Only-Mandatory-No Exceptions) Monday. March 23. 2020 (Hours Of Operation: Monday-Thursday 8:00 a.m 4:30 p.m. Friday 8:00a.m 2:00 p. m.) Location: 400 Park Street, Canton, TX 75103 (Located Behind School Building) Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Thursday, March 26, 2020 /Friday. March 27. 2020/Monday. March 30.2020 (Hours Of Operation: Monday-Thursday 8:00 a.m 4:30 p.m. Friday 8:00a.m 2:00 p.m.) Removal Contact: Denise Stone (903) 567-4179 Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	Read Me
1	(1) 1991 Ford Pickup F250 Vin #1232 - Needs To Be Towed	Needs To Be Towed - Unit #MD1 - Engine Problems: Missing Parts - Gas - Battery: Dead - Does Not Run - Automatic - Brakes: Hydraulic - Inspection Sticker Month: Unknown - Mileage NOT ACTUAL 94,146 - Interior Condition: Poor - Body Condition: Poor - Tires Condition: Fair Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown	
2	(1) 1996 International Bus Vin #6436 - Needs To Be Towed	Needs To Be Towed - Unit #16 - Conventional Type - Passenger: 77 - Engine Size/Type: 7.3, T444E - Engine In Front - Engine Problems: Damaged In A Wreck - Diesel - Battery: Dead - Does Not Run - Automatic - Transmission Condition: Good - Brakes: Air - Inspection Sticker Date: Unknown - Mileage NOT ACTUAL 144,394 - Interior Condition: Fair - Body Condition: Poor - Body Problems: Wrecked - Tires Condition: Poor - Tire Problems: Cracking Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown	

(1) 1997 International Bus Handicap Vin #9719 - Needs To Be Towed	Needs To Be Towed - Unit #M4 - Conventional Type - Passenger: 12 - Engine Size/Type: 7.3, T444E - Engine In Front - engine Problems: Unknown - Diesel - Does Not Have Battery, Dead - Does Not Run - Automatic - Transmission Type Or Condition: Unknown - Brakes: Hydraulic - Inspection Sticker Month: Unknown - Mileage NOT ACTUAL 153,147 - Has Wheel Chair Lift, Condition Unknown - Interior Condition: Poor - Interior Problems: Torn Seats, Holes In Floor, Needs Cleaning - Body Condition: Fair - Body Problems: Dents, Scratches - Tires Condition: Fair - Tire Problems: Does Not Hold Air Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown	
(1) 1997 International Bus Vin #9718 - Needs To Be Towed	Engine In Front - Engine Problems: Unknown - Diesel - Battery: Dead - Automatic - Transmission Condition: Unknown - Brakes: Air - Inspection Sticker Month: Unknown - Mileage: NOT ACTUAL 150,415 - Interior Condition: Fair - Interior Problems: Torn Seats, Holes, Rust - Body Condition: Fair - Dents & Scratches, Broken Lights, Missing Parts - Tires Condition: Fair - Tire Problems: Out Of Date Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown	
(1) 1992 Chevy Van Vin #8598 - Needs To Be Towed	Needs To Be Towed - Unit #M2 - Passenger: 15 - Engine Size/Type: 5.7, Chevy - Engine In Front - Engine Problems: Unknown - Gas - Battery: Dead - Does Not Run - Transmission Condition: Bad - Brakes: Hydraulic - Inspection Sticker Date: Unknown - Mileage NOT ACTUAL 196,977 - Interior Condition: Poor - Interior Problems: Torn Seats, Bad Floor - Body Condition: Fair - Body Problems: Scratches, Dents, Poor Paint - Tires Condition: Fair - Tire Problems: Does Not Hold Air Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown	
	International Bus Handicap Vin #9719 - Needs To Be Towed (1) 1997 International Bus Vin #9718 - Needs To Be Towed (1) 1992 Chevy Van Vin #8598 - Needs To Be Needs To Be	- Engine In Front - Engine Problems: Unknown - Diesel - Does Not Have Battery, Dead - Does Not Bare. Automatic - Transmission Type Or Condition: Unknown - Brakes: Hydraulic - Inspection Sticker Month: Unknown - Mileage NOT ACTUAL 153,147 - Has Wheel Chair Lift, Condition Unknown - Interior Condition: Poor - Interior Problems: Torn Seats, Holes In Floor, Needs Cleaning - Body Condition: Fair - Body Problems: Dents, Scratches - Tires Condition: Fair - Tire Problems: Does Not Hold Air Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed Handicap Vin #9719 - Needs To Be Towed Bowel Be - *All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown Needs To Be Towed - Unit #3 - Conventional Type - Passenger: 77 - Engine Size/Type - 7.9, T444E - Current Condition: Unknown - Brakes: Air - Inspection Sticker Month: Unknown - Mileage: NOT ACTUAL 150,415 - Interior Condition: Tair - Interior Problems: Torn Seats, Holes, Rust-Body Condition: Fair - Deats & Scratches, Broken Lights, Missing Parts - Tires Condition: Fair - Tire Problems: On Seats, Holes, Rust-Body Condition: Fair - Deats & Scratches, Broken Lights, Missing Parts - Tires Condition: Fair - Tire Problems: On Seats, Holes, Rust-Body Condition: Fair - Deats & Scratches, Broken Lights, Missing Parts - Tires Condition: Fair - Tire Problems: On Seats, Holes, Rust-Body Condition: Fair - To Bet Vehicle Started And/Or Removed 11 1997 Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own

6	(1) 1995 Ford Bus Vin #7267 - Needs To Be Towed	Needs To Be Towed - Unit #19 - Passenger: 77 - Conventional Type - Engine Size/Type: 5.9, Cummins - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Dead - Does Not Run - Automatic - Transmission Condition: Unknown - Brakes: Air - Inspection Sticker Month: Unknown - Mileage: NOT ACTUAL 6,937 - Interior Condition: Poor - Interior Problems: Torn Seats, Holes - Body Condition: Poor - Body Problems: Dents, Missing Parts - Tires condition: Poor - Tire Problems: Out Of Date Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**	
		- Current Condition Unknown	
7	(1) 1992 International Bus Vin #7169 - Needs To Be Towed	Needs to Be Towed - Unit #25 - Conventional Style - Passenger: 77 - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Dead - Does Not Run - Automatic - Transmission Condition: Unknown - Brakes: Air - Inspection Sticker Month: Unknown - Mileage: NOT ACTUAL 157,292 - Interior Condition: Fair - Interior Problems: Bad - Body Condition: Fair - Body Problems: Dents - Tires Condition: Fair - Tire Problems: Out Of Date - Additional Problems: Parts Missing Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown	
8	(1) 1992 International Bus Vin #7168 - Needs To Be Towed	Needs to Be Towed - Unit #18 - Conventional Style - Passenger: 77 - Engine Size: 7.3 - Engine In Front - Engine Problems: Unknown - Diesel - Battery: Dead - Does Not Run - Automatic - Transmission Condition: Unknown - Brakes: Unknown - Inspection Sticker Month: Unknown - Mileage: NOT ACTUAL 176,446 - Interior Condition: Poor - Interior Problems: torn Seats, Holes - Body Condition: Poor - Body Problems: Dents, Scratches - Tires Condition: Fair - Tire Problems: Out Of Date Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown	
	L	- Current Condition Onknown	<u> </u>

9	(1) 1987 Chevy Pickup Vin #1144 - Needs To Be Towed	Needs To Be Towed - Unit #MD12 - Passenger: 2 - Engine Size: 5.7 - Engine Problems: Unknown - Gas - Does Not Have Battery - Does Not Run - Automatic - Transmission Condition: Unknown - Brakes: Hydraulic - Inspection Sticker Month: Unknown - Mileage: NOT ACTUAL 39,235 - Interior Condition: Poor - Interior Problems: Rust, Body Damage - Body Condition: Poor - Body Problems: Dents - Tires Condition: Fair - Tire Problems: Low Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown	
10	(1) 1989 Chevy Truck Vin #5053 - Needs To Be Towed	Needs To Be Towed - Unit #MD5 - Engine Size: 5.7 - Engine Problems: Yes, Possible Head Gaskets - Gas - Does Not Have Battery - Does Not Run - Automatic - Transmission Condition: Unknown - Brakes: Hydraulic - Inspection Sticker Month: Unknown - Mileage: NOT ACTUAL 117,982 - Interior Condition: Poor - Interior Problems: Unknown - Body Condition: Poor - Body Problems: Unknown - Tires Condition: Fair - Tire Problems: Unknown Runs But Has Dead Battery - Winning Bidder Will Be Responsible For Bringing Own Battery, Equipment, Etc. To Get Vehicle Started And/Or Removed There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** - Current Condition Unknown	