

Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>IMPORTANT NOTICE FOR TYLER ISD AUCTION: **All purchases will be subject to a 14% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</p> <p>Preview: No Preview Available For This Auction</p> <p>Note: Prior To Bidding, Buyer Must Provide Lemons Auctioneers, LLP With Proper Funding Such As A Bank Letter Of Guarantee Or \$200 Charge On A Visa /MasterCard. Deposit Will Not Be Refunded To Buyer Until Removal Is Complete.</p> <p>Location 1 (Lots 1-18): Plyer TISD Complex, 807 W Glennwood Blvd., Tyler, TX 75701 Driving Directions</p> <p>Removal :(By Appointment Only-Mandatory-No Exceptions) Monday, May 11, 2020/Tuesday, May 12, 2020/Wednesday, May 13, 2020/Thursday, May 14, 2020 (Hours Of Operation: 10:00 a.m. – 2:00 p.m.)</p> <p>Preview & Removal Contact: Rita Taylor (903) 262-3188 email: rita.taylor@tylerisd.org</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>Location 2 (Lots 19-20):Tyler ISD Custodial Services, 2800 Walton Rd., Tyler, Tx 75701 Driving Directions</p> <p>Removal :(By Appointment Only-Mandatory-No Exceptions) Monday, April 9, 2018 - Friday, April 13, 2018 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.)</p> <p>Preview & Removal Contact: Rita Taylor (903) 262-3188 email: rita.taylor@tylerisd.org</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>*Social distancing will be enforced *Customers will not be allowed inside to use the restrooms. No Exceptions! *Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled. *We recommend wearing gloves and face mask for personal safety and health while on auction location.</p>	

1	(1) 2010 Ford 4Dr Crown Victoria Vin #5953	<p>Passenger: 5 - Engine Size: 4.6L - Engine Problems: Unknown, Light Hum Sound Noted When Engine Started, Goes Away After A Few Seconds - Gas - Has Battery, Dead - Runs - Automatic - Brakes: Hydraulic - Inspection Sticker Month: April 2020 - Approx. Mileage NOT ACUTAL: 124,794 - Interior Condition: Fair - Interior Problems - Needs Cleaning, Tear On Driver's Seat, Seats Are Stained & Need To Be Cleaned - Body Condition: Fair - Body Problems: Peeling Paint, Hole In Roof Where Antenna Light Was Mounted, Oxidized Paint, Hole In Trunk Where Antenna Was Mounted - Tires Condition: Poor</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
2	(1) 2010 Ford 4Dr Crown Victoria Vin #5283 (Needs To Be Towed)	<p>(Needs To Be Towed) - Passenger: 5 - Engine Size: 4.6L - Engine Problems: Unknown - Gas - Has Battery, Dead - Runs, But Will Not Drive - Automatic - Transmission Condition: Bad Transmission - Brakes: Hydraulic - Inspection Sticker Month: January 2020 - Approx. Mileage NOT ACTUAL: 176,297 - Interior Condition: Fair - Interior Problems: Needs Cleaning - Body Condition: Fair to Poor - Body Problems: Crack On Front Windshield, Hood Peeling And Oxidized, Oxidized Paint All Over Unit, Needs Cleaning, Hole On Trunk and Roof Where Light Or Antenna Was Mounted - Tires Condition: Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
3	(1) 2009 Ford 4Dr Crown Victoria Vin #8194 (Needs To Be Towed)	<p>(Needs To Be Towed) - Passenger: 5 - Engine Size: 4.6L - Engine Problems: Unknown - Gas - Has Battery, Dead - Runs, But Will Not Drive - Automatic - Transmission Condition: Bad Transmission, Slipping - Brakes: Hydraulic - Inspection Sticker Month: November 2018 - Approx. Mileage NOT ACTUAL: 120,789 - Interior Condition: Fair - Interior Problems: Needs Cleaning - Body Condition: Fair to Poor - Body Problems: Oxidized Paint All Over Unit, Peeling Paint, Scratches, Cracked/Hole On Right Front Lens Cover, Scratches On Windshield, Needs Cleaning, Hole On Trunk and Roof Where Light Or Antenna Was Mounted - Tires Condition: Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	

4	(1) 2006 Ford 4Dr Crown Victoria Vin #0307	<p>Passenger: 5 - Engine Size: 4.6L - Engine Problems: Unknown - Gas - Has Battery, Dead - Runs - Automatic - Brakes: Hydraulic - Inspection Sticker Month: December 2019 - Approx. Mileage NOT ACUTAL: 114, 301 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Stains On Seats & Carpet - Body Condition: Poor - Peeling Paint, Rust On Roof, Hole On Roof & Truck Where Antenna Or Light Was Mounted, Needs Cleaning, Rock Chip On Windshield, Scratches, Stress Lines On Right Rear Bumper - Tires Condition: Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
5	(1) 2009 Ford 4Dr Crown Victoria Vin #2350	<p>Passenger: 5 - Engine Size: 4.6L - Engine Problems: Unknown - Gas - Has Battery, Dead - Runs - Automatic - Brakes: Hydraulic - Inspection Sticker Month: February 2020 - Approx. Mileage NOT ACUTAL: 102,103 - Interior Condition: Fair - Interior Problems: Needs Cleaning - Body Condition: Poor - Peeling Paint All Over, Oxidized Paint All Over, Scratches, Surface Rust, Cracks In Windshield, Hole On Roof & Truck Where Antenna Or Light Was Mounted - Tires Condition: Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
6	(1) 2008 International CE200 Vin #2188	<p>Passenger: 47 - Engine Size/Type: VT365/A200 - Engine In Front - Engine Problems: Unknown - Diesel - Has Battery, Dead - Runs - Automatic - Brakes: Air - Inspection Sticker Month: September 2020 - Approx. Mileage NOT ACUTAL: 151,334 - Wheel Chair Lift: No - Interior Condition: Fair - Interior Problems: Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Scratches On Left Rear Panel, Cracks On Windshield - Tires Condition: Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
7	(1) 2004 International CE200 Vin #6339	<p>Passenger: 71 - Engine Size/Type: 7.3L/International - Engine Problems: Engine Knocks - Diesel - Has Battery, Dead - Runs - Automatic - Brakes: Air - Inspection Sticker Month: February 2020 - Approx. Mileage NOT ACUTAL: 164,032 - Wheel Chair Lift: No - Interior Condition: Fair - Interior Problems: Needs Cleaning, Some Torn Seats - Body Condition: Fair - Body Problems: Surface Scratches - Tires Condition: Fair to Poor - Tire Problems: Right Rear Poor, Remainder Tires Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	

8	(1) 2004 International CE200 Vin #6335 (Needs To Be Towed)	<p>(Needs To Be Towed) - Passenger: 71 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Ignition Problem, Engine Okay - Diesel - Has Battery, Dead - Runs: See Engine Problem Note - Automatic - Brakes: Air - Inspection Sticker Month: January 2020 - Approx. Mileage NOT ACUTAL: 192,242 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Some Torn Seats - Body Condition: Fair - Body Problems: Slight Indention On Right Side Lower Panel In Front Of Rear Wheel, Surface Scratches, Surface Rust On Roof, Scratch/Dent On Right Rear Near Bumper, Dent On Rear Corner, Crack On Hood</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
9	(1) 2004 International CE200 Vin #6340	<p>Passenger: 71 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Unknown - Diesel - Has Battery, Dead - Runs - Automatic - Brakes: Air - Inspection Sticker Month: January 2020 - Approx. Mileage NOT ACUTAL: 128,166 - Interior Condition: Fair - Interior Problems: Drivers Seat Torn & Some Passenger Seats Torn, Needs Cleaning - Body Condition: Fair - Body Problems: Slight Indention Under #4 Window On Right Side, Some Scratches, Minor Peeling On Rear, Crack On Hood, Rock Chip On Windshield - Tires Condition: Fair to Poor - Tire Problems: Right Rear Poor, Remainder Tires Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
10	(1) 2004 International CE200 Vin #6513	<p>Conventional Style - Passenger: 71 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Unknown - Diesel - Has Battery, Dead - Runs - Automatic - Brakes: Air - Inspection Sticker Month: February 2020 - Approx. Mileage NOT ACUTAL: 169,852 - Interior Condition: Fair - Interior Problems: Some Seats Torn, Needs Cleaning - Body Condition: Fair - Body Problems: Scratch/Dent on Right Rear Under #9 Window & Scratch/Indention On Lower Panel, Scratches Under #2 Window On Left Side, Cracked Corner Window On Left Front, Front Grill Is Loose On Hood - Tires Condition: Fair to Poor - Tire Problems: Left Rear Poor, Remainder Tires Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	

11	(1) 2004 International CE200 Vin #6487	<p>Conventional Style - Passenger: 27 & (2) Wheel Chair - Engine Size/Type: T444E - Engine In Front - Engine Problems: Unknown - Diesel - Has Battery, Dead - Runs - Automatic - Brakes: Air - Inspection Sticker Month: January 2019 - Approx. Mileage NOT ACUTAL: 238,377 - Wheel Chair Lift: Yes, Condition Unknown - Interior Condition: Fair - Interior Problems: Minor Torn Seats, Needs Cleaning - Body Condition: Fair - Body Problems: Surface Scratches, Rock Chip On Windshield, Small Crack On Hood - Tires Condition: Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
12	(1) 2004 International CE200 Vin #6489	<p>Conventional Style - Passenger: 27 & (2) Wheel Chair - Engine Size/Type: T444E - Engine In Front - Engine Problems: Unknown - Diesel - Has Battery, Dead - Runs - Automatic - Brakes: Air - Inspection Sticker Month: November 2019 - Approx. Mileage NOT ACUTAL: 182,368 - Wheel Chair Lift: Yes, Condition Unknown - Interior Condition: Fair - Interior Problems: Some Torn Seats, Missing Parts On Steering Wheel (Horn) & Possible Other Parts - Body Condition: Fair - Body Problems: Surface Scratches, Oxidized Paint - Tires Condition: Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
13	(1) 2007 International CE200 Vin #6209 (Needs To Be Towed)	<p>(Needs To Be Towed) - Conventional Style - Passenger: 48 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Parts Missing On Engine - Diesel - Battery: No - Does Not Run - Automatic - Brakes: Air - Inspection Sticker Month: November 2019 - Approx. Mileage NOT ACUTAL: 145,702 - Wheel Chair Lift: No - Interior Condition: Fair - Interior Problems: Some Parts Missing On Entry Door, Dash, Drivers Side Window, & More, Some Torn Seats - Body Condition: Fair - Body Problems: Missing Light On Rear, Oxidized Paint, Scratches - Tires Condition: Fair to Poor - Tires Condition: Right Rear Poor, Remainder Are Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	

14	(1) 2004 International CE200 Vin #6338	<p>Conventional Style - Passenger: 71 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Unknown - Diesel - Has Battery, Dead - Runs - Automatic - Brakes: Air - Inspection Sticker Month: February 2020 - Approx. Mileage NOT ACUTAL: 183,670 - Interior Condition: Fair - Interior Problems: Drivers Sear Torn, Some Passenger Seats Are Torn, Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Scratch/Dent On Right Side Under #5 & #6 Window, Some Scratches- Tires Condition: Fair to Poor - Tire Problems: Right & Left Rear Poor, Remainder Tires Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
15	(1) 2003 Ford Cargo Van Vin #4538	<p>Conventional Style - Passenger: 2 - Engine Size/Type: Ford Econoline/5.4L - Engine In Front - Engine Problems: Bad Head Gasket, Recommend Towing - Gas - Has Battery, Dead - Runs - Automatic - Brakes: Hydraulic - Inspection Sticker Month: May 2019 - Approx. Mileage NOT ACUTAL: 221,775 - Interior Condition: Fair - Interior Problems: Drivers Seat Poor/ Torn, Needs Cleaning, Has Protection Cage Walk Thru Type - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Crack On Windshield, Surface Rust On Roof - Tires Condition: Poor - Tire Problems: Recommend Replacing Soon</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
16	(1) 1996 Chevy Heavy Duty Box Truck Vin #7241 (Needs To Be Towed)	<p>(Needs To Be Towed) - Conventional Style - Passenger: 3 - Engine Size/Type: CAT 3116 - Engine In Front - Engine Problems: Not Running, Problem Not Known - Diesel - Battery: No - Does Not Run - Automatic - Brakes: Air - Inspection Sticker Month: September 2018 - Approx. Mileage NOT ACTUAL: 53,339 - Interior Condition: Fair - Interior Problems: Needs Cleaning, Headliner Needs Replacing, Dash Worn & Some Damage, Cab Light Cover Missing, W/Lift Gate, Condition Unknown, High Cube Van, Box Bed Length (Approx.) 18' - Body Condition: Fair - Body Problems: Morgan Corp Box Model: GV5D09718096 - Additional Information: Gawr/Front: 11000, Gawr/RR: 22700, GVWR: 33,700, Has (1) Fuel Tank</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	

17	(1) 2007 International CE200 Vin #6263 (Needs To Be Towed)	<p>(Needs To Be Towed) - Conventional Style - Passenger: 71 - Engine Size/Type: T444E - Engine In Front - Engine Problems: Parts Missing On Engine, Problem Unknown - Diesel - Battery: No - Does Not Run - Automatic - Brakes: Air - Inspection Sticker Month: September 2020 - Approx. Mileage NOT ACTUAL: Unknown, Dead Battery - Wheel Chair Lift: No - Interior Condition: Fair - Interior Problems: Some Torn Seats, Drivers Seat Torn, Some Parts Missing - Body Condition: Fair - Body Problems: Oxidized Paint, Small Indention On Lower Panel Right Rear, Rear Bumper Dented, Scratches, Needs Cleaning, Peeling On Hood - Tires Condition: Fair to Poor - Tires Condition: Right Rear Poor, Remainder Are Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
18	(1) 2003 Ford F350 Super Duty 4Dr Dually Vin #3150 (Needs To be Towed)	<p>(Needs To Be Towed) - Conventional Style: Passenger: 6 - Engine Size/Type: V8 Power Stroke Turbo Diesel - Engine In Front - Engine Problems: Needs Crank Sensor - Diesel - Has Battery, Dead - Does Not Run - Automatic - Brakes: Hydraulic - Inspection Sticker Month Date: May 2020 - Approx. Mileage NOT ACTUAL: Unable To Read, Dead Battery - Interior Condition: Fair - Interior Problems: Needs Cleaning, Rear Seats Worn - Body Condition: Fair - Body Problems: Peeling Paint, Surface Scratches, Dents, Surface Rust, Dent In Right Rear Bed, Tailgate Is Poor, Rear Bumper Missing Rubber Padding, Dent On Left Rear In Front Of Break Light, Damage On Left Rear Wheel Well - Tires Condition: Fair</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
19	(1) 1989 Chevy 1500 Pickup Truck Vin #3313 - Recommend Towing	<p>Conventional Style - Passenger: 3 - Engine Size/Type: 4.3L - Engine Problems: Unknown, Ran When Parked, Key Is Broke Off Inside The Ignition, Unable To Try to Start - Gas - Has Battery, Dead - Do Not Know If It Runs - Automatic - Brakes: Hydraulic - Inspection Sticker Month: January 2021 - Approx. Mileage NOT ACTUAL: 139,762 - Interior Condition: Poor - Interior Problems: Seats Need To Be Replaced, Needs Cleaning, Needs Headliner Replaced, Door Panels Are Worn - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Rust, Surface Scratches, Needs Cleaning, Scratches, Dents - Tires Condition: Fair - Recommend Towing, Due to Key Stuck In Ignition</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	

20	(1) 2005 Ford Passenger Van Vin #2349 (Needs To Be Towed)	<p>(Needs To Be Towed) - Unit M13 - Conventional Style - Passenger: 2 - Engine Size/Type: Unknown - Engine In Front - Engine Problems: Wrecked - Gas - No Battery - Does Not Run, Wrecked - Brakes: Hydraulic - Inspection Sticker Date: August 2020 - Approx. Mileage NOT ACUTAL: Unknown - Interior Condition: Poor - Interior Problems: Wrecked, Parts Missing - Body Condition: Poor - Body Problems: Wrecked, Parts Missing - Tires Condition: Poor - Tire Problems: Front Tires Poor Due To Wreck</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
----	---	--	---