

| Lot Number | Title | Description | Thumbnail |
|------------|-------------------------------|--|---|
| 0 | Preview & Removal Information | <p>IMPORTANT NOTICE FOR LACKLAND ISD AUCTION: All purchases will be subject to a 13% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</p> <p><i>This Auction Requires Additional Registration For Bidding. Must Agree To Auction Terms & Conditions. Please Call Lemons Auctioneers At (281)357-4977 To Be Approved For Bidding Once Auction Registration Is Complete.</i></p> <p>PLEASE READ PRIOR TO BIDDING: To visit Lackland ISD, the military installation requires all visitors to have a pass. To process a pass your information must appear exactly as it is written on your drivers license. Please fill out the form here: https://www.cognitofrms.com/LacklandISD1/BaseVisitorPassRequest Once approved, a pass will be generated and sent to security to await your arrival. All visitors need to stop at the visitor's center, located to the right of the gate, and pick up your pass. The security office will ask for photo ID, proof of car registration & proof of car insurance. Please allow 30-45 minutes to complete check in procedures. On Thursday's, the wait time will increase to 1 hour or longer due to an event the base holds. If you must visit on a Thursday, you may wish to pick up your pass the day before.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Thursday, May 21, 2020 /Friday, May 22, 2020 (Hours Of Operation: 8:30 a.m.- 4:00 p.m.)</p> <p>Location: Transportation Services, JBSA-Lackland Air Force Base, 2460 Kenly Avenue, San Antonio, TX 78236-1244 Driving Directions Removal: (By Appointment Only - No Exceptions) Wednesday, May 27, 2020/Thursday, May 28, 2020/Friday, May 29, 2020 (Hours Of Operation: 8:30 a.m.- 4:00 p.m.) Preview & Removal Contact: Steven Rodriguez, (210) 357-5047, email: rodriguez.s@lacklandisd.net</p> <p>*Social distancing will be enforced *Customers will not be allowed inside to use the restrooms. No Exceptions! *Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled. *We recommend wearing gloves and face mask for personal safety and health while on auction location.</p> <p>There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** No Manpower Or Lifting Equipment Available. Please Bring Own Tie Downs, Dollies, Manpower, Etc...</p> |  |

| | | | |
|-----|--------------------------------------|---|---|
| 115 | (1) 2002 International Bus Vin #9900 | <p>Bus #11 Transit Style Passenger: 84 Engine Size/Type: T444E Engine In Rear Engine Problems: Needs Belt, WILL NOT RUN, Ran When Last Parked, Note: Buyer Should Bring Their Own Belt Or Vehicle Will Need To Be Towed Diesel Has Battery Will Run, But Needs Belt Automatic Brakes: Air Inspection Sticker Month: August 2019 Approx. Mileage (NOT ACTUAL) 1888 Does Not Have Wheelchair Lift Interior Condition: Fair Interior Problems: Most Of The Seats Are Torn Body Condition: Fair Body Problems: Oxidized Paint, Peeling On Lower Cargo Dorr On Lift Side, Some Scratches Tires Condition: Good Additional Information: Has Under Storage There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p> |  |
| 116 | (1) 2002 International Bus Vin #9901 | <p>Unit #12 Transit Style Passenger: 84 Engine Size/Type: T444 E/7.3 L/V8 Engine Problems: Dead Battery, Ran When Parked Diesel Runs, Dead Battery Automatic Brakes: Air Approx. Mileage (NOT ACTUAL): 42,246 No Wheelchair Lift Interior Condition: Fair Interior Problems: Torn Seats Throughout Bus Body Condition: Fair Body Problems: Damage On Lower Cargo Door On Right Side Under 9 & 10 Window, Oxidized Paint, Dent On Left Rear Cargo Door Tires Condition: Good There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p> |  |

| | | | |
|-----|--|---|---|
| 117 | (1) 2004 International Bud Vin #9046 - Needs To Be Towed | <p>NEEDS TO BE TOWED Unit #1 TD 466 Conventional Style Passenger: 21 & (2) Wheelchair Spots Engine Size/Type: 7.6 L Engine Problems: Engine Is Blown Diesel Does Not Have A Battery Automatic Brakes: Air Inspection Sticker Month: January 2018 Approx. Mileage (NOT ACTUAL): 148,821 Has Wheelchair Lift, Condition Unknown Interior Condition: Fair Interior Problems: Needs Cleaning, Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint, Surface Scratches, Missing Left Rear Tire & Wheel, Chipped Paint On Roof, Peeling Paint On Hood Tires Condition: Poor Tire Problems: Possible Dry Rot On Tires There Will Be A \$25.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p> |  |
|-----|--|---|---|