

Lot Number	Title	Description	Thumbnail
------------	-------	-------------	-----------

**IMPORTANT NOTICE FOR AUSTIN ISD AUCTION: \*\*All purchases will be subject to a 13% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.\*\***

**\*Social distancing will be enforced**

**\*Customers will not be allowed inside to use the restrooms. No Exceptions!**

**\*Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled.**

**\*We recommend wearing gloves and face mask for personal safety and health while on auction location.**

**\*All Wifi Has Been Removed From Buildings**

**\*All Door Locks Have Been Removed From Buildings**

**\*Some Contents May Still Be Conveyed In Buildings**

**\*Most Of The Contents Will Be Removed From Buildings**

**\*\*Seller Disclosure\*\* Austin ISD and Lemons Auctioneers & Online Pros recommends that all prospective buyers inspect buildings prior to bidding for structural, roof, & electrical condition, environmental hazards, and moisture intrusion. Lemons Auctioneers noted a few of the buildings had an informational plaque stating that the building has Asbestos on the floor Tiles/Mastic & sink coating. This information was noted on the lots.**

**Preview: (By Appointment Only - Mandatory - No Exceptions) Thursday, June 25, 2020 (Hours Of Operation: 7:30 a.m.-11:30 a.m./1:00 p.m.-3:30 p.m.)**

**Location 1 (Lots 1-7): Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744**

[Driving Directions](#)

**Location 2: (Lots 8-9) Langford Elementary School, 2206 Blue Meadow Dr., Austin, TX 78744**

[Driving Directions](#)

**Location 3 (Lots 10-19): Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752**

[Driving Directions](#)

**Location 4 (Lots 20-21): Burnet Middle School, 8401 Hathaway St., Austin, TX 78752**

[Driving Directions](#)

**Location 5 (Lot 22): O. Henry Middle School, 2610 West 10th Street, Austin, TX 78703**

[Driving Directions](#)

**Location 6 (Lots 23-26): Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739**

[Driving Directions](#)

**Note: Prior To Bidding. Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!\*\*\*The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer. And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.\*\*\* Lemons Auctioneers 281-357-4977**

**Removal For All Locations: (By Appointment Only - Mandatory - No Exceptions)**

Portables Must Be Removed By Midnight Of Thursday, July 30, 2020 - There will be a \$100 late fee PER DAY if portables are not removed by deadline. (Hours Of Operation: 7:30 a.m.-11:30 a.m./1:00 p.m.-3:30 p.m.)

**Location 1 (Lots 1-7): Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744**

[Driving Directions](#)

**Location 2: (Lots 8-9) Langford Elementary School, 2206 Blue Meadow Dr., Austin, TX 78744**

[Driving Directions](#)

**Location 3 (Lots 10-19): Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752**

[Driving Directions](#)

**Location 4 (Lots 20-21): Burnet Middle School, 8401 Hathaway St., Austin, TX 78752**

[Driving Directions](#)

**Location 5 (Lot 22): O. Henry Middle School, 2610 West 10th Street, Austin, TX 78703**

[Driving Directions](#)

**Location 6 (Lots 23-26): Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739**

[Driving Directions](#)

**Preview & Removal Contact: Mark Curtis (512) 414-606 Email: mark.curtis@austinisd.org**

**[Click Here For Insurance Requirements Guideline Form](#)**



0

Preview &  
Removal  
Information

1	(1) Portable Building	<p>Building #1  Building ID #P-364/89pf - Room P-24/P-23  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2 - Both Are Operable  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Zone Air Package Units  Exterior Condition/Problems: Minor Scratches, Dents, Fully Skirted  Interior Condition/Problems: Has Cabinet W/Sink &amp; Closets In Both Rooms - Ceiling Tiles Are In Good Condition - Floor Tiles Are Okay - Electrical Panel In Center Of Building On Inside  Entry To Building: Double Front - (1) Entry On Right Side Of Building W/Aluminum Steps  Overall Condition Of Portable Building: Fair  Additional Information: Has A Pass Thru Hallway Between Both Rooms</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*,  *This Item Is Being Sold "As/Is", * **Photo's And Descriptions Were Supplied By Lemons Auctioneers  - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location -  No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
2	(1) Portable Building	<p>Building #2  Building ID #P465/93 - Room P-21/P-22  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Mfg. Unknown  Exterior Condition/Problems: Building Is Fully Skirted, Some Dents &amp; Minor Scratches, Will Need Cleaning On Front  Interior Condition/Problems: Both Rooms Have A Bathroom &amp; Cabinet W/Sink - Water Stain On Left Wall &amp; Ceiling Tile In Classroom 1 - Floor Appears Okay - Electrical Panel In Center Of Building On The Inside  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair  Additional Information: Has Pass Thru Hallway Between Both Rooms</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*,  *This Item Is Being Sold "As/Is", * **Photo's And Descriptions Were Supplied By Lemons Auctioneers  - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location -  No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

3	(1) Portable Building	<p>Building #3  Building ID #P-407/90 - Rooms P-20/P-19  Double  Approx. Size: 65' x 30' W/Eaves  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Mfg. Unknown  Exterior Condition/Problems: Right Side Has Approx. 8" x 6" Dent W/Metal Missing - Minor Dents &amp; Scratches - Will Need Cleaning On Front  Interior Condition/Problems: Each Room Has A Cabinet W/Sink &amp; Bathroom &amp; 3 Closets - Floor Has Stains On Vinyl Tile In (1) Classroom - A Few Minor Water Spots On Ceiling Tiles In (1) Classroom - Has A Teachers Closet  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair  Additional Information: Has Pass Thru Hallway Between Both Rooms</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*,  *This Item Is Being Sold "As/Is",* ***Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
4	(1) Portable Building	<p>Building #4  Building ID #P455/93pf - Room P-17/P-18  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Mfg. Unknown  Exterior Condition/Problems: Left Side Siding Has Approx. 8"-10" Gash - Some Dents &amp; Scratches - Approx. 5" Gash On Right Corner Front - Front Of Building Needs Cleaning  Interior Condition/Problems: Floor Vinyl Tiles Look Good - Ceiling Tiles Are Okay - Both Rooms Have (1) Cabinet W/Sink - (2) Closets &amp; Bathrooms &amp; (1) Teachers Closet  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair  Additional Information: Has Pass Thru Hallway Between Both Rooms</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*,  *This Item Is Being Sold "As/Is",* ***Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

5	(1) Portable Building	<p>Building #5  Building ID #P-249/85pf - Rooms P1-P2  Double  Approx. Size: 65' x 30' W/Eaves  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Mfg. Unknown  Exterior Condition/Problems: Minor Scratches &amp; Dents - Small Gash On Lower Panel On Left Side  Approx. 5" x 5" - Dent/Gash On Left Rear Corner  Interior Condition/Problems: Each Room Has (1) Cabinet W/Sink, Teachers Closet, (Approx. 3) Additional Closets &amp; (1) Bathroom - A Few Water Spots On Ceiling Tile - Floor is Fair But Usable Condition  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*,  *This Item Is Being Sold "As/Is",* ***Photo's And Descriptions Were Supplied By Lemons Auctioneers  - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location -  No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
6	(1) Portable Building	<p>Building #6  Building ID #P-252/85pf - Room P-13/P-14  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Zone Aire  Exterior Condition/Problems: Minor Dents &amp; Scratches - Fully Skirted - Will Need Cleaning On Front  Interior Condition/Problems: Each Classroom Has (1) Cabinet W/Sink, Bathroom, Teacher's Closet &amp; (Approx. 3) Additional Storage Closets - Ceiling Tiles &amp; Floor Vinyl Are Okay - Electrical Panel Located Inside Center Of Building  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair  Additional Information: Has Pass Thru Hallway Between Both Rooms</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*,  *This Item Is Being Sold "As/Is",* ***Photo's And Descriptions Were Supplied By Lemons Auctioneers  - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location -  No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

7	(1) Portable Building	<p>Building #7  Building ID #P051 - Rooms P-11/P-12  Double  Approx. Size: 65' x 25'  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Roll On Roofing/Flat Roof  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Mfg. Unknown  Exterior Condition/Problems: Some Minor Dents &amp; Scratches - Fully Skirted  Interior Condition/Problems: All Rooms Have (1) Teachers Closet, (1) Cabinet W/Sink, (Approx. 2) Additional Storage Closets - Some Tiles Are Damaged In Both Rooms - Floor Tiles Okay - Both Rooms Have A Bathroom  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*, *This Item Is Being Sold "As/Is", * **Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
8	(1) Portable Building	<p>Building #8  Building ID #P531 - Room J1/J2  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard A/C Heat Package Units  Exterior Condition/Problems: Minor Scratches &amp; Dents - A Few Gashes On Right Side - Fully Skirted  Interior Condition/Problems: Both Classrooms Have (1) Teachers Closet, (Approx. 2) Additional Storage Closets, (1) Bathroom &amp; (1) Cabinet W/Sink - Floor Tiles Have Some Minor Damage - Ceiling Tile Panel Missing In (1) Room - Electrical Panel Is Located In Center Of Inside Building  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair  Additional Information: Has Pass Thru Hallway Between Both Rooms</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Langford Elementary School, 2206 Blue Meadow Dr., Austin, TX 78744, *Condition Unknown*, *This Item Is Being Sold "As/Is", * **Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

9	(1) Portable Building	<p>Building #9  Building ID #P530 - Rooms K2-K1  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: The Wall Mount Package AC/Heat Unit  Exterior Condition/Problems: Some Dents &amp; Scratches - Wood Rot On Lower Door 2" x 4" Piece On Right Side  Interior Condition/Problems: Some Tiles Are Damaged On Floor - Ceiling Tiles Look Okay - Both Rooms Have (1) Cabinet W/Sink, (1) Teachers Closet, (Approx. 2) Storage Cabinets &amp; (1) Bathroom - electrical Panel Is In The Center Of Building  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Langford Elementary School, 2206 Blue Meadow Dr., Austin, TX 78744, *Condition Unknown*, *This Item Is Being Sold "As/Is",* ***Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
10	(1) Portable Building	<p>Building #10  Building ID #P204/83 - Rooms 8A/8B  Double  Approx. Size: 65' x 30' W/Eaves  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard AC/Heat Package Units  Exterior Condition/Problems: Minor Scratches &amp; Dents - Fully Skirted  Interior Condition/Problems: Some Tiles On Floor Are Damaged - Ceiling Tiles Okay - Both Rooms Have (1) Bathroom, (1) Teachers Closet, (Approx. 3) Storage Closets, (1) Cabinet W/Sink  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair  Additional Information: Has Pass Thru Hallway Between Both Rooms - Some Contents Will Be In Unit</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

11	(1) Portable Building	<p>Building #11  Building ID # P190/83 - Room 7A/7B  Double  Approx. Size: 65' x 30 W/Eaves  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2 + 1  Brand A/C Units &amp; Type: Bard AC/Heat Package Units &amp; (1) Window Unit  Exterior Condition/Problems: On Right Rear Corner Pencil Graffiti, Will Need To Be Painted - Pencil Or Scratch Graffiti On Right Side - Fully Skirted  Interior Condition/Problems: 7A: (1) Room Has Been Divided Into 2 Rooms &amp; Has (1) Bathroom, (1) Cabinet W/Sink, (1) Storage Cabinet - Water Stains On Tile - Floor Okay - 7B: Room Type Unknown /No Key For Entry  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
12	(1) Portable Building	<p>Building #12  Building ID #P-296 - Room 6A/6B  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Mfg. Unknown  Exterior Condition/Problems: Minor Dents &amp; Scratches - Center Rear Lower Panel Large Dent, Approx. 20" - Fully Skirted  Interior Condition/Problems: Some Soft Spots On Tile - Some Floor Tiles Are Damaged - Both Rooms Have (1) Cabinet W/Sink, (1) Teachers Cabinet, (Approx. 3) Storage Closets &amp; (1) Bathroom  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

13	(1) Portable Building	<p>Building #13  Building ID #P-227/84pf - Rooms 5A/5B  Double  Approx. Size: 65' x 30' W/Eaves  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard AC/Heat Package Unit  Exterior Condition/Problems: Damage On Siding On Left Corner - Dents &amp; Some Surface Scratches - Rotted Wood Under (1) Entry Door  Interior Condition/Problems: Both Rooms Have A Cabinet W/Sink, Bathroom &amp; Storage Cabinets - Some Damage On Floor Tile - Some Water Stains On Ceiling Tile  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair  Additional Information: Has Pass Thru Hallway Between Both Rooms - Has Asbestos Floor Tile &amp; Mastic &amp; Sink Coating Noted On Small Plaque</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
14	(1) Portable Building	<p>Building #14  Building ID #P-547/97pf  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Wood - Metal Skirting/Fully Skirted  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Mfg. Unknown  Exterior Condition/Problems: Minor Scratches &amp; Dents  Interior Condition/Problems: Both Rooms Have (1) Teachers Closet, (Approx. 2) Additional Closets, (1) Bathroom, (1) Cabinet W/Sink - Ceiling Tile Is Good - Floor Okay  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair  Additional Information: Has Plaque That States The Building Is Asbestos Free - No Asbestos</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

15	(1) Portable Building	<p>Building #15  Building ID # P-099/70pf - Rooms 3A/3B  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Wood  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Mfg. Unknown  Exterior Condition/Problems: Minor Dents &amp; Surface Scratches - Fully Skirted  Interior Condition/Problems: Both Rooms Have Storage Cabinets/No Closets, (1) Bathroom, (1) Cabinet W/Sink - Floor Tiles Okay - Ceiling Tiles Have Some Water Stains  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
16	(1) Portable Building	<p>Building #16  Building ID # P-301/87pf - Rooms 12A/12B  Double  Approx. Size: 65' x 30' W/ Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Wood  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard AC/Heat Package Units  Exterior Condition/Problems: Minor Dents &amp; Scratches - Fully Skirted  Interior Condition/Problems: Both Rooms Have (1) Bathroom, (1) Cabinet W/Sink  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair  Additional Information: Has Plaque That States The Building Has Asbestos On Floor Tile/Mastic</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

17	(1) Portable Building	<p>Building #17  Building ID # P-239/85pf - Rooms 11A/11B  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Wood  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard AC/Heat Package Units  Exterior Condition/Problems: Minor Dents &amp; Scratches - Fully Skirted  Interior Condition/Problems: Both Rooms Have Storage Cabinets, (1) Bathroom, (1) Cabinet W/Sink - Ceiling Tiles &amp; Floor Okay  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
18	(1) Portable Building	<p>Building #18  Building ID # P-588/98 pf - Room 9A/9B  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Wood  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard AC/Heat Package Unit  Exterior Condition/Problems: Minor Scratches &amp; Dents - Fully Skirted  Interior Condition/Problems: Both Rooms Have (1) Teachers Closet, (Approx. 3) Additional Closets, (1) Bathroom, (1) Cabinet W/Sink - Ceiling Tiles Okay - Floor Tiles Okay  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

19	(1) Portable Building	<p>Building #19  Building ID # P-476/94pf  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Wood  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard AC/Heat Package Unit  Exterior Condition/Problems: Some Minor Scratches &amp; Dents - Fully Skirted  Interior Condition/Problems: Both Rooms Have (1) Teachers Closet, (Approx. 3) Additional Closets, (1) Bathroom, (1) Cabinet W/Sink - Some Damage On Floor Tiles - Ceiling Tiles Okay  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
20	(1) Portable Building	<p>Building #20  Building ID # P-068/64pf - Rooms P-501/P-503  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): No  Classroom(s): Yes, How Many: 2  Type Of Siding: Hardi Panel &amp; Lap Board &amp; Metal/Pressboard  Type Of Roof: Flat Roof/Roll On  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Package AC/Heat Unit  Exterior Condition/Problems: Some Scratches &amp; Pencil Graffiti On Left Side  Interior Condition/Problems: Both Rooms Have Some Ceiling Tile Damage, (1) Storage Closet - Floor Appears Okay  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Burnet Middle School, 8401 Hathaway St., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

21	(1) Portable Building	<p>Building #21  Building ID # P-021/56 - Rooms 613/615  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): No  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Flat Roof/Roll On  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard/The Wall Mount AC/Heat Package Trimboard Units (Recently Replaced) &amp; (Approx. 2) Window A/C Units  Exterior Condition/Problems: Some Rotted Wood Around Base - Fully Skirted  Interior Condition/Problems: Room #1 Has (Approx. 2) Closets &amp; (Approx. 2) Room Offices On End Of Building - Ceiling Tiles &amp; Floor Tiles Okay  Entry To Building: Double Front + (1) Entry On Right Side  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Burnet Middle School, 8401 Hathaway St., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
22	(1) Portable Building	<p>Building #22  Building ID # P-066/64 - Rooms P6/P7  Double  Approx. Size: 65' x 28'  Restroom(s): No  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Flat Roof/Roll On  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard AC/Heat Package Units - (1) Not Working  Exterior Condition/Problems: Built On Front Awning Has Rotted Wood - Wood Rot On Eaves - Scratches &amp; Dents - Fully Skirted  Interior Condition/Problems: Both Rooms Have (1) Teachers Closet, (Approx. 3) Additional Closets - Floor Tiles Looks Okay - Some Ceiling Tiles Are Damaged  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair  Additional Information: Has Pass Thru Hallway Between Both Rooms - Has Plaque That States Building Contains Asbestos Building Materials - 9x9 Floor Tiles/Mastic Decked Over W/NAD - 12x12 Tile/Mastic</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: O. Henry Middle School, 2610 West 10th Street, Austin, TX 78703, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

23	(1) Portable Building	<p>Building #23  Building ID # P-311 - Rooms P11A/P11B  Double  Approx. Size: 68' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  Exterior Condition/Problems: Surface Scratches - Minor Dents - fully Skirted - Some Rotted Wood On Base Of Siding - Gutter Damage Above Door  Interior Condition/Problems: Both Rooms Have Storage Cabinets/No Closet, (1) Bathroom, (1) Cabinet W/Sink - Floor &amp; Ceiling Tiles Okay  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
24	(1) Portable Building	<p>Building #24  Building ID # P-229/84 pf - Rooms P-9A/P-9B  Double  Approx. Size: 68' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Marvair Package AC/Heat Units  Exterior Condition/Problems: Some Scratches &amp; Minor Dents - Fully Skirted  Interior Condition/Problems: Both Rooms Have (1) Bathroom, (1) Cabinet W/Sink - Ceiling Tiles &amp; Floor Tiles Okay - Storage Cabinets &amp; Built In Bookcases  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Additional Information: Asbestos Noted In Building M&amp;S 12x12 Cream &amp; Brown Tile &amp; White Specks Wood Floor, Sink Coating (Pink)</p> <p>Location: Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

25	(1) Portable Building	<p>Building #25  Building ID # P-185/82 pf - Rooms 8A/8B  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Classroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard AC/Heat Package Units  Exterior Condition/Problems: Dent On Rear Left Corner - Some Scratches &amp; Minor Dents - (1) Meal Eave Corner On Right Side Dented - Fully Skirted  Interior Condition/Problems: Some Tiles Are Damaged - Floor tiles Okay - Both Rooms Have (1) Teachers Closet, (Approx. 2) Additional Closets, (1) Bathroom, (1) Cabinet W/Sink  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*  Additional Information: Has Pass Thru Hallway Between Both Rooms</p> <p>Location: Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
26	(1) Art Deco Building /Classroom /Studio	<p>Building #26  Building ID # P-422/91 pf  Double  Approx. Size: 65' x 30' W/Eaves  Restroom(s): Yes, How Many: 2  Type Of Siding: Metal/Pressboard  Type Of Roof: Composition  Skid: Unknown  A/C Unit(s): Yes, How Many: 2  Brand A/C Units &amp; Type: Bard AC/Heat Package Units  Exterior Condition/Problems: Minor Scratches &amp; Dents  Interior Condition/Problems: Some Floor Tiles Are Damaged - Will Need Some Paint - Both Rooms Have (1) Teachers Closet, (1) Bathroom, (1) Cabinet W/Sink  Entry To Building: Double Front  Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!  ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	