




Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>**There Will Be A 14% Bover's Premium Added To The Bover's Total For Each Item Purchased. There Will Be A 3% Fee For All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order & Wire Transfer**</p> <p>*Social distancing will be enforced</p> <p>*Customers will not be allowed inside to use the restrooms. No Exceptions!</p> <p>*Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled.</p> <p>*We recommend wearing gloves and face mask for personal safety and health while on auction location.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, June 30, 2020 (Hours Of Operation: 9:00 a.m. - 1:00 p.m.) Preview Contact: Allen Woodson (512) 898-0062</p> <p>Location: 201 S Bounds, Thrall, TX 76578 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Monday, July 6, 2020 /Tuesday, July 7, 2020/Wednesday, July 8, 2020 (Hours Of Operation: 9:00 a.m. - 2:00 p.m.) Removal Contact: JD Fralicker (512) 898-0062</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buvers responsibility once purchased by buver. Bover should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buver with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	
38	(1) 1995 International Bus Vin #2141	<p>Unit #38 Conventional Style Passenger: 59 Engine Size/Type: T444 International Engine In Front Diesel Has Battery Runs Automatic Transmission Type/Condition: Allison Brakes: Air Inspection Sticker Date: January 2013 Approx. Mileage (NOT ACTUAL): 164,505 Has Wheel Chair Lift - Condition Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Sitting In Dusty Lot Body Condition: Fair Body Problems: Faded - Missing Parts Tires Condition: Poor Tire Problems: Old</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

39	(1) 1992 International Bus Vin #2378	<p>Unit #39 Conventional Style Passenger: 71 Engine Size/Type: DT466 International Engine In Front Diesel Has Battery Runs Automatic Transmission Type/Condition: Allison Brakes: Air Inspection Sticker Date: October 2016 Approx. Mileage (NOT ACTUAL):164,936 Interior Condition: Fair Interior Problems: Needs Cleaning - Sitting In Dusty Lot Body Condition: Fair Body Problems: Faded - Missing Parts Tires Condition: Poor Tire Problems: Old</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
----	--------------------------------------	---	---