

Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>IMPORTANT NOTICE FOR ALIEF ISD AUCTION All purchases will be subject to a 14% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</p> <p>Click Here For Covid-19 Protocol Instructions!</p> <p>Preview: (Bv Appointment Only-Mandatory-No Exceptions) Thursday, July 9, 2020 (Hours Of Operation: 9:00 a.m. – 1:00 p.m.)</p> <p>Location: Transportation Department, 6150 Snyott, Houston, TX 77083 Driving Directions</p> <p>Removal:(Bv Appointment Only-Mandatory-No Exceptions) Wednesday, July 15, 2020/Thursday, July 16, 2020/Monday, July 20, 2020 (Hours Of Operation: 9:00 a.m. - 1:00 p.m.)</p> <p>Preview & Removal Contact: Dennis Comancho 281-983-8400 x29914</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>No Forklift Or Manpower Available For Removal. Winning Bidder Is Solely Responsible For Own Removal.</p>	
1	(1) 2006 IC Bus Vin #7357 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #202 Passenger: 17 W/5 Wheelchair Spaces Engine Size/Type: 7.3 Engine Problems: Possible Computer Problems - Drive Shaft Is Sitting Inside Bus Diesel Has Battery Does Not Run Automatic Inspection Sticker Month: May 2020 Approx. Mileage (NOT ACTUAL): Unable To Read Wheel Chair Lift: Yes, Condition: Works Interior Condition: Fair Interior Problems: Some Seats Torn Body Condition: Fair Body Problems: Oxidized Paint - Peeling Paint - Surface Scratches, Rust & Dents Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

2	(1) 2002 International Bus Vin #2181 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #218 Passenger: 13 W/3 Wheelchair Spaces Engine Size/Type: 7.3 Engine Problems: Oil Leaks - Turbo Is Leaking Oil Diesel Has Battery Does Not Run Automatic Brakes: Air Inspection Sticker Month: October 2020 Approx. Mileage (NOT ACTUAL): 178,977 Wheel Chair Lift: Yes, Condition: Works Interior Condition: Fair Interior Problems: Needs Cleaning - Seats In Fair Condition Body Condition: Fair Body Problems: Oxidized Paint - Peeling On Cowl - Small Hole In Hood - Minor Dents & Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
3	(1) 2003 Ford Vin #1543	<p>Unit #927 Passenger: 2 Engine Size/Type: 3.8 V6 Engine Problems: Unknown Gas Has Battery, Dead Runs Automatic Inspection Sticker Month: September 2020 Approx. Mileage (NOT ACTUAL): 47,930 Interior Condition: Fair Interior Problems: Peeling Paint On Roof - Small Dent On Right Front Bumper - Passenger Seats Missing - Needs Cleaning Body Condition: Fair Body Problems: Surface Rust On Roof - Peeling Paint On Hood - Oxidized Paint - Small Dent On Right Front Bumper - Some Dents, Scratches & Rust - Slight Damage On Right Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

5	<p>(1) 1999 Ford E350 Superduty Box Van Vin #9196 - WILL NEED TO BE TOWED</p>	<p>WILL NEED TO BE TOWED Unit #812 Passenger: 2 Engine Size/Type: 5.4L Engine Problems: Exhaust Needs To Be Replaced Gas Has Battery Does Not Run Automatic Inspection Sticker Month: July 2019 Approx. Mileage (NOT ACTUAL): 58,416 Interior Condition: Fair Interior Problems: Both Seats Need Replacing - Needs Cleaning - Normal Wear - Drivers Side Door Needs Replacing Body Condition: Fair Body Problems: Big Holes & Dents On Box Portion Of Truck On Both Sides - Crack In Front Grill - Floor Needs Replacing Inside Box - Roof Leaks Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
6	<p>(1) 2000 International Bus Vin #5504</p>	<p>Unit #194 Passenger: 71 Engine Size/Type: 7.3 T44E Engine Problems: Unknown Diesel Has Battery, Dead Runs Automatic Inspection Sticker Month: February 2021 Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Seats Need Deep Cleaning - Some Seats Torn Body Condition: Fair Body Problems: Peeling Paint On Hood & Cowl - Oxidized Paint - Minor Dents & Scratches - Minor Damage On Hood - Left Rear Lower Panel Dented Tires Condition: Fair Tire Problems: Unknown *Ran When Last Parked*</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

7	(1) 2000 International Bus Vin #1808	<p>Unit #184 Passenger: 71 Engine Size/Type: 7.3 Engine Problems: Unknown Diesel Has Battery, Dead Runs Automatic Inspection Sticker Month: September 2020 Approx. Mileage (NOT ACTUAL): 191,064 Interior Condition: Fair Interior Problems: Seats Need Cleaning - Some Seats Torn Body Condition: Fair Body Problems: Peeling Paint - Oxidized Paint - Surface Scratches - Rock Chips & Cracks On Windshield - Missing Fuse Box Cover - Drivers Seat Needs Repair - Needs Cleaning - Dent On Lower Panel By Entry Door - Left Rear Corner Dented - Minor Damage & Hole On Hood - Tires Condition: Fair Tire Problems: Unknown *Ran When Last Parked*</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
8	(1) 2001 International Bus Vin #2173 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #209 Passenger: Has The Capacity To Fit 48 - Currently Only Fits 8 Passengers W/4 Wheelchair Spaces Engine Problems: Possible Engine & Computer Problems, Cause Unknown Diesel Does Not Run Automatic Brakes: Air Inspection Sticker Month: September 2020 Approx. Mileage (NOT ACTUAL): 190,421 Wheel Chair Lift: Yes, Condition: Works But Leaks Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Drivers Seat Body Condition: Fair Body Problems: Oxidized Paint - Rock Chips On Windshield - Peeling Paint On Hood & Cowl - Has Surface Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

9	(1) 2001 International Bus Vin #2172 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #215 Passenger: Has The Capacity To Fit 48 - Currently Only Fits 8 Passengers W/4 Wheelchair Spaces Engine Size/Type: 3800 T444E Engine Problems: Unknown Diesel Has Battery Does Not Run Automatic Brakes: Air Inspection Sticker Month: September 2019 Approx. Mileage (NOT ACTUAL): 221,202 Wheel Chair Lift: Yes, Condition: Works Interior Condition: Fair Interior Problems: Torn Drivers Seat - Seats Need Deep Cleaning Body Condition: Fair Body Problems: Peeling Paint On Cowl & Hood - Oxidized Paint - Some Scratches & Dents - Scratches & Dents On Back Bumper - Missing Mirror On Drivers Side - Large Crack On Right Side Windshield & Rock Chips Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
10	(1) 2002 Chevy Mid Bus Guide Vin #3798 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #334 Passenger: 20 Engine Size/Type: 5.7L Engine Problems: Unknown Gas Has Battery, Dead Does Not Run Automatic Inspection Sticker Month: February 2018 Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Dent On Passenger Side Past Entry Door - Missing Right Front Crossover Mirror - Indention On Lower Panel Behind Passenger Entry Door - Driver Side Door Dented Tires Condition: Fair Tire Problems: Unknown *Has Been Sitting For 4 Years*</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

11	(1) 2002 GMC Mid Bus Guide Vin #0699 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #319 Passenger: 20 Engine Size/Type: 5.7L Engine Problems: Bad Engine Gas Has Battery, Dead Does Not Run Automatic Inspection Sticker Month: October 2020 Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Needs New Sunvisor - Small Chip In Windshield Body Condition: Fair Body Problems: Oxidized Paint - Peeling Paint - Dented Panel Behind Driver Side Door Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
12	(1) 2004 Chevy Mid Bus Guide Vin #5849 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #337 Passenger: 20 Engine Size/Type: 6.0L Engine Problems: Unknown Gas Has Battery, Dead Does Not Run Inspection Sticker Month: July 2020 Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Some Seat Belts Missing - Minor Tears On Seats Body Condition: Fair Body Problems: Some Parts Missing - Oxidized Paint - Minor Scratches On Front Blinker Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

13	(1) 2006 Chevy Mid Bus Guide Vin #1795 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #308 Passenger: 21 Engine Size/Type: 6.0L Engine Problems: Missing Parts & Engine Cover - Needs Engine Gas Does Not Have Battery Does Not Run Automatic Inspection Sticker Month: June 2018 Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Missing Parts On Switch Panel - Engine Cover Present But Not Installed - Some Seat Belts Missing Body Condition: Fair Body Problems: Oxidized Paint - Left Rear Bumper Dented Tires Condition: Poor Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
14	(1) 2005 IC Bus Vin #5339 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #87 Passenger: 71 Engine Problems: Unknown Diesel Has Battery Does Not Run Automatic Brakes: Air Inspection Sticker Month: May 2018 Approx. Mileage (NOT ACTUAL): No Dash Wheel Chair Lift: Yes, Condition: Works Interior Condition: Fair Interior Problems: Parts Missing On Interior - Missing Dash Console & Possibly Other Parts - Needs Cleaning - Some Torn Seats - Torn Drivers Seat - Small Chip On Windshield - Crack On Window Behind Drivers Seat Body Condition: Fair Body Problems: Oxidized Paint - Some Scratches, Rust & Dents - Missing Rear Light Tires Condition: Fair To Poor Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

15	(1) 2005 IC Bus Vin #5342 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #97 Passenger: 71 Engine Size/Type: 6L Engine Problems: Unknown Diesel Has Battery Does Not Run Automatic Inspection Sticker Month: May 2020 Approx. Mileage (NOT ACTUAL): Unknown Wheel Chair Lift: Yes, Condition: Works Interior Condition: Fair Interior Problems: Some torn Seats - Needs Cleaning Body Condition: Fair Body Problems: Dent On Wheel On Drivers Side - Oxidized Paint - Rock Chips On Windshield - Surface Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
16	(1) 2000 International Bus Vin #1820	<p>Unit #187 Passenger: 71 Engine Size/Type: 7.3L 3800 T44E Engine Problems: Unknown Diesel Has Battery, Dead Runs Automatic Inspection Sticker Month: September 2020 Approx. Mileage (NOT ACTUAL): 194,997 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Torn - Rock Chip On Windshield - Missing Glove Box Body Condition: Fair Body Problems: Oxidized Paint - Small Dent On Left & Right Rear Corner - Dent On Right Rear Window Trim - Peeling Paint On Hood & Cowl - Crack On Hood Tires Condition: Fair Tire Problems: Unknown *Ran When Last Parked*</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

17	(1) 2000 International Bus Vin #1816	<p>Unit #183 Passenger: 71 Engine Size/Type: 3800 T44E Engine Problems: Unknown Diesel Has Battery Runs Automatic Inspection Sticker Month: September 2020 Approx. Mileage (NOT ACTUAL): 216,457 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Seats Torn & Worn Body Condition: Fair Body Problems: Oxidized Paint - Dent On Left Rear Corner - Right Side Bumper Slightly Pulled Out - Rock Chips On Windshield Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
20	(Lot) Misc. Bus Parts	<p>Bluebird Bus Steps Diesel Particular Components - Complete Unknown Muffler Clamps Donaldson Emissions Monitor - Complete Unknown</p> <p>- Current Condition Unknown</p>	
21	(1) Craftsman Commercial Drill Press	<p>(Approx. 15-1/2") Operable Model: 11324610 Missing Belt</p> <p>- Current Condition Unknown</p>	
22	(Lot) Bus Drivers Seats	<p>(Approx. 10) Mechanical Style</p> <p>- Current Condition Unknown</p>	
23	(Lot) Bumpers	<p>(1) 2015 F350 Front Bumper - New (Approx. 2) School Bus Rear Bumpers</p> <p>- Current Condition Unknown</p>	
24	(Lot) Misc. Bus Parts	<p>(Approx. 2 Pallets) Includes: Seal Band Clamps - Genisys-Scan System - Atrax Video Camera Heads For Security Cameras On Bus - Power Supply for Two Way Radio - Transmission Rebuild Tools - Oil Filters - (Approx. 6) Alternators (Rebuilt) - Transmission Filter Kits - (Approx. 3) Starters Qty Of Items Unknown</p> <p>- Current Condition Unknown</p>	
25	(Lot) Misc. Bus Parts	<p>Misc. Automotive Part - Diagnosis Repair books - Water Pumps - Ball Joints - U Joints - Motorola Radio's Qty Of Items Unknown</p> <p>- Current Condition Unknown</p>	