

Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>IMPORTANT NOTICE FOR BROWNSBORO ISD AUCTION: All purchases will be subject to a 14% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash. Cashier's Check, Money Order, Wire Transfer or Direct Deposit.</p> <p>*Social distancing will be enforced</p> <p>*Customers will not be allowed inside to use the restrooms. No Exceptions!</p> <p>*Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled.</p> <p>*We recommend wearing gloves and face mask for personal safety and health while on auction location.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, July 14, 2020 (Hours Of Operation: 7:00 a.m. - 4:00 p.m.)</p> <p>Location 1: Transportation Dept., 227 Educator Lane, Wallis, TX 77485 Driving Directions</p> <p>Removal: (By Appointment Only-Mandatory-No Exceptions) Wednesday, July 22, 2020 /Thursday, July 23, 2020/Friday, July 24, 2020 (Hours Of Operation: Wednesday: 7:00 a.m. - 4:00 p.m. – Thursday-Friday 7:00 a.m. – 12:00 p.m.)</p> <p>Preview & Removal Contact: Tim Petersen 903-904-7657</p> <p>Forklift & Driver Available For Any Items On Pallets. All Other Items Are Buyers Responsibility To Load. Buyers Need To Bring Own Batteries. Dollies & Any Tools With Them For Removal. Buyers Need To Adhere To Social Distancing, Pre-Screening & PPE In Accordance With Covid-19 Rules & Regulations.</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	
1	(Lot) Floor Burnishers	<p>(Approx. 3) Mfg. Merit/Clark Model: 2000 Electric, Single Phase, 120V, 60hz Used For Parts</p> <p>- Poor Condition</p>	
2	(Lot) Halide Lights	<p>(Approx. 7) Mfg. Luminaire Model: M59 Electric, Single Phase, 120/208/240/277V, 60hz</p> <p>- Good Condition</p>	
3	(Lot) Halide Lights	<p>(Approx. 6) Mfg. Luminaire Model: M59 Electric, Single Phase, 120/208/240/277V, 60hz</p> <p>- Good Condition</p>	
4	(Lot) Halide Lights	<p>(Approx. 6) Mfg. Luminaire Model: M59 Electric, Single Phase, 120/208/240/277V, 60hz</p> <p>- Good Condition</p>	
5	(Lot) Halide Lights	<p>(Approx. 7) Mfg. Luminaire Model: M59 Electric, Single Phase, 120/208/240/277V, 60hz</p> <p>- Good Condition</p>	

6	(Lot) Halide Lights	(Approx. 6) Mfg. Luminaire Model: M59 Electric, Single Phase, 120/208/240/277V, 60hz - Good Condition	
7	(Lot) Vacuum Cleaners	(Approx. 10) Mfg. Windsor/Clark Electric, Single Phase, 120V - Good Condition	
8	(Lot) Vacuum Cleaners	(Approx. 12) Mfg. Sonitrol/Clark Electric, Single Phase, 120V - Good Condition	
9	(1) Astro Turf	(Approx. 8' x 50' Roll) - Good Condition	
10	(Lot) Sandwich Warmer	(Approx. 2) Mfg. hatch Electric, 120V - Good Condition	
11	(Lot) Disinfectant Foggers	(Approx. 6) Mfg. Fogmaster Electric, 120V - Good Condition	
12	(1) Floor Scrubber	Mfg. Factory Cat Model: Mini Mag Electric Used For Parts - Poor Condition	
13	(Lot) Rollup Doors	(Approx. 2) (Approx. 6 x 10') - Good Condition	
14	(1) Tire Machine	Mfg. Coats - Good Condition	
15	(1) Tire Balancer	Mfg. Coats Model: 850 - Good Condition	
16	(1) Grinder	Mfg. Tool Cutter Model: CED 414 Electric, Single Phase, 120V, 60hz - Good Condition	
17	(1) Grinder	Mfg. Tool Cutter Model: CED 414 Electric, Single Phase, 120V, 60hz - Good Condition	

18	(1) Zero Turn Mower	Mfg. John Deere Model: z930 Gas Used For Parts - Poor Condition	
19	(1) Tractor	Mfg. Massey Ferguson Model: 1233 Diesel - Good Condition	
20	(Lot) Wet /Dry Vac	(Approx. 5) Mfg. Clark Electric, Single Phase, 120V, 60hz - Good Condition	
21	(1) Large Field Roller	- Good Condition	
22	(1) Small Field Roller	- Good Condition	
23	(1) Field Roller (Barrel Only)	Mfg. Agri-Fab - Good Condition	
24	(1) Plasma Table	Mfg. Plasma CAM Model: DHC Electric No Cutter With Table - Fair Condition	

25	(1) 2006 IC Bus Vin #8356 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #9 Conventional Passenger: 77 Engine Size/Type: DT466 Engine In Front Engine Problems: Fuel System Does Not have Fuel Filter Housing - Bad Injectors Diesel Does Not Have Battery Does Not Run Automatic Transmission Type: Allison Brakes: Air Inspection Sticker Date: July 2020 Approx. Mileage (NOT ACTUAL): 220,000 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Minor Dents & Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Poor Condition</p>	
26	(1) 2002 International Bus Vin #8137	<p>Unit #32 Conventional Passenger: 24 Engine Size/Type: 7.3 Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type: Allison Brakes: Hydraulic Inspection Sticker Date: July 2018 Approx. Mileage (NOT ACTUAL): 132,500 Wheel Chair Lift: Yes, - Condition: Good Interior Condition: Good Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Fair Condition</p>	

27	(1) 2000 Freightliner Bus Vin #8704	<p>Unit #53 Passenger: 67 Engine Size/Type: 5.9 Cummins Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type: Allison Brakes: Air Inspection Sticker Date: July 2018 Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Some Bad Seats Body Condition: Fair Body Problems: Missing Door Glass Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Fair Condition</p>	
28	(1) 2000 International Bus Vin #6221 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #51 Conventional Passenger: 67 Engine Size/Type: 7.3 Engine In Front Engine Problems: Radiator Bad, Leaks Diesel Does Not Have Battery Runs Automatic Transmission Type: Allison Brakes: Air Inspection Sticker Date: July 2020 Approx. Mileage (NOT ACTUAL): 148,000 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Unknown Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Fair Condition</p>	

29	(1) 1998 International Bus Vin #7859	<p>Unit #31 Conventional Passenger: 30 Engine Size/Type: 7.3 Engine In Front Engine Problems: Unknown Diesel Does Not Have Battery Runs Automatic Transmission Type: Allison Brakes: Hydraulic Inspection Sticker Date: July 2018 Approx. Mileage (NOT ACTUAL): 157,000 Wheel Chair Lift: Yes, - Condition: Good Interior Condition: Good Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Some Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Fair Condition</p>	
30	(1) 1999 Ford F350 Pickup Truck Vin #2762 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #T-10 Engine Size/Type: 7.3 Engine Problems: Fuel Pump Bad - Shift Linkage Broke Diesel Does Not Have Battery Runs Automatic Brakes: Hydraulic Inspection Sticker Date: July 2020 Approx. Mileage (NOT ACTUAL): 195,724 Interior Condition: Poor Interior Problems: Needs Cleaning - Seats Torn Body Condition: Poor Body Problems: Several Dents & Scratches - No Tailgate Tires Condition: Good Tire Problems: Unknown</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Poor Condition</p>	

31	(1) 2003 Ford Crown Victoria Vin #4238 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #Crown Vin Engine Size/Type: 4.6 Engine In Front Engine Problems: Has A Small Transmission Leak Gas Does Not Have Battery Runs Automatic Transmission Type Or Condition: Good Inspection Sticker Date: July 2017 Approx. Mileage (NOT ACTUAL): 106,974 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Needs Cleaning - Some Rust Tires Condition: Fair Tire Problems: All Tires Are Low</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Poor Condition</p>	
32	(1) Pole Vault Pit	<p>Mfg. Port A Pit - Good Condition</p>	
33	(Lot) Floor Stripper	<p>(Approx. 40) Mfg. Devastator - Good Condition</p>	