













Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>** All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR EL CAMPO I.S.D. AUCTION: **All purchases will be subject to a 8% buver's premium. However, There Will Be A 3% Administrative Fee On All Purchases Not Made By Cash, Cashier's Check, Direct Deposit, Money Order Or Wire Transfer**</p> <p>*Social distancing will be enforced</p> <p>*Customers will not be allowed inside to use the restrooms. No Exceptions!</p> <p>*Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled.</p> <p>*We recommend wearing gloves and face mask for personal safety and health while on auction location.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, July 21, 2020 (Hours of Operation: 8:00 a.m. - 4:00 p.m.)</p> <p>Location: El Campo ISD Transportation Department, 310 West Loop, El Campo, TX 77437 Driving Directions</p> <p>Removal:(By Appointment Only - Mandatory - No Exceptions) Monday, July 27, 2020/Tuesday, July 28, 2020/Thursday, July 29, 2020 (Hours Of Operation: 8:00 a.m. - 4:00 p.m.)</p> <p>Preview & Removal Contacts: Mark Freeman 979-543-5252</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Must Call & Set An Appointment For Preview & Removal. There Will Be No Assistance Available With Removal. Buyer Is Solely Responsible For Bringing Own Manpower & Loading Equipment.</p>	
1	(1) 2006 Dodge Pickup Vin #6300	<p>Engine Size/Type: 3.7 V6 Gas Has Battery Runs Automatic Inspection Sticker Month: December 2020 Approx. Mileage (NOT ACTUAL): 114,635 Interior Condition: Poor Interior Problems: Torn Seats Body Condition: Fair Body Problems: Rust Along Bed Rail Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	



2	(1) 2006 Ford Pickup Vin #8164	<p>Engine Size/Type: V6 Gas Has Battery Runs Standard Transmission Type Or Condition: Automatic/Good Brakes: Hydraulic Inspection Sticker Month: January 2021 Approx. Mileage (NOT ACTUAL): 96,587 Interior Condition: Poor Interior Problems: Torn Seats - Stained Seats Body Condition: Fair Body Problems: Rust Along Bed Rail - Dents In Front Right & Rear Right Fender Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
3	(1) 2006 Chevy Pickup Vin #4615	<p>Passenger: 5 Engine Size/Type: V8 Engine In Front Gas Has Battery Runs Automatic Transmission Type Or Condition: Automatic/Good Brakes: Hydraulic Inspection Sticker Month: March 2021 Approx. Mileage (NOT ACTUAL): 147,128 Interior Condition: Good Interior Problems: Needs Cleaning Body Condition: Good Body Problems: Minor Scratches Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	




4	(1) 2001 Dodge Cargo Van Vin #8070	<p> Passenger: 2 Engine Size/Type: 4.7L V8 Engine In Front Gas Has Battery Runs Automatic Transmission Type Or Condition: Automatic/Good Brakes: Hydraulic Inspection Sticker Month: June 2021 Approx. Mileage (NOT ACTUAL): 66,381 Interior Condition: Good Interior Problems: Drivers Seat Torn - Scratches In Cargo Area Body Condition: Fair Body Problems: Rust & Scratches In Several Areas Tires Condition: Fair </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	
5	(1) 2002 Chevy Pickup Vin #9826	<p> Passenger: 5 Engine Size/Type: 4.8L V8 Engine In Front Gas Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Hydraulic Inspection Sticker Month: December 2020 Approx. Mileage (NOT ACTUAL): 112,795 Interior Condition: Fair Interior Problems: Torn Drivers Seat - Worn Back Seat - Needs Cleaning Body Condition: Good Body Problems: Rust Along Bed Rail Where Toolbox Was Tires Condition: Fair </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	



6	(1) 2004 Ford Excursion Vin #8854	<p> Passenger: 8 Engine Size/Type: 5.4L V8 Engine In Front Gas Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Hydraulic Inspection Sticker Month: January 2021 Approx. Mileage (NOT ACTUAL): 154,336 Interior Condition: Good Interior Problems: None Body Condition: Good Body Problems: Minor Rust & Dents On Hood Tires Condition: Fair </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	
7	(1) 2007 Chevy Cargo Van Vin #2478	<p> Passenger: 2 Engine Size/Type: 4.8L V8 Engine In Front Gas Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Hydraulic Inspection Sticker Month: August 2020 Approx. Mileage (NOT ACTUAL): 48,914 Interior Condition: Good Interior Problems: None Body Condition: Fair Body Problems: Paint Peeling In Several Areas - Minor Rust On Body Tires Condition: Fair Additional Information: Food Service Serving Tray Rack Mounted To Interior Of Cargo Area - New Battery </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	



8	(1) 1997 Chevy Pickup Vin #7291	<p> Passenger: 5 Engine Size/Type: 5.0 Vortec V8 Engine In Front Engine Problems: Needs Spider Gear/Fuel Injector - Vehicle Runs But Occassionally Misfires Gas Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Hydraulic Inspection Sticker Month: March 2021 Approx. Mileage (NOT ACTUAL): 120,544 Interior Condition: Fair Interior Problems: Stains On Seats - Needs Cleaning - Drivers Seat Headrest Missing Body Condition: Fair Body Problems: Long Scratch On Rear Left Quarter Panel - Rust & Scratches On Body Tires Condition: Fair </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	
9	(1) 2008 Ford Pickup Vin #7592	<p> Passenger: 2 Engine Size/Type: 5.4L V8 Engine In Front Engine Problems: Check Engine Light Is On Due To Cylinder Misfire - Vehicle Runs Gas Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Hydraulic Inspection Sticker Month: Unknown Approx. Mileage (NOT ACTUAL): 87,136 Interior Condition: Poor Interior Problems: Seats Stained & Worn - Floor Board Worn - Needs Cleaning Body Condition: Fair Body Problems: Rust & Scratches On Hood Exterior Above Door From Where Overhead Pipe Rack Was Tires Condition: Fair </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	





10	(1) 2004 Ford Pickup Vin #5487	<p>Passenger: 5 Engine Size/Type: 6.0 Powerstroke Engine In Front Engine Problems: Runs Good - Needs To Warm Up - Needs Injector & Drivers Front Hub Diesel Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Hydraulic Inspection Sticker Month: December 2020 Approx. Mileage (NOT ACTUAL): 152,476 Interior Condition: Good Interior Problems: Stains On Seats - Needs Cleaning Body Condition: Good Body Problems: Rust On Wheel Hubs Tires Condition: Poor Tire Problems: Needs New Tires</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
11	(1) 1995 GMC Flatbed Truck Vin #9943 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Passenger: 2 Engine In Front Engine Problems: Engine Is Partially Disassembled - Needs Flywheel, Starter & Injection Pump - Lift Does Not Work Gas Has Battery, Dead Does Not Run Automatic Transmission Type Or Condition: Automatic Brakes: Hydraulic Inspection Sticker Month: 82,018 Approx. Mileage (NOT ACTUAL): 87,136 Interior Condition: Poor Interior Problems: Torn Seat Body Condition: Poor Body Problems: Paint Discoloration - Rust Tires Condition: Poor Tire Problems: Tires Appear To Hold Air But Vehicle Has Been Disable Since 2017 So Unable To verify Condition</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	




12	(1) 2016 Ford Pickup Vin #8810	<p> Passenger: 6 Engine Size/Type: 6.7 Powerstroke Engine In Front Engine Problems: Exhaust/Emission System Issue - DEF Tank Needs To Be Replaced Diesel Has Battery Runs Automatic Transmission Type Or Condition: Unknown Brakes: Hydraulic Inspection Sticker Month: November 2020 Approx. Mileage (NOT ACTUAL): 64,313 Interior Condition: Good Interior Problems: Needs Cleaning Body Condition: Good Body Problems: None Tires Condition: Good </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	
13	(1) 1996 GMC Pickup Vin #0556	<p> Passenger: 2 Engine Size/Type: 5.0 Vortec Engine In Front Engine Problems: Runs excellent - Possible Needs Master Cylinder Gas Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Hydraulic Inspection Sticker Month: May 2021 Approx. Mileage (NOT ACTUAL): 149,952 Interior Condition: Poor Interior Problems: Seat Torn - Needs Cleaning - Floorboard Worn Body Condition: Poor Body Problems: Paint Discoloration - Rust & Scratches Tires Condition: Fair </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	

14	(1) 2007 GMC Pickup Vin #4155	<p> Passenger: 2 Engine Size/Type: 6.0 Vortec Engine In Front Engine Problems: "Service Air Bag" Notice Is On Dash - Vehicle Runs Fine Gas Has Battery Runs Automatic Transmission Type Or Condition: Good Brakes: Hydraulic Inspection Sticker Month: February 2021 Approx. Mileage (NOT ACTUAL): 55,841 Interior Condition: Fair Interior Problems: Needs Cleaning - Floorboard Worn Near Gas Pedal Body Condition: Good Body Problems: Truck Previously Had A Toolbox Bed So Bed Was Replaced For Auction - Comes With Tailgate (Not Attached) Tires Condition: Fair </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	
15	(1) Tractor	<p> Mfg. Kubota Model: 3750 Diesel Runs Good - Needs Battery </p> <p>- Current Condition Unknown</p>	
16	(1) 2000 International Bus Vin #1279	<p> Unit # 1 Passenger: 65 Conventional Style Engine Size/Type: 7.3 International Engine In Front Diesel Has Battery Runs Automatic Brakes: Air Inspection Sticker Date: April 2021 Approx. Mileage (NOT ACTUAL): 198,346 Interior Condition: Fair Interior Problems: Normal Wear & Tear On Seats & Drivers Area Body Condition: Fair Body Problems: Normal Wear - Paint Discoloration Tires Condition: Fair </p> <p> There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.** </p> <p>- Current Condition Unknown</p>	

17	(1) 2004 International Bus Vin #3027	<p>Unit # 2 Passenger: 65 Conventional Style Engine Size/Type: 7.3 International Engine In Front Diesel Has Battery Runs Automatic Brakes: Air Inspection Sticker Date: April 2021 Approx. Mileage (NOT ACTUAL): 184,702 Interior Condition: Fair Interior Problems: Normal Wear & Tear On Seats & Drivers Area Body Condition: Fair Body Problems: Paint Discoloration - Peeling Paint - Minor Rust Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
18	(1) 2002 International Bus Vin #5730	<p>Unit # 13 Passenger: 65 Conventional Style Engine Size/Type: 7.3 International Engine In Front Engine Problems: Needs Injectors - Weak Battery Diesel Has Battery Runs Automatic Brakes: Air Inspection Sticker Date: April 2021 Approx. Mileage (NOT ACTUAL): 1,996,040 Interior Condition: Fair Interior Problems: Normal Wear & Tear On Seats & Drivers Area Body Condition: Fair Body Problems: Paint Discoloration - Peeling Paint - Paint Chips Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

19	(1) 2001 International Bus Vin #3650	<p>Unit # 18 Passenger: 65 Conventional Style Engine Size/Type: 7.3 Engine In Front Engine Problems: Engine Electrical Fault - Bus Dies But Runs Intermittently Diesel Has Battery Runs Automatic Brakes: Air Inspection Sticker Date: August 2020 Approx. Mileage (NOT ACTUAL): 200,474 Interior Condition: Fair Interior Problems: Normal Wear Body Condition: Fair Body Problems: Paint Discoloration - Minor Dents - Paint Chips Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
20	(1) 2004 International Bus Vin #0840	<p>Unit # 27 Passenger: 65 Conventional Style Engine Size/Type: 7.3 Engine In Front Engine Problems: Gauge Cluster Has A Fault & Doesn't Work Consistently - Bus Runs Fine Diesel Has Battery Runs Automatic Brakes: Air Inspection Sticker Date: January 2021 Approx. Mileage (NOT ACTUAL): 229,476 Interior Condition: Fair Interior Problems: Normal Wear Body Condition: Fair Body Problems: Paint Discoloration - Paint Peeling - Paint Chips Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	

21	(1) 1999 International Bus Vin #4740	<p>Unit # 61 Passenger: 65 Conventional Style Engine Size/Type: 7.3 Engine In Front Engine Problems: None Diesel Has Battery Runs Automatic Brakes: Air Inspection Sticker Date: January 2021 Approx. Mileage (NOT ACTUAL): 176,768 Interior Condition: Fair Interior Problems: Normal Wear Body Condition: Fair Body Problems: Paint Discoloration - Paint Peeling - Paint Chips Tires Condition: Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
22	(1) 2004 International Bus Vin #3028	<p>Unit # 52 Passenger: 35 Conventional Style Engine Size/Type: 7.3 Engine In Front Engine Problems: Engine Runs Excellent - Electrical Fault In Gauge Cluster - Gauges Have Intermittent Issues Diesel Has Battery Runs Automatic Brakes: Air Inspection Sticker Date: March 2021 Approx. Mileage (NOT ACTUAL): 211,597 Interior Condition: Fair Interior Problems: Normal Wear Body Condition: Fair Body Problems: Dent On Front Overhead By Flashing Light - Paint Discoloration & Wear Tires Condition: Good</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased. **All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>- Current Condition Unknown</p>	
23	(1) Zero Turn Lawn Mower	<p>Mfg. Grasshopper Model: 3220 Working Condition</p> <p>- Current Condition Unknown</p>	
24	(1) Zero Turn Lawn Mower	<p>Mfg. Kubota Model: ZG327 Diesel Working Condition</p> <p>- Current Condition Unknown</p>	

25	(Lot) Student Desks	(Approx. 100) - Current Condition Unknown	
26	(Lot) Student Desks	(Approx. 100) - Current Condition Unknown	
27	(Lot) Student Desks	(Approx. 100) - Current Condition Unknown	
28	(Lot) Student Desks	(Approx. 100) - Current Condition Unknown	