

Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>** All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR AUSTIN ISD AUCTION: **All purchases will be subject to a 13% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</p> <p>*Social distancing will be enforced</p> <p>*Customers will not be allowed inside to use the restrooms. No Exceptions!</p> <p>*Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled.</p> <p>*We recommend wearing gloves and face mask for personal safety and health while on auction location.</p> <p>*All Wifi Has Been Removed From Buildings</p> <p>*All Door Locks Have Been Removed From Buildings</p> <p>*Some Contents May Still Be Conveyed In Buildings</p> <p>*Most Of The Contents Will Be Removed From Buildings</p> <p>**Seller Disclosure** Austin ISD and Lemons Auctioneers & Online Pros recommends that all prospective buyers inspect buildings prior to bidding for structural, roof, & electrical condition, environmental hazards, and moisture intrusion. Lemons Auctioneers noted a few of the buildings had an informational plaque stating that the building has Asbestos on the floor Tiles/Mastic & sink coating. This information was noted on the lots.</p> <p>Click Here For Insurance Requirements Guideline Form</p> <p>Preview: There Is No Preview For This Auction</p> <p>Location 1 (Lots 1-7): Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 Driving Directions</p> <p>Location 2: (Lots 8-9) Langford Elementary School, 2206 Blue Meadow Dr., Austin, TX 78744 Driving Directions</p> <p>Location 3 (Lots 11-19): Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752 Driving Directions</p> <p>Location 4 (Lots 20-21): Burnet Middle School, 8401 Hathaway St., Austin, TX 78752 Driving Directions</p> <p>Location 5 (Lot 22): O. Henry Middle School, 2610 West 10th Street, Austin, TX 78703 Driving Directions</p> <p>Location 6 (Lots 23-26): Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739 Driving Directions</p> <p>Note: Prior To Bidding. Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>Removal For All Locations: (By Appointment Only - Mandatory - No Exceptions) Portables Must Be Removed By Midnight Of Monday, August 24, 2020 - There will be a \$100 late fee PER DAY if portables are not removed by deadline. (Hours Of Operation: 7:30 a.m.-11:30 a.m./1:00 p.m.-3:30 p.m.)</p> <p>Location 1 (Lots 1-7): Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 Driving Directions</p> <p>Location 2: (Lots 8-9) Langford Elementary School, 2206 Blue Meadow Dr., Austin, TX 78744 Driving Directions</p> <p>Location 3 (Lots 11-19): Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752 Driving Directions</p> <p>Location 4 (Lots 20-21): Burnet Middle School, 8401 Hathaway St., Austin, TX 78752 Driving Directions</p> <p>Location 5 (Lot 22): O. Henry Middle School, 2610 West 10th Street, Austin, TX 78703 Driving Directions</p> <p>Location 6 (Lots 23-26): Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739</p>	

[Driving Directions](#)

Preview & Removal Contact: Mark Curtis (512) 414-6061 Email: mark.curtis@austinisd.org

1	(1) Portable Building	<p>Building #1 Building ID #P-364/89pf - Room P-24/P-23 Double Approx. Size: 65' x 30' W/Eaves Restroom(s): Yes, How Many: 2 - Both Are Operable Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Zone Air Package Units Exterior Condition/Problems: Minor Scratches, Dents, Fully Skirted Interior Condition/Problems: Has Cabinet W/Sink & Closets In Both Rooms - Ceiling Tiles Are In Good Condition - Floor Tiles Are Okay - Electrical Panel In Center Of Building On Inside Entry To Building: Double Front - (1) Entry On Right Side Of Building W/Aluminum Steps Overall Condition Of Portable Building: Fair Additional Information: Has A Pass Thru Hallway Between Both Rooms</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*, *This Item Is Being Sold "As/Is", * **Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
---	-----------------------------	---	---

5	(1) Portable Building	<p>Building #5 Building ID #P-249/85pf - Rooms P1-P2 Double Approx. Size: 65' x 30' W/Eaves Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Mfg. Unknown Exterior Condition/Problems: Minor Scratches & Dents - Small Gash On Lower Panel On Left Side Approx. 5" x 5" - Dent/Gash On Left Rear Corner Interior Condition/Problems: Each Room Has (1) Cabinet W/Sink, Teachers Closet, (Approx. 3) Additional Closets & (1) Bathroom - A Few Water Spots On Ceiling Tile - Floor is Fair But Usable Condition Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*, *This Item Is Being Sold "As/Is", * **Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
---	-----------------------------	--	---

6	(1) Portable Building	<p>Building #6 Building ID #P-252/85pf - Room P-13/P-14 Double Approx. Size: 65' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Zone Aire Exterior Condition/Problems: Minor Dents & Scratches - Fully Skirted - Will Need Cleaning On Front Interior Condition/Problems: Each Classroom Has (1) Cabinet W/Sink, Bathroom, Teacher's Closet & (Approx. 3) Additional Storage Closets - Ceiling Tiles & Floor Vinyl Are Okay - Electrical Panel Located Inside Center Of Building Entry To Building: Double Front Overall Condition Of Portable Building: Fair Additional Information: Has Pass Thru Hallway Between Both Rooms</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*, *This Item Is Being Sold "As/Is",* ***Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
7	(1) Portable Building	<p>Building #7 Building ID #P051 - Rooms P-11/P-12 Double Approx. Size: 65' x 25' Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Roll On Roofing/Flat Roof Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Mfg. Unknown Exterior Condition/Problems: Some Minor Dents & Scratches - Fully Skirted Interior Condition/Problems: All Rooms Have (1) Teachers Closet, (1) Cabinet W/Sink, (Approx. 2) Additional Storage Closets - Some Tiles Are Damaged In Both Rooms - Floor Tiles Okay - Both Rooms Have A Bathroom Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Blazier Elementary School, 8601 Vertex Blvd., Austin, TX 78744 , *Condition Unknown*, *This Item Is Being Sold "As/Is",* ***Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

8	(1) Portable Building	<p>Building #8 Building ID #P531 - Room J1/J2 Double Approx. Size: 65' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Bard A/C Heat Package Units Exterior Condition/Problems: Minor Scratches & Dents - A Few Gashes On Right Side - Fully Skirted Interior Condition/Problems: Both Classrooms Have (1) Teachers Closet, (Approx. 2) Additional Storage Closets, (1) Bathroom & (1) Cabinet W/Sink - Floor Tiles Have Some Minor Damage - Ceiling Tile Panel Missing In (1) Room - Electrical Panel Is Located In Center Of Inside Building Entry To Building: Double Front Overall Condition Of Portable Building: Fair Additional Information: Has Pass Thru Hallway Between Both Rooms</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Langford Elementary School, 2206 Blue Meadow Dr., Austin, TX 78744, *Condition Unknown*, *This Item Is Being Sold "As/Is",* ***Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
9	(1) Portable Building	<p>Building #9 Building ID #P530 - Rooms K2-K1 Double Approx. Size: 65' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: The Wall Mount Package AC/Heat Unit Exterior Condition/Problems: Some Dents & Scratches - Wood Rot On Lower Door 2" x 4" Piece On Right Side Interior Condition/Problems: Some Tiles Are Damaged On Floor - Ceiling Tiles Look Okay - Both Rooms Have (1) Cabinet W/Sink, (1) Teachers Closet, (Approx. 2) Storage Cabinets & (1) Bathroom - electrical Panel Is In The Center Of Building Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Langford Elementary School, 2206 Blue Meadow Dr., Austin, TX 78744, *Condition Unknown*, *This Item Is Being Sold "As/Is",* ***Photo's And Descriptions Were Supplied By Lemons Auctioneers - Auctioneers New Policy: Any Buyer Discrepancies Must Be Reported At Seller's Physical Location - No Exceptions**</p> <p>Note: Prior To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House /Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!!***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

11	(1) Portable Building	<p>Building #11 Building ID # P190/83 - Room 7A/7B Double Approx. Size: 65' x 30 W/Eaves Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 + 1 Brand A/C Units & Type: Bard AC/Heat Package Units & (1) Window Unit Exterior Condition/Problems: On Right Rear Corner Pencil Graffiti, Will Need To Be Painted - Pencil Or Scratch Graffiti On Right Side - Fully Skirted Interior Condition/Problems: 7A: (1) Room Has Been Divided Into 2 Rooms & Has (1) Bathroom, (1) Cabinet W/Sink, (1) Storage Cabinet - Water Stains On Tile - Floor Okay - 7B: Room Type Unknown /No Key For Entry Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
12	(1) Portable Building	<p>Building #12 Building ID #P-296 - Room 6A/6B Double Approx. Size: 65' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Mfg. Unknown Exterior Condition/Problems: Minor Dents & Scratches - Center Rear Lower Panel Large Dent, Approx. 20" - Fully Skirted Interior Condition/Problems: Some Soft Spots On Tile - Some Floor Tiles Are Damaged - Both Rooms Have (1) Cabinet W/Sink, (1) Teachers Cabinet, (Approx. 3) Storage Closets & (1) Bathroom Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

13	(1) Portable Building	<p>Building #13 Building ID #P-227/84pf - Rooms 5A/5B Double Approx. Size: 65' x 30' W/Eaves Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Bard AC/Heat Package Unit Exterior Condition/Problems: Damage On Siding On Left Corner - Dents & Some Surface Scratches - Rotted Wood Under (1) Entry Door Interior Condition/Problems: Both Rooms Have A Cabinet W/Sink, Bathroom & Storage Cabinets - Some Damage On Floor Tile - Some Water Stains On Ceiling Tile Entry To Building: Double Front Overall Condition Of Portable Building: Fair Additional Information: Has Pass Thru Hallway Between Both Rooms - Has Asbestos Floor Tile & Mastic & Sink Coating Noted On Small Plaque</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
15	(1) Portable Building	<p>Building #15 Building ID # P-099/70pf - Rooms 3A/3B Double Approx. Size: 65' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Wood A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Mfg. Unknown Exterior Condition/Problems: Minor Dents & Surface Scratches - Fully Skirted Interior Condition/Problems: Both Rooms Have Storage Cabinets/No Closets, (1) Bathroom, (1) Cabinet W/Sink - Floor Tiles Okay - Ceiling Tiles Have Some Water Stains Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

16	(1) Portable Building	<p>Building #16 Building ID # P-301/87pf - Rooms 12A/12B Double Approx. Size: 65' x 30' W/ Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Wood A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Bard AC/Heat Package Units Exterior Condition/Problems: Minor Dents & Scratches - Fully Skirted Interior Condition/Problems: Both Rooms Have (1) Bathroom, (1) Cabinet W/Sink Entry To Building: Double Front Overall Condition Of Portable Building: Fair Additional Information: Has Plaque That States The Building Has Asbestos On Floor Tile/Mastic</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
17	(1) Portable Building	<p>Building #17 Building ID # P-239/85pf - Rooms 11A/11B Double Approx. Size: 65' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Wood A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Bard AC/Heat Package Units Exterior Condition/Problems: Minor Dents & Scratches - Fully Skirted Interior Condition/Problems: Both Rooms Have Storage Cabinets, (1) Bathroom, (1) Cabinet W/Sink - Ceiling Tiles & Floor Okay Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

19	(1) Portable Building	<p>Building #19 Building ID # P-476/94pf Double Approx. Size: 65' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Wood A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Bard AC/Heat Package Unit Exterior Condition/Problems: Some Minor Scratches & Dents - Fully Skirted Interior Condition/Problems: Both Rooms Have (1) Teachers Closet, (Approx. 3) Additional Closets, (1) Bathroom, (1) Cabinet W/Sink - Some Damage On Floor Tiles - Ceiling Tiles Okay Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Barrington Elementary School, 400 Cooper Dr., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
20	(1) Portable Building	<p>Building #20 Building ID # P-068/64pf - Rooms P-501/P-503 Double Approx. Size: 65' x 30' W/Eaves Restroom(s): No Classroom(s): Yes, How Many: 2 Type Of Siding: Hardi Panel & Lap Board & Metal/Pressboard Type Of Roof: Flat Roof/Roll On Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Package AC/Heat Unit Exterior Condition/Problems: Some Scratches & Pencil Graffiti On Left Side Interior Condition/Problems: Both Rooms Have Some Ceiling Tile Damage, (1) Storage Closet - Floor Appears Okay Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Burnet Middle School, 8401 Hathaway St., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

21	(1) Portable Building	<p>Building #21 Building ID # P-021/56 - Rooms 613/615 Double Approx. Size: 65' x 30' W/Eaves Restroom(s): No Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Flat Roof/Roll On Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Bard/The Wall Mount AC/Heat Package Trimboard Units (Recently Replaced) & (Approx. 2) Window A/C Units Exterior Condition/Problems: Some Rotted Wood Around Base - Fully Skirted Interior Condition/Problems: Room #1 Has (Approx. 2) Closets & (Approx. 2) Room Offices On End Of Building - Ceiling Tiles & Floor Tiles Okay Entry To Building: Double Front + (1) Entry On Right Side Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Burnet Middle School, 8401 Hathaway St., Austin, TX 78752, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
22	(1) Portable Building	<p>Building #22 Building ID # P-066/64 - Rooms P6/P7 Double Approx. Size: 65' x 28' Restroom(s): No Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Flat Roof/Roll On Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Bard AC/Heat Package Units - (1) Not Working Exterior Condition/Problems: Built On Front Awning Has Rotted Wood - Wood Rot On Eaves - Scratches & Dents - Fully Skirted Interior Condition/Problems: Both Rooms Have (1) Teachers Closet, (Approx. 3) Additional Closets - Floor Tiles Looks Okay - Some Ceiling Tiles Are Damaged Entry To Building: Double Front Overall Condition Of Portable Building: Fair Additional Information: Has Pass Thru Hallway Between Both Rooms - Has Plaque That States Building Contains Asbestos Building Materials - 9x9 Floor Tiles/Mastic Decked Over W/NAD - 12x12 Tile/Mastic</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: O. Henry Middle School, 2610 West 10th Street, Austin, TX 78703, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

23	(1) Portable Building	<p>Building #23 Building ID # P-311 - Rooms P11A/P11B Double Approx. Size: 68' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown Exterior Condition/Problems: Surface Scratches - Minor Dents - fully Skirted - Some Rotted Wood On Base Of Siding - Gutter Damage Above Door Interior Condition/Problems: Both Rooms Have Storage Cabinets/No Closet, (1) Bathroom, (1) Cabinet W/Sink - Floor & Ceiling Tiles Okay Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
24	(1) Portable Building	<p>Building #24 Building ID # P-229/84 pf - Rooms P-9A/P-9B Double Approx. Size: 68' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Marvair Package AC/Heat Units Exterior Condition/Problems: Some Scratches & Minor Dents - Fully Skirted Interior Condition/Problems: Both Rooms Have (1) Bathroom, (1) Cabinet W/Sink - Ceiling Tiles & Floor Tiles Okay - Storage Cabinets & Built In Bookcases Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Additional Information: Asbestos Noted In Building M&S 12x12 Cream & Brown Tile & White Specks Wood Floor, Sink Coating (Pink)</p> <p>Location: Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	

25	(1) Portable Building	<p>Building #25 Building ID # P-185/82 pf - Rooms 8A/8B Double Approx. Size: 65' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Classroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Bard AC/Heat Package Units Exterior Condition/Problems: Dent On Rear Left Corner - Some Scratches & Minor Dents - (1) Meal Eave Corner On Right Side Dented - Fully Skirted Interior Condition/Problems: Some Tiles Are Damaged - Floor tiles Okay - Both Rooms Have (1) Teachers Closet, (Approx. 2) Additional Closets, (1) Bathroom, (1) Cabinet W/Sink Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD* Additional Information: Has Pass Thru Hallway Between Both Rooms</p> <p>Location: Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	
26	(1) Art Deco Building /Classroom /Studio	<p>Building #26 Building ID # P-422/91 pf Double Approx. Size: 65' x 30' W/Eaves Restroom(s): Yes, How Many: 2 Type Of Siding: Metal/Pressboard Type Of Roof: Composition Skid: Unknown A/C Unit(s): Yes, How Many: 2 Brand A/C Units & Type: Bard AC/Heat Package Units Exterior Condition/Problems: Minor Scratches & Dents Interior Condition/Problems: Some Floor Tiles Are Damaged - Will Need Some Paint - Both Rooms Have (1) Teachers Closet, (1) Bathroom, (1) Cabinet W/Sink Entry To Building: Double Front Overall Condition Of Portable Building: Fair</p> <p>*Some Items In Buildings May Convey With Building. It Is Up To The Discretion Of Austin ISD*</p> <p>Location: Kiker Elementary School, 5913 La Crosse Ave., Austin, TX 78739, To Bidding, Buyer Will Need To Get A Quote On The Cost Of Moving From A House/Building Mover Prior To Bidding. This Information Must Be Provided To Lemons Auctioneers, LLC Prior To Bidding - No Exceptions!! ***The Cost And Removal Of Each Building Is The Sole Responsibility Of The Buyer, And Should Be Obtained Prior To Bidding On Our Online Auction Site. Please Contact A Structural Mover In Your Area. Note That The Structural Mover Is Required To Meet The Minimum Insurance Requirements By Austin ISD And Must Contact Austin ISD For Requirement Information.*** Lemons Auctioneers 281-357-4977</p> <p>- Current Condition Unknown</p>	