











Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>** All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR NORTHSIDE ISD AUCTION: All purchases will be subject to a 14% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</p> <p>*Social distancing will be enforced *Customers will not be allowed inside to use the restrooms. No Exceptions! *Please schedule an appointment prior to removal. Customers may be turned away without an appointment scheduled. *We recommend wearing gloves and face mask for personal safety and health while on auction location.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, September 15, 2020 (Hours Of Operation: 8:00 a.m. - 12:00 p.m.) Location: McClung Transportation Station, 14173 Old FM 471, San Antonio, TX 78253 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Monday, September 21, 2020/Tuesday, September 22, 2020/Wednesday, September 23, 2020 (Hours Of Operation: 8:00 a.m. - 12:00 p.m.) Preview & Removal Contact: Xavier Quintero 210-825-2985 & Michael Butler 210-825-2967</p> <p>Winning Bidder Solely Responsible For Removal. No Assistance Is Provided.</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p>	

1	(1) 1999 GMC Bluebird Bus Vin #2521	<p>Unit #59 Conventional Style Passenger: 71 Engine Size/Type: 454 Engine In Front Engine Problems: Ran While In Service Propane Has Battery, Dead Runs Automatic Transmission Type Or Condition: Auto - Runs Fair Brakes: Air Approx. Mileage (NOT ACTUAL): 157,490 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Dents And Scratches - Rear Bumper Pushed In Tires Condition: Fair Tire Problems: Older Than 5 Years Additional Information: Bus Was Running When Last Parked - Out Of Service Since 2019 - Current Condition Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
2	(1) 1999 GMC Bluebird Bus Vin #2046	<p>Unit #63 Conventional Style Passenger: 71 Engine Size/Type: 454 Engine In Front Engine Problems: Ran While In Service Propane Has Battery, Dead Runs Automatic Transmission Type Or Condition: Runs Fair Brakes: Air Approx. Mileage (NOT ACTUAL): 172,271 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Dents, Scratches & Faded Paint Tires Condition: Fair Tire Problems: Older Than 5 Years Additional Information: Bus Was Running When Last Parked - Out Of Service Since 2019 - Current Condition Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	

3	(1) 2000 GMC Bluebird Bus Vin #5212	<p>Unit #67 Conventional Style Passenger: 47 Engine Size/Type: 454 Engine In Front Engine Problems: Ran While In Service Propane Has Battery, Dead Runs Automatic Transmission Type Or Condition: Runs Fair Approx. Mileage (NOT ACTUAL): 186,403 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Dents And Scratches Tires Condition: Fair Tire Problems: Old Additional Information: Bus Was Running When Last Parked - Out Of Service Since 2018 - Current Condition Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
4	(1) 2001 GMC Bluebird Bus Vin #8543 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #402 Conventional Style Passenger: 47 Engine Size/Type: 8.1 Engine In Front Engine Problems: Does Not Start - Missing Parts Gas & Propane Has Battery, Dead Does Not Run Automatic Transmission Type Or Condition: Runs Fair - Old Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 185,538 Interior Condition: Poor Interior Problems: Missing Dash Parts - Missing Instrument Cluster - Needs Cleaning Body Condition: Fair Body Problems: Floor Rotted - Rear Door Bent - Windows Missing Tires Condition: Fair Tire Problems: Old - Holds Air Additional Information: Bus Needs To Be Towed - Unit Has AC, Was Working When Last Parked</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	

5	(1) 2002 GMC Bluebird Bus Vin #0744	<p>Unit #407 Conventional Style Passenger: 47 Engine Size/Type: 8.1 Engine In Front Engine Problems: Runs Well Gas & Propane Has Battery, Dead Runs Automatic Transmission Type Or Condition: Runs Fair, Old Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 127,741 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats - Floor Rotted Body Condition: Fair Body Problems: Dents Tires Condition: Fair Tire Problems: Old, Used Additional Information: Bus Was Running When Last Parked - Out Of Service Since 2018 - Unit Has AC, Was Working When Last Parked - Current Condition Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
6	(1) 2001 GMC Bluebird Bus Vin #9014 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #81 Conventional Style Passenger: 71 Engine Size/Type: 8.1 Engine In Front Engine Problems: Engine Blown Gas & Propane Has Battery, Dead Does Not Run Automatic Transmission Type Or Condition: Runs Fair Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 182,470 Interior Condition: Fair Interior Problems: Torn Seats - Needs Cleaning Body Condition: Fair Body Problems: Dents & Scratches Tires Condition: Fair Tire Problems: Old Additional Information: Bus Needs To Be Towed</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	

7	(1) 1999 GMC Bluebird Bus Vin #2173	<p>Unit #449 Conventional Style Passenger: 71 Engine Size/Type: 454 Engine In Front Engine Problems: Unknown Propane Has Battery, Dead Runs Automatic Transmission Type Or Condition: Runs Fair Brakes: Air Approx. Mileage (NOT ACTUAL): 176,894 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats Body Condition: Fair Body Problems: Dents, Scratches & Faded Paint Tires Condition: Fair Tire Problems: Old Additional Information: Bus Was Running When Last Parked - Out Of Service Since 2018 - Current Condition Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
8	(1) 1999 Chevy Bluebird Bus Vin #5894 - WILL NEED TO BE TOWED	<p>WILL NEED TO BE TOWED Unit #448 Conventional Style Passenger: 47 Engine Size/Type: 454 Engine In Front Engine Problems: Missing Catalytic Converter Propane Has Battery, Dead Runs Automatic Transmission Type Or Condition: Runs Fair Brakes: Hydraulic Approx. Mileage (NOT ACTUAL): 176,372 Interior Condition: Fair Interior Problems: Torn Seats - Needs Cleaning - Rear View Mirror Cracked Body Condition: Fair Body Problems: Dents & Scratches Tires Condition: Fair Tire Problems: Old Additional Information: Will Start But Missing Catalytic Converter</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	

9	(1) 2000 GMC Bluebird Bus Vin #5701	<p>Unit #455 Conventional Style Passenger: 71 Engine Size/Type: 454 Engine In Front Engine Problems: Low Compression On One Cylinder - Runs With Low Power Propane Has Battery, Dead Runs Automatic Transmission Type Or Condition: Runs Fair Brakes: Air Approx. Mileage (NOT ACTUAL): 134,958 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats Body Condition: Fair Body Problems: Dents, Scratches & Faded Paint Tires Condition: Fair Tire Problems: Old Additional Information: Runs With Low Power</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	
10	(1) 1999 GMC Bluebird Bus Vin #2089	<p>Unit #451 Conventional Style Passenger: 71 Engine Size/Type: 454 Engine In Front Engine Problems: Low Compression On Two Cylinders - Runs With Low Power Propane Has Battery, Dead Runs Automatic Transmission Type Or Condition: Runs Fair Brakes: Air Approx. Mileage (NOT ACTUAL): 169,931 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats Body Condition: Fair Body Problems: Dents & Scratches Tires Condition: Fair Tire Problems: Old Additional Information: Runs With Low Power</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/Or Removed</p> <p>- Current Condition Unknown</p>	