

Lot Number	Title	Description	Thumbnail
0	Preview & Removal Information	<p>** All Winning Bidders Will Be Invoiced After 3pm The Day The Auction Closes**</p> <p>IMPORTANT NOTICE FOR ALDINE ISD AUCTION:**All purchases will be subject to a 14% buyer's premium. There Will Be A 3% Administrative Fee For Purchases Not Made By Cash, Cashier's Check, Money Order, Wire Transfer or Direct Deposit.**</p> <p>Preview Location: (By Appointment Only-Mandatory-No Exceptions) Wednesday, November 4, 2020 (Hours Of Operation: 8:00 a.m. - 5:00 p.m.)</p> <p>**Items Not Removed By Deadline Will Be Forfeited & No Refund Will Be Issued**</p> <p>Location: Westside Transportation, 9900 Antoine, Houston, TX 77086 Driving Directions. Removal: (By Appointment Only - Mandatory - No Exceptions) Monday, November 9, 2020 /Tuesday, November 10, 2020/Wednesday, November 11, 2020 (Hours Of Operation: 8:00 a.m. - 5:00 p.m.) Preview & Removal Contacts: Brett Dishong 281-878-7814 or Lonny Hornsby 281-878-7815</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>	
1	(1) 1998 International School Bus Vin #8097 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #778 Passenger: 72 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Approx. Mileage (NOT ACTUAL): 14,326 Interior Condition: Fair Interior Problems: Side Electric Panel Removed - Wires Exposed - Rust - Needs Cleaning - Seats Torn Body Condition: Fair Body Problems: Missing Front Mirror On Passenger Side - Peeling Paint - Oxidized Paint - Scratches - Dents - Rust On Rear Front Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

2	(1) 1996 International School Bus Vin #7900 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #133A Passenger: Unknown Engine Size/Type: 3800 T44E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: October 2018 Approx. Mileage (NOT ACTUAL): 325,693 Interior Condition: Poor Interior Problems: Possible Parts Missing Above Drivers Side On Top - Torn Drivers Seat - Needs Cleaning - Torn Seats - Buttons Missing On Control Panel Body Condition: Fair Body Problems: Scratches - Dents - Rust - Oxidized & Peeling Paint - Rust On Front & Rear Bumpers Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
3	(1) 2003 Freightliner School Bus Vin #1115 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #243A Passenger: Unknown Engine Size/Type: Unknown Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: July 2018 Approx. Mileage (NOT ACTUAL): 263,157 Interior Condition: Fair Interior Problems: Needs Cleaning - Control Panel Door Open - Wires Exposed - Missing Parts On Dash - A/C Cover Removed In Back Body Condition: Fair Body Problems: Scratches - Dents - Rust - Cracked Windshield - Oxidized & Peeling Paint - Dents In Rear Bumper On Both Sides Behind Wheels Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

4	<p>(1) 1996 International School Bus Vin #7895 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #118A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 284,678 Interior Condition: Fair Interior Problems: Needs Cleaning - Control Panel Removed - Wires Exposed - Rust - Torn Seats Body Condition: Fair Body Problems: Scratches - Dents - Rust - Dent In Rear & Front Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
5	<p>(1) 2003 Freightliner School Bus Vin #1136 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #248A Passenger: 47 Engine Size/Type: 5.9L-L-6 Diesel Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2019 Approx. Mileage (NOT ACTUAL): 306,255 Interior Condition: Poor Interior Problems: Needs Cleaning - Missing Drivers Seat - Control Panel Open - Exposed Wires - Has Rust Body Condition: Fair Body Problems: Scratches - Dents - Rust - Oxidized Paint - Dents On Both Sides In Back Behind Wheels - Rust On Front Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

6	<p>(1) 2001 International School Bus Vin #5105 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #226A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: July 2019 Approx. Mileage (NOT ACTUAL): 24,524 Interior Condition: Fair Interior Problems: Needs Cleaning - Control Panel Removed - Wires Exposed - Torn Seats - Has Rust Body Condition: Fair Body Problems: Scratches - Dents - Rust - Oxidized & Peeling Paint - Rust On Front & Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
7	<p>(1) 1996 International School Bus Vin #7894 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #117A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: March 2018 Approx. Mileage (NOT ACTUAL): 262,049 Interior Condition: Fair Interior Problems: Needs Cleaning - Soft Spot In Floor By Drivers Seat - Control Panel Missing Buttons - Has Rust - Torn Seats - Missing Window On Seat #5 - A/C Cover Is Missing Body Condition: Fair Body Problems: Scratches - Dents - Rust - Oxidized & Peeling Paint - Rust On Front Bumper - Peeling Paint On Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

8	(1) 1995 International School Bus Vin #3570 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #110A Passenger: 47 Engine Size/Type: 7.3L/V-8 Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 305,758 Interior Condition: Fair Interior Problems: Needs Cleaning - Missing Buttons On Control Panel - Has Rust - Exposed Wires Body Condition: Fair Body Problems: Scratches - Dents - Rust - Oxidized & Peeling Paint - Rust On Front & Rear Bumpers Tires Condition: Fair Tire Problems: Unknown Additional Information: No Ignition - No Key</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
9	(1) 2001 International School Bus Vin #5112 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #59A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2019 Approx. Mileage (NOT ACTUAL): 7,043 Interior Condition: Fair Interior Problems: Needs Cleaning - Has Rust - Exposed Wires - Torn Seats - A/C Cover Off Body Condition: Fair Body Problems: Scratches - Dents - Rust - Oxidized & Peeling Paint - Rust On Front & Rear Bumpers Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

10	(1) 1999 International School Bus Vin #3263 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #210A Passenger: 47 Engine Size/Type: 7.3L/V-8 Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2019 Approx. Mileage (NOT ACTUAL): 232,436 Interior Condition: Fair Interior Problems: Needs Cleaning - Has Rust - Control Panel Open - Exposed Wires Body Condition: Fair Body Problems: Scratches - Dents - Rust - Rust & Scratches On Rear Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
11	(1) 2003 Freightliner School Bus Vin #1117 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #257A Passenger: 47 Engine Size/Type: Unknown Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2019 Approx. Mileage (NOT ACTUAL): 293,177 Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Drivers Seat - Control Panel Out- Exposed Wires Body Condition: Fair Body Problems: Scratches - Dents - Rust - Cracked Windshield - Rust On Front & Back Bumper - Oxidized & Peeling Paint - Dents On Both Sides Of Bumper In Back Behind Wheels Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

12	(1) 2001 International School Bus Vin #5116 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #233A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: March 2020 Approx. Mileage (NOT ACTUAL): Dash Has Been Removed/Not Available Interior Condition: Fair Interior Problems: Needs Cleaning - Torn Seats - Control Panel Open - Exposed Wires - Has Rust - Dash Panel Missing Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Rust On Front & Rear Bumpers Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
13	(1) 1995 International School Bus Vin #3566 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #106A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 273,991 Interior Condition: Fair Interior Problems: Needs Cleaning - Exposed Wires - Has Rust - Buttons Missing On Control Panel - Missing Both A/C Covers - Soft Spot On Floor By Drivers Seat Body Condition: Fair Body Problems: Scratches - Dents - Rust - Oxidized Paint - Rust On Front & Back Bumpers - Dent On Quarter Panel Behind Wheel - Dent On Back Bumper - Missing Both Side Mirrors In Front Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

14	(1) 1998 International School Bus Vin #0696 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #165A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: January 2020 Approx. Mileage (NOT ACTUAL): 302,?43 Interior Condition: Poor Interior Problems: Needs Cleaning - Control Panel Open - Exposed Wires - Has Rust - Torn Drivers Seat - Ignition Panel Loose Body Condition: Fair Body Problems: Oxidized Paint - Rust On Front & Back Bumpers - Emergency Door Dented In Back - Dent On Back Passenger Side Quarter Panel Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
16	(1) 1998 International School Bus Vin #0705 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #174A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2020 Approx. Mileage (NOT ACTUAL): 281,381 Interior Condition: Fair Interior Problems: Needs Cleaning - Control Panel Loose - Exposed Wires - Has Rust - Torn Drivers Seat Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Rust On Front & Back Bumpers - Dent Next To Gas Tank - Dent On Front Of Quarter Panel On Passenger Side - Rust On Front & Back Bumper - Hydraulics Are Bad On Hood (Does Not Stay Closed) Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

17	<p>(1) 1999 International School Bus Vin #3277 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #179A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2019 Approx. Mileage (NOT ACTUAL): 7,710 Interior Condition: Fair Interior Problems: Needs Cleaning - Control Panel Open & Missing Buttons - Exposed Wires Body Condition: Fair Body Problems: Rust On Front & Rear Bumpers - Scratches - Dents - Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
18	<p>(1) 2002 AmTran School Bus Vin #8326 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #633 Passenger: 72 Engine Size/Type: 7.3L/V-8 Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: April 2019 Approx. Mileage (NOT ACTUAL): 1,201 Interior Condition: Poor Interior Problems: Needs Cleaning - Control Panel Open - Exposed Wires - Missing Entry Door & Steps Body Condition: Fair Body Problems: Oxidized Paint - Rust On Front & Rear Bumpers - Dent On Rear Passenger Side Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

19	(1) 2003 Freightliner School Bus Vin #1131 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #242A Passenger: 47 Engine Size/Type: 5.9L/L-6 Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: April 2019 Approx. Mileage (NOT ACTUAL): 254,032 Interior Condition: Fair Interior Problems: Needs Cleaning - Control Panel Open - Exposed Wires - Torn Drivers Seat Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Rust On Front & Rear Bumpers - Emergency Door Dented - Scratches - Dents - Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
20	(1) 2001 International School Bus Vin #5114 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #229A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2019 Approx. Mileage (NOT ACTUAL): 307,183 Interior Condition: Poor Interior Problems: Control Panel Damaged - Torn Drivers Seat - Missing Dash Panels Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Rust On Front & Rear Bumpers - Scratches - Dents - Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

21	(1) 1998 International School Bus Vin #9727 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #150A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: April 2019 Approx. Mileage (NOT ACTUAL): 8,420 Interior Condition: Fair Interior Problems: Control Panel Open - Exposed Wires - Some Tears On Drivers Seat - Has Rust - Shattered Glass In Back Of Bus In Aisle Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Rust On Front & Rear Bumpers - Dent On Emergency Door - Scratches - Dents - Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
22	(1) 1998 International School Bus Vin #8096 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #777 Passenger: 72 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): Missing Dash Panel Interior Condition: Poor Interior Problems: Missing Drivers Seat - Control Panel Open - Exposed Wires - Needs Cleaning - Has Rust - Missing Dash Panel - Missing A/C Cover Body Condition: Fair Body Problems: Oxidized Paint - Dents - Scratches - Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

23	(1) 2005 Bluebird School Bus Vin #6294 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #82A Passenger: 47 Engine Size/Type: Unknown Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: March 2019 Approx. Mileage (NOT ACTUAL): No Battery/Unavailable Interior Condition: Fair Interior Problems: Control Panel Open - Exposed Wires - Needs Cleaning - Has Rust - Drivers Seat Worn Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Scratches - Dents - Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
24	(1) 2005 Bluebird School Bus Vin #6295 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #269A Passenger: 47 Engine Size/Type: 7.2L/L-6 Engine In Front Engine Problems: Unknown - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2020 Approx. Mileage (NOT ACTUAL): No Battery/Not Available Interior Condition: Poor Interior Problems: Control Panel Open - Exposed Wires - Needs Cleaning - A/C Cover Off - Drivers Seat Torn Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Dent On Drivers Side Between Front & Back Tires - Rust On Front & Back Bumpers - Dents & Scratches On Passenger Side Rear Panel Tires Condition: Fair Tire Problems: Unknown Additional Information: Has Bad Ignition Switch</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

25	(1) 1996 International School Bus Vin #7907 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #138A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2019 Approx. Mileage (NOT ACTUAL): 144,043 Interior Condition: Fair Interior Problems: Missing buttons On Control Panel - Has Rust - Torn Drivers Seat - Needs Cleaning - Soft Spot On Floor By Drivers Seat Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Cover Missing For Stop Sign Controls - Rust On Front & Back Bumpers - Dent Above Flashing Lights On Passenger Side Roof Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
26	(1) 1998 International School Bus Vin #9720 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #159A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: April 2020 Approx. Mileage (NOT ACTUAL): 7,485 Interior Condition: Fair Interior Problems: Control Panel Open - Exposed Wires - Has Rust - Needs Cleaning Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Rust On Front & Back Bumpers - Crack On Drivers Side Rear In Front Of Bumper Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

27	(1) 1996 International School Bus Vin #7899 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #135A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: July 2018 Approx. Mileage (NOT ACTUAL): 118,537 Interior Condition: Poor Interior Problems: Control Panel Open - Exposed Wires - Has Rust - Needs Cleaning - Soft Spot On Floor By Drivers Seat - Broken Drivers Side Window - Dashboard Is Loose Under Steering Wheel - Broken Glass On Entry Door Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Rust On Front & Back Bumpers - Broken Drivers Side Headlight - Dent On Drivers Side Behind Wheel - Missing Tail Light Cover Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
28	(1) 1998 International School Bus Vin #9719 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #168A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2020 Approx. Mileage (NOT ACTUAL): 21,165 Interior Condition: Poor Interior Problems: Control Panel Open - Exposed Wires - Needs Cleaning - Both A/C Covers Off - Missing Some Dash Panel Covers Body Condition: Fair Body Problems: Oxidized Paint - Rust On Front & Back Bumpers - Back Bumper Dented On Drivers Side - Emergency Door Warped (Does Not Close) - Rust - Dents - Scratches Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

30	(1) 2001 International School Bus Vin #5286 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #827 Passenger: 47 Engine Size/Type: Unknown Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: July 2019 Approx. Mileage (NOT ACTUAL): 2,705 Interior Condition: Poor Interior Problems: Control Panel Open - Exposed Wires - Needs Cleaning - Torn Drivers Seat - Both A/C Covers Off - Metal Panel Sticks Out When You Walk In The Door - Has Rust Body Condition: Fair Body Problems: Rust On Front & Back Bumpers - Dent On Back Bumper - Peeling Paint On Roof Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
31	(1) 2001 AmTran School Bus Vin #5308 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #767 Passenger: 47 Engine Size/Type: 7.3L/V-8 Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: September 2019 Approx. Mileage (NOT ACTUAL): 16,464 Interior Condition: Fair Interior Problems: Control Panel Open - Exposed Wires - Needs Cleaning - Buttons Missing On Dash & Control Panel - Has Rust - Worn Drivers Seat - A/C Cover Is Off Body Condition: Fair Body Problems: Oxidized Paint - Rust On Front & Back Bumpers Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

32	(1) 1998 International School Bus Vin #0706 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #173A Passenger: 47 Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: May 2020 Approx. Mileage (NOT ACTUAL): 254,453 Interior Condition: Fair Interior Problems: Control Panel Off - Exposed Wires - Needs Cleaning - Has Rust Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Rust On Front & Back Bumpers - Rust - Scratches - Dents Tires Condition: Fair Tire Problems: Flat On Front Passenger Side - All Other Tires Are Fair</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
33	(1) 2001 AmTran School Bus Vin #5288 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #680 Passenger: 47 Engine Size/Type: 7.3L/V-8 Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: October 2019 Approx. Mileage (NOT ACTUAL): 129,675 Interior Condition: Fair Interior Problems: Needs Cleaning - Has Rust - Missing Buttons On Control Panel - Rip In Drivers Seat Body Condition: Fair Body Problems: Oxidized Paint - Scratches On Drivers Side Hood Above Headlight - Some Rust On Rear Bumper - Rust - Scratches - Dents Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

34	(1) 1995 International School Bus Vin #6278 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #722 Passenger: Unknown Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: July 2019 Approx. Mileage (NOT ACTUAL): Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Has Rust - Control Panel Damaged (Will Not Close) - Part Of Dash Panel Missing - Exposed Wire - Hole In Drivers Seat Body Condition: Fair Body Problems: Oxidized & Peeling Paint - Rusted Front & Rear Bumpers -Dents On Driver & Passenger Side Behind Wheels Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
35	(1) 1996 International School Bus Vin #9702 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #144A Passenger: Unknown Engine Size/Type: 3800 T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 186,954 Has Wheel Chair Lift - Condition Unknown Interior Condition: Poor Interior Problems: Dash Panel Missing - Exposed Wires - Needs Cleaning - Has Rust - Only Has 1 Seat Body Condition: Poor Body Problems: Oxidized & Peeling Paint - Tint Peeling On Windows - Shattered Glass On Back Emergency Door - Scratches - Dents - Rust Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

36	(1) 1998 International Crown By Carpenter School Bus Vin #0702 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #172A Passenger: 43 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: May 2020 Approx. Mileage (NOT ACTUAL): 35,587 Interior Condition: Fair Interior Problems: Needs Cleaning - Minor Torn Seats - Possible Parts Missing Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Scratches & Dents On Right Rear Corner Panel - Indention On Rear Bumper - Roof Is Oxidized & Peeling On Rack - Scratches On Cowl & Hood - Chips In Windshield - Scratches & Dents On Right Rear Corner Tires Condition: Fair to Poor Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
37	(1) 1999 International Bluebird School Bus Vin #3269 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #200A Passenger: 47 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: December 2019 Approx. Mileage (NOT ACTUAL): Dash Is Missing - Unable To Read Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Possible Parts Missing - Dash Missing - Drivers Side Cover Missing Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Minor Indention In Rear Bumper - Battery Cover Loose & Inside Bus - Rock Chips On Windshield - Possible Parts Missing Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

38	(1) 1995 International School Bus Vin #3574 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #114A Passenger: 47 Engine Size/Type: 7.3L/V-8 Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 330,280 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Possible Parts Missing - Floor Worn In Drivers Area Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Roof Paint Is Peeling & Needs Cleaning - Missing (2) Lights In Rear - Rock Chips On Windshield - Peeling On Cowl & Hood - Possible Parts Missing Tires Condition: Fair Tire Problems: Unknown Additional Information: No Ignition - No Key</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
39	(1) 1995 International School Bus Vin #3572 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #112A Passenger: 47 Engine Size/Type: T444 Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): No Dash - Unable To Verify Interior Condition: Fair Interior Problems: Needs Cleaning - Possible Parts Missing - No Dash - Loose Panels - Loose Entry Step Light Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Rock Chips On Windshield - Peeling On Cowl & Hood - Possible Parts Missing - Roof Has Some Peeling Paint & Needs Cleaning - Large Dent In Rear Bumper Tires Condition: Fair Tire Problems: Unknown Additional Information: No Ignition - No Key</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

40	(1) 1998 International Crown By Carpenter School Bus Vin #0699 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #169A Passenger: 47 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: April 2019 Approx. Mileage (NOT ACTUAL): 316,804 Interior Condition: Fair Interior Problems: Needs Cleaning - Possible Parts Missing - Some Torn Seats Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Fuel Door Needs Repair - Roof Is Oxidized & Needs Cleaning - Minor Surface Rust On Right Rear - (1) Light Missing In Rear - Mild Damage On Left Rear Near Bumper - Rock Chips On Windshield - Peeling On Cowl & Hood - Possible Missing Parts Tires Condition: Fair Tire Problems: Unknown Additional Information: No Ignition - No Key</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
42	(1) 2003 Freightliner School Bus Vin #1137 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #240A Passenger: 47 Engine Size/Type: Cummins Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: October 2019 Approx. Mileage (NOT ACTUAL): Dash Has Been Removed - Unknown Interior Condition: Fair Interior Problems: Needs Cleaning - Possible Parts Missing - Some Torn Seats - Loose Panels - Missing Dash Body Condition: Fair Body Problems: Surface Scratches - Missing (1) Lense Cover On Rear - (1) Lense Cover Damaged On Rear - Missing (1) Passenger Window - Missing Lense On Hood Caution Light Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

<p>43</p>	<p>(1) 1995 International Thomas School Bus Vin #6438 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #744 Passenger: 71 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: August 2018 Approx. Mileage (NOT ACTUAL): 24,559 Interior Condition: Poor Interior Problems: Missing Both Roof Hatches - Seats Are Torn & Needs Cleaning - Parts Missing Throughout Bus Body Condition: Fair Body Problems: Hood Is Damaged & Unable To Operate - Missing Passenger Window - Oxidized Paint - Surface Scratches - Rock Chips On Windshield - Surface Scratches - Oxidized Paint - Scratches On Left Rear - Possible Parts Missing Tires Condition: Fair Tire Problems: Unknown Additional Information: Recommend Parts/Salvage Bus</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
<p>44</p>	<p>(1) 2003 Freightliner Thomas School Bus Vin #1132 - Will Need To Be Towed</p>	<p>Will Need To Be Towed Unit #258A Passenger: 47 Engine Size/Type: Cummins 15..9L/L-6 Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: May 2019 Approx. Mileage (NOT ACTUAL): Bash Has Been Removed - Unable To Read Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Parts Missing Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Roof Needs Cleaning - Scratches & Dents On Rear Right Corner Panel - Windshield Scratches From Bad Wiper Blades - Blinker Cover On Hood Missing Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

45	(1) 1998 International Crown By Carpenter School Bus Vin #9738 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #176A Passenger: 35 Engine Size/Type: 7.3L/V-8 Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: December 2018 Approx. Mileage (NOT ACTUAL): 221,754 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Parts Missing Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Scratches & Dent Behind Fuel Door On Right Side - Roof Is Oxidized & Needs Cleaning - Dent & Scratch On Left Rear Corner Panel - Small Scratch Behind Battery Door - Peeling On Cowl - Hood Latch Is Broken & Hood Is Damaged Where It Attaches To Bus Tires Condition: Fair Tire Problems: Unknown Additional Information: No Ignition - No Key</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
46	(1) 2000 International Thomas School Bus Vin #6063 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #816 Passenger: 71 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 205,214 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Possible Parts Missing - Drivers Seat Missing Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Peeling On Cowl & Hood - Roof Needs Cleaning - Mild Dents On Right Wheel Well - Possible Parts Missing - Rock Chips On Windshield Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

47	(1) 1998 International Crown By Carpenter School Bus Vin #9734 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #149A Passenger: 35 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: Unknown Approx. Mileage (NOT ACTUAL): 259,729 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Possible Parts Missing - Drivers Seat Missing Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Stop Arm Loose On Unit - Peeling On Cowl - Roof Is Peeling & Oxidized - Rock Chips On Windshield - Small Crack On Hood - Peeling On Hood - Possible Parts Missing Tires Condition: Fair Tire Problems: Unknown Additional Information: No Ignition - No Key</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
48	(1) 1995 International Thomas School Bus Vin #1610 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #721 Passenger: 71 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: October 2018 Approx. Mileage (NOT ACTUAL): 55,863 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Possible Parts Missing Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Scratches & Dent In Front On Right Side Wheel Well - Rock Chip On Windshield - Peeling On Cowl Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

49	(1) 1995 International Thomas School Bus Vin #1670 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #714 Passenger: 71 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: August 2018 Approx. Mileage (NOT ACTUAL): 256,028 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Possible Parts Missing Body Condition: Fair Body Problems: Oxidized Paint - Damage/Dents On Right Rear Panel - Surface Rust - Possible Parts Missing Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
50	(1) 2017 Bluebird School Bus Vin #2534 - Wrecked - Will Need To Be Towed	<p>Will Need To Be Towed Unit #450 Passenger: 71 Engine Size/Type: Unknown Engine Problems: Has Been Removed Transmission Has Been Removed Interior Condition: Poor Interior Problems: Seats, Windows & Various Other Parts Have Been Removed Body Condition: Poor Body Problems: Bus Has Been Wrecked - Parts Are Missing All Over Unit Tires Condition: Poor Tire Problems: Some Tires & Wheels Have Been Removed In Rear - Front Tires Are Flat Additional Information: Wrecked - No Ignition - No Key</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

51	(1) 1995 International Thomas School Bus Vin #1671 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #712 Passenger: 71 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Air Inspection Sticker Date: November 2018 Approx. Mileage (NOT ACTUAL): 294,505 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Possible Parts Missing Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Long Scratch On Right Rear Side - Peeling On Cowl & Hood - Possible Parts Missing Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
52	(1) 1996 International School Bus Vin #7911 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #139A Passenger: 47 Engine Size/Type: T444E Engine In Front Engine Problems: Unknown - Has Been Sitting Up - Possible Parts Missing Diesel Does Not Have Battery Does Not Run Automatic Brakes: Hydraulic Inspection Sticker Date: December 2018 Approx. Mileage (NOT ACTUAL): 256,100 Interior Condition: Fair Interior Problems: Needs Cleaning - Some Torn Seats - Possible Parts Missing Body Condition: Fair Body Problems: Oxidized Paint - Surface Scratches - Roof Paint Is Oxidized To Color Light Black - Peeling On Cowl - Possible Parts Missing - Some Peeling On Hood Tires Condition: Fair Tire Problems: Unknown</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	

53	(1) 1994 Ford E-150 Van Vin #7823 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #E-120 Passenger: 2 Engine Size/Type: 4.9L Engine In Front Engine Problems: Unknown Ran When Parked Gas Does Not Have Battery Does Not Run Automatic Inspection Sticker Date: December 2019 Approx. Mileage (NOT ACTUAL): No Battery Interior Condition: Fair Interior Problems: Needs Cleaning - Part Of Dash Missing Under Steering Wheel Body Condition: Fair Body Problems: Needs Cleaning Tires Condition: Fair Tire Problems: Unknown Additional Information: Protective Cage - Missing Door</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	
55	(1) 1998 Ford F150 Pickup Truck Vin #5662 - Will Need To Be Towed	<p>Will Need To Be Towed Unit #T-35 Passenger: 2 Engine Size/Type: 4.2L Engine In Front Engine Problems: Unknown - Not Running Gas Does Not Have Battery Does Not Run Automatic Inspection Sticker Date: November 2018 Approx. Mileage (NOT ACTUAL): 213,834 Interior Condition: Fair Interior Problems: Needs Cleaning Body Condition: Fair Body Problems: Peeling Paint - Dents & Rusted Rear & Front Bumper Tires Condition: Poor Tire Problems: Flat On Rear Drivers Side Additional Information: No Key</p> <p>There Will Be A \$35.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p> <p>Titles Will Not Be Available Until 7-10 Days After Payment Is Received.</p> <p>- Current Condition Unknown</p>	