

Lot Number	Title	Description
0	Preview & Removal Information	<p>All purchases will be subject to a 13% buyer's premium.</p> <p>Preview: (By Appointment Only-Mandatory-No Exceptions) Tuesday, November 13, 2018 (Hours Of Operation: 7:00 a.m. - 2:30 p.m.) Preview Contact: Nathan Spivey, (409)246-2822 Ext: 7</p> <p>Location: KISD Maintenance Shop, 1280 South Hickory, Kountze, Tx 77625 Driving Directions Removal: (By Appointment Only-Mandatory-No Exceptions) Monday, November 19, 2018/Tuesday, November 20, 2018/Wednesday, November 21, 2018 (Hours Of Operation: 7:00 a.m. - 2:30 p.m.) Removal Contact: John French, (409)651-2733</p>
1	(1) 1982 Chevy Truck Vin #4443 - Will Need To Be Towed	<p>Will Need To Be Towed - Engine Size/Type: Possibly 305/350, Unknown - Gas - Battery: Yes - Engine In Front - Engine Problems: Needs Throw-out Bearing & Transmission Is Hung In 1st Gear - Runs - Transmission: 4 Speed, Stuck In 1st Gear - Hydraulic Brakes - Standard - Interior Condition: Fair - Approx. Mileage: 36,155**Unknown Actual Mileage** - Body Condition: Poor - Body Problems: Dump Bed Wrecked When Parked, 1 Ton Truck But Rear Springs Have Been Built Up To Accommodate Heavier Loads - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
2	(1) 2002 Ford Crown Victoria Vin #4566 - Will Need To Be Towed	<p>Will Need To Be Towed - Engine Size/Type: 4.6L - Gas - Battery: Yes - Engine In Front - Engine Problems: Needs Alternator - Transmission Condition: Fair - Runs - Hydraulic Brakes - Automatic - Approx. Mileage Reads: 166,995 **Unknown Actual Mileage** - Interior Condition: Fair - Body Condition: Fair - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
3	(1) 1998 International School Bus Vin #5070 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 2 - Passengers: 72 - Engine Size/Type: 7.3L International 444E - Diesel - Battery: No - Engine In Front - Engine Problems: Needs Throttle Position Sensor - Runs - Transmission Condition: Fair - Air Brakes - Automatic - Approx. Mileage Reads: 107,482**Unknown Actual Mileage** - Interior Condition: Fair - Body Condition: Fair - Body Problems: Has Cracked Frame - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
4	(1) 1993 International School Bus Vin #4812 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 3 - Conventional Style - Passengers: 72 - Engine Size/Type: 7.3L International - Diesel - Battery: Yes - Engine In Front - Engine Problems: Has (2) Slung Rods - Does Not Run - Transmission Condition: Fair - Air Brakes - Automatic - Approx. Mileage Reads: 216,347**Unknown Actual Mileage** - Interior Condition: Unknown - Body Condition: Fair - Tires Condition: Poor - The Unit Will Have A 30 Day Wait For The Title</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

5	(1) 1997 International School Bus Vin #3289	<p>Will Need To Be Towed - Bus #: 7 - Conventional Style - Passengers: 72 - Engine Size/Type: 7.3 International 444E - Diesel - Battery: No - Engine In Front - Engine Problems: Has Electrical Problems - Does Not Run - Transmission Condition: Fair - Air Brakes - Automatic - Approx. Mileage Reads: 171,662**Unknown Actual Mileage** - Interior Condition: Fair - Body Condition: Fair - Body Problems: Has Cracked Frame - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
6	(1) 1997 International School Bus Vin #3288 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 10 - Conventional Style - Passengers: 72 - Engine Size/Type: 7.3L International 444E - Diesel - Battery: No - Engine In Front - Engine Problems: Needs IPR Valve - Does Not Run - Transmission Condition: Fair - Air Brakes - Automatic - Approx. Mileage Reads: 102,650**Unknown Actual Mileage** - Interior Condition: Fair - Body Condition: Fair - Body Problems: Has Cracked Frame - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
7	(1) 1998 International School Bus Vin #5071 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 11 - Conventional Style - Passengers: 72 - Engine Size/Type: 7.3L International 444E - Diesel - Battery: No - Engine In Front - Runs - Transmission Condition: Fair - Air Brakes - Automatic - Approx. Mileage Reads: 112,009**Unknown Actual Mileage** - Interior Condition: Fair - Body Condition: Fair - Body Problems: Cracked Frame - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
8	(1) 1991 International School Bus Vin #9372 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 15 - Conventional Style - Passengers: 72 - Engine Size/Type: 7.3L IDI International - Diesel - Battery: Yes - Engine In Front - Engine Problems: Electrical System needs Rewired - Runs - Transmission Condition: Fair - Air Brakes - Automatic - Approx. Mileage: 218,060**Unknown Actual Mileage** - Interior Condition: Unknown - Body Condition: Fair - Tires Condition: Poor</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
9	(1) 2004 International School Bus Vin #6740 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 21 - Conventional Style - Passengers: Unknown - Engine Size/Type: Diesel DT466 International - Diesel - Battery: No - Engine In Front - Runs - Transmission Condition: Fair - Air Brakes - Automatic - Approx. Mileage: 101,399**Unknown Actual Mileage** - Interior Condition: Fair - Wheel Chair Lift, Condition Unknown - Body Condition: Fair - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

10	(1) 1992 International School Bus Vin #2361 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 41 - Conventional Style - Passengers: 72 - Engine Size/Type: 360 International - Diesel - Battery: Yes - Engine In Front - Runs - Transmission Condition: Fair - Air Brakes - Automatic - Approx. Mileage: 102,031 **Unknown Actual Mileage** - Interior Condition: Unknown - Body Condition: Poor - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
11	(1) 1992 International School Bus Vin #2360 - Will Need To Be Towed	<p>Will Need To Be Towed - Bus #: 58 - Conventional Style - Passengers: 72 - Engine Size/Type: 360 International - Diesel - Battery: Yes - Engine In Front - Runs - Transmission Condition: Fair - Air Brakes - Automatic - Approx. Hub Reads: 62,840 **Unknown Actual Mileage - Rebuilt 10-15-14 - Interior Condition: Fair - Body Condition: Poor - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>