

Lot Number	Title	Description
0	Preview & Removal Information	<p>All purchases will be subject to a 13% buyer's premium.</p> <p>Preview: (By Appointment Only - No Exceptions) Thursday, December 6, 2018 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.) Location 1: (Lots 1-26) Livingston ISD Transportation, 3350 Bus Lane, Livingston, Texas 77351 Driving Directions Removal: (By Appointment Only - No Exceptions) Wednesday, December 12, 2018/Thursday, December 13, 2018 /Friday, December 14, 2018 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.) Preview & Removal Contact: Sara Vega, (936)328-2280 No Working on Vehicle on Premises, Bring Your own Jumper Cables, Batteries, Towing Equipment.</p> <p>Location 2: (Lots 27-32) Livingston ISD Distribution Center, 1630 Hwy 146 S, Livingston, Tx 77351 Driving Directions Removal: (By Appointment Only - No Exceptions) Wednesday, December 12, 2018/Thursday, December 13, 2018 /Friday, December 14, 2018 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.) Preview & Removal Contact: Lisa Pearson, (936) 425-1249 Buyer must bring own man power for removal.</p> <p>Location 3: (Lots 33-53) Old Carpenter Shop & Special Education Center, 601 N. Jackson, Livingston, TX 77351 Driving Directions Removal: (By Appointment Only - No Exceptions) Wednesday, December 12, 2018/Thursday, December 13, 2018 /Friday, December 14, 2018 (Hours Of Operation: 8:00 a.m. - 3:00 p.m.) Preview & Removal Contact: Lisa Pearson, (936) 425-1249 Buyer must bring own man power for removal.</p>
1	(1) 2007 Chevy LS Suburban Vin #3486 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Unit #: 7 - Conventional Style - Passengers: 8 - Engine Size/Type: 5.3L - Gas - Battery: Yes/Dead - Engine In Front - Engine Problems: Bad Motor, Runs Hot, Auctioneer Recommends Towing - Runs - Hydraulic Brakes - Automatic - Approx.. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Worn, Some Holes On Upholstery, Crack On Dash, Stains On Upholstery - Body Condition: Fair - Inspection Sticker Date: 12/18 - Body Problems: Minor Surface Scratches, Some Peeling Paint - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
2	(1) 2001 Chevy LS Suburban Vin #1807 - Will Need To Be Towed	<p>Will Need To Be Towed - Unit #: 5 - Conventional Style - Passengers: 8 - Engine Size/Type: 5.3L - Gas - Battery: Yes /Dead - Engine In Front - Engine Problems: Unknown - Runs - Bad Transmission - Hydraulic Brakes - Automatic - Approx. Mileage Unable To Read/Dead Battery - Interior Condition: Fair - Interior Problems: Worn, Seat Worn Drivers Side, Stains On Upholstery, Cracked Dash, Needs Cleaning, Brake Release Pull Knob Loose On Floor - Body Condition: Fair - Inspection Sticker Date: 02/19 - Body Problems: Dent On Left Front Wheel Well, Scrape On Left Passenger Door, Surface Scratches, Dent On Front Bumper - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
3	(1) 2002 International School Bus Vin #4429 - Will Need To Be Towed	<p>Will Need To Be Towed - Recommend Salvage Or Parts - Conventional Style - Bus #: F100 - Passengers: 71 - Engine Size /Type: DI466 - Diesel - Battery: No - Engine In Front - Engine Problems: Parts Missing - Does Not Run - Air Brakes - Automatic - Approx. Mileage Reads: 206,601**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Parts Missing, Rescue Roof Hatches Missing - Body Condition: Fair - Inspection Sticker Date: 07/19 - Body Problems: Surface Scratches, Passenger Windows Missing, Dent On Left Rear, Windshield Scratches From Windshield Wiper - Tire Problems: Missing Left Rear Tire & Wheel</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

4	(1) 1998 International Thomas School Bus Vin #0430 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: 73 - Conventional Style - Passengers: 71 - Engine Size/Type: DT466E - Diesel - Battery: Yes/dead - Engine In Front - Engine Problems: Unknown/Ran When Parked - Current Condition Unknown - Air Brakes - Automatic - Approx. Mileage Reads: 213,943**Unknown Actual Mileage** - Interior Condition: Fair - Inspection Sticker Date: 06/18 - Body Problems: Oxidized Paint, Surface Scratches, Peeling On Hood & Cowl, Some Scratches & Dent, Indention On Left Rear Behind Wheel Panel - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
5	(1) 1997 International Thomas School Bus Vin #1544 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: F67 - Conventional Style - Passengers: 77 - Engine Size/Type: DT466E - Diesel - Battery: Yes/Dead - Engine In Front - Engine Problems: No Oil Pressure - Will Start - Auctioneer Recommends Towing - Air Brakes - Automatic - Approx. Mileage Reads: 85,368**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Torn Seats, Needs Cleaning, Drivers Seat Torn, Floor Will Need Repair In Future/Soft Spots - Body Condition: Fair - Inspection Sticker Date: 07/18 - Body Problems: Oxidized Paint, Large Indention Of Right Side Below Windows 5-7, Indention On Lower Panel In Front Of Rear Wheel On Right Side, Surface Scratches, Dent On Rear Bumper, Scratches On Left Side Below Drivers Window, Peeling On Hood & Cowl, Cracked Windshield</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
6	(1) 2005 Chevy Van Bus Vin #2334 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Bus #: 114 - Conventional Style - Passengers: 19 Passengers W/ (1) Wheel Chair Space - Engine Size/Type: 6.0L Vortec - Gas - Battery: Yes - Engine In Front - Engine Problems: No Oil Pressure - Will Run - Auctioneer Recommends Towing - No Key - Hydraulic Brakes - Automatic - Approx. Mileage Reads: 198,223**Unknown Actual Mileage** - Interior Condition: Fair - Wheel Chair Lift, Condition: Unknown - Interior Problems: Needs Cleaning, Tears On Drivers Seat - Body Condition: Fair - Inspection Sticker Date: 08/18 - Body Problems: Oxidized Paint, Surface Scratches, Surface Rust On Roof - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
7	(1) 2003 Chevy Mid Van Bus Vin #0823	<p>Bus #: 108 - Conventional Style - Passengers: 12 Passengers & (1) Wheel Chair Space - Engine Size/Type: 6.0L - Gas - Battery: Yes - Engie In Front - Engine Problems: Unknown - Run - Hydraulic Brakes - Automatic - Approx. Mileage Reads: 211,504**Unknown Actual Mileage** - Interior Condition: Fair - Wheel Chair Lift, Condition: Unknown - Interior Problems: Drivers Seat Poor/Torn, Floor Questionable In A Couple Of Spot, A Few Torn Passenger Seats - Body Condition: Fair - Inspection Sticker Date: 07/18 - Body Problems: Oxidized Paint, Scratches On Right Rear, Peeling Rear Bumper, Some Peeling, Surface Scratches, Missing (1) Mirror, Peeling On Hood - Tires Condition: Fair - Tire Problems: Left Rear Questionable, Remainder Fair Condition</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

8	(1) 2001 International 3800 Bluebird School Bus Vin #0541	<p>Bus #: 97 - Conventional Style - Passengers: 72 - Engine Size/Type: DT466E - Diesel - Battery: Yes/dead - Engine In Front - Engine Problems: Unknown - Ran When Parked 1 Year Ago - Air Brakes - Automatic - Approx. Mileage Reads: 022,003 **Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats All Need To Be Replaced, Some Interior Panels Are Loose & Need To Be Reattached - Body Condition: Fair - Inspection Sticker Date: 07/18 - Body Problems: Oxidized Paint, Surface Scratches, Peeling On Cowl & Hood, Surface Rust, Indention On Left Rear Panel - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
9	(1) 1999 International 3800 Thomas School Bus Vin #6120 - Will Need To Be Towed	<p>Will Need To Be Towed - Auctioneer Recommends Salvage Or Scrap Use - Bus #: 81 - Conventional Style - Passengers: 72 - Engine Size/Type: DT466E - Diesel - Battery: No - Engine In Front - Engine Problems: Parts Missing - Does Not Run - Air Brakes - Automatic - Dash Removed - Interior Condition: Poor - Interior Condition: Seats Are Poor, Parts Missing - Body Condition: Poor - Inspection Sticker Date: N/A - Body Problems: Missing (1) Windshield, Oxidized Paint, Scratches, Some Dents, Parts Missing - Tires Condition: Fair To Poor</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
10	(1) 2002 International School Bus Vin #4430 - Will Possibly Need To Be Towed	<p>Will Possibly Need To Be Towed - Conventional Style - Bus #: 101 - Passengers: 71 - Diesel - Battery: Yes/Dead - Engine In Front - Engine Problems: Ran When Parked A Year Ago, Current Condition Unknown - Air Brakes - Automatic - Approx. Mileage Reads: 047,231**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Loose Panels, Drivers Seat Torn, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 07/18 - Body Problems: Oxidized Paint, Surface Scratches, Large Dent Rear Bumper, Drivers Side Window Missing, Crack On Small Window On Drivers Side, Front Bumper Is On Ground & Needs To Be Reattached - Tires Condition: Fair To Poor - Tire Problems: Left Rear Tire Is Flat & Off Rim</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
11	(1) 2009 International BE200 School Bus Vin #8235 - Will Need To Be Towed	<p>Will Need To Be Towed - Recommend Salvage Or Scrap - Bus #: 127 - Conventional Style - Passengers: 24 Passengers, (1) Wheel Chair - Engine Size/Type: Maxx Force 7 - Diesel - Battery: No - Engine Problems: Bad Engine, Parts Missing - Does Not Run - Hydraulic Brakes - Automatic - Approx. Mileage Reads: 176,860**Unknown Actual Mileage** - Interior Condition: Fair - Wheel Chair Lift, Condition Unknown - Interior Problems: Seats Needs Cleaning, Some Are Torn, Parts Missing - Body Condition: Fair - Inspection Sticker Date: 07/18 - Body Problems: Parts Missing On Rear Right, Oxidized Paint, Surface Scratches, Front Bumper Removed, Hood Loose On Unit - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

12	(1) 2000 International Thomas School Bus Vin #3367	<p>Bus #: 83 - Conventional Style - Passengers: 71 - Diesel - Battery: Yes/Dead - Engine In Front - Engine Problems: Unknown - Runs - Air Brakes - Automatic - Approx. Mileage Reads: 243,784**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Torn Seats, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 07/19 - Body Problems: Oxidized Paint, Scratches, Peeling On Cowl, Oxidized Hood, Windshield Scratched From Windshield Wiper Blade - Tire Problems: Right Rear Tire Flat & Off Rim, Most Tires Are Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
13	(1) 1998 International Thomas 3800 School Bus Vin #0429	<p>Bus #: 72 - Conventional Style - Passengers: 72 - Engine Size/Type: DT466E - Diesel - Battery: Yes/Dead - Engine In Front - Engine Problems: Perm Down - Runs - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/or Removed - Air Brakes - Automatic - Inspection Sticker Date: 08/19 - Approx. Mileage Reads: 249,703**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats & Needs Cleaning - Body Condition: Fair - Body Problems: Oxidized Paint, Surface Scratches, Some Peeling Paint, Dent On Right Rear, Rear Bumper Out Of Alignment, Peeling On Cowl & Hood, Scratches On Windshield From Windshield Wipers - Tires Condition: Good To Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
14	(1) 1997 International Thomas School Bus Vin #1546	<p>Bus #: 68 - Conventional Style - Passengers: 71 - Engie Size/Type: DT466E - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/or Remove - Engine In Front - Engine Problems: Unknown - Runs - Air Brakes - Automatic - Approx. Mileage Reads: 247,626**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Seats Are Torn, Drivers Seat Torn, Interior Worn - Body Condition: Fair - Inspection Sticker Date: 08/19 - Body Problems: Oxidized Paint, Surface Scratches, Minor Dents, Rear Door Glass Broken, Peeling on Hood - Tires Condition: Good To Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
15	(1) 1997 International Thomas 3800 School Bus Vin #1545	<p>Bus #: 66 - Conventional Style - Passengers: 71 - Engine Size/Type: DT466E - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/or Removed - Engine In Front - Engine Problems: Unknown - Run - Air Brakes - Automatic - Approx. Mileage Reads: 232,372**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Drivers Seat Torn, Some Torn Passenger Seats, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 07/19 - Body Problems: Large Indention On Lower Panel On Right Side Under 4-6 Windows, Oxidized Paint, Surface Scratches, Peeling On Cowl & Hood, Scratches On Front Windshield From Windshield Wipers, Scratch On Roof On Right Side - Tires Condition: Good To Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

16	(1) 1997 International Thomas 3800 School Bus Vin #1543	<p>Bus #: 65 - Conventional Style - Passengers: 71 - Engine Size/Type: DT466E - Diesel - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Air Brakes - Automatic - Approx. Mileage Reads: 231,283**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Are Torn & Needs Replacing Or Repair, Needs Cleaning - Body Condition: Fair - Body Problems: Large Scratch On Right Side Under 3-6 Windows, Dent Rear Bumper, Oxidized Paint, Surface Scratches, Peeling On Cowl & Hood, Scratches On Windshield From Windshield Wipers, Crack On One Side Of Windshield - Inspection Sticker Date: 08/19 - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
17	(1) 1997 International Thomas 3800 School Bus Vin #1547	<p>Bus #: 69 - Conventional Style - Passengers: 71 - Engine Size/Type: DT466E - Diesel - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Air Brakes - Automatic - Approx. Mileage Reads: 094,307**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 06/19 - Body Problems: Large Dent In Front Of Right Rear Wheel Well, Oxidized Paint, Scratches, Dent On Rear Bumper, Peeling On Cowl & Hood - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
18	(1) 1998 International Thomas 3800 School Bus Vin #0428	<p>Bus #: 75 - Conventional Style - Passengers: 71 - Engine Size/Type: DT466E - Diesel - Battery: Yes - Engine In Front - Engie Problems: Unknown - Runs - Air Brakes - Automatic - Approx. Mileage Reads: 242,794**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 07/19 - Body Problems: Oxidized Paint, Surface Scratches, Some Peeling Paint, Peeling On Cowl & Hood - Tires Condition: Good To Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
19	(1) 1999 International Thomas School Bus Vin #6116	<p>Bus #: 77 - Conventional Style - Passengers: 71 - Engine Size/Type: DT466E - Diesel - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Air Brakes - Automatic - Approx. Mileage Reads: 232,655**Unknown Actual Mileage** - Interior Condition: Poor - Interior Problems: Seats Are Torn All Over Bus, Will Need To Be Replaced Or Repaired, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 08/19 - Body Problems: Oxidized Paint, Surface Scratches - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>

20	(1) 1999 International Thomas 3800 School Bus Vin #6117	<p>Bus #: 78 - Conventional Style - Passengers: 71 - Engine Size/Type: DT466E - Diesel - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Air Brakes - Automatic - Approx. Mileage Reads: 190,027**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: 06/19 - Body Problems: Oxidized Paint, Surface Scratches, Dents On Right Wheel Well & Surface Rust, Scratches On Roof, Peeling On Cowl & Hood - Tires Condition: Good To Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
21	(1) 2004 International School Bus Vin #1132	<p>Bus #: 103 - Conventional Style - Passengers: 71 - Diesel - Battery: Yes - Engine In Front - Engine Problems: Unknown - Runs - Air Brakes - Automatic - Approx. Mileage Reads: 152,188**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning - Body Condition: Fair - Inspection Sticker Date: NA - Body Problems: Missing (2) Passenger Windows, Oxidized Paint, Surface Scratches, Some Peeling Paint, Some Surface Rust - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
22	(1) 2001 International Bluebird 3800 School Bus Vin #0542	<p>Bus #: 98 - Conventional Style - Passengers: 71 - Engine Size/Type: DT466E - Diesel - Battery: Yes/Dead - Winning Bidder Is Responsible For Bringing Own Batteries, Equipment, Etc. To Get Vehicle Started And/or Removed - Engine In Front - Engine Problems: Unknown - Runs - Air Brakes - Automatic - Approx. Mileage Reads: 267,567**Unknown Actual Mileage** - Interior Condition: Fair - Interior Problems: Some Torn Seats, Needs Cleaning, Possible Floor Repair In Spots - Inspection Sticker Date: 07/19 - Body Problems: Oxidized Paint, Surface Scratches, Dent On Right Rear, Some Peeling Paint, Rust On Rear Bumper, Peeling On Cowl & Hood, Rock Chip On Windshield - Tires Condition: Fair</p> <p>Current Condition Unknown</p> <p>There Will Be A \$20.00 Title Preparation Fee Added To The Buyers Total For Each Unit Purchased.</p> <p>**All defects and flaws with a vehicle will be the buyers responsibility once purchased by buyer. Buyer should be aware that they are purchasing a used vehicle as it sits on the auction location with No warranty or Guarantee Whatsoever. Seller and Auctioneer have made a diligent attempt to supply the buyer with a general description of each unit and do not guarantee the accuracy of the information supplied. Seller and Auctioneer recommend Buyers to thoroughly inspect each vehicle prior to bidding.**</p>
23	(1) DT466 Engine	<p>Operable - Missing Front Timing Cover - Oil Cooler - Turbo - Mfg: International</p> <p>Current Condition Unknown</p>
24	(1) Snap On Computer Wheel Balance	<p>Current Condition Unknown</p>
25	(1) Fox Valley Load Control Batter Load Tester	<p>Portable</p> <p>Current Condition Unknown</p>
26	(1) Speedaire Air Compressor	<p>Will Work - Problem (1) Valve On Compressor Head Is Bad - 3 Phase - 10 HP - 208/230/460 - Model: 5Z640A2</p> <p>Current Condition Unknown</p>
27	(1) Vulcan Braiser	<p>Needs Repair - (1) Broken Leg - Gas</p> <p>Current Condition Unknown</p>
28	(1) Duke Levelator	<p>Needs Repair - Portable</p> <p>Current Condition Unknown</p>
29	(1) Crescor Crown X Warmer	<p>Table Top Model - Bottom Pan Bent</p> <p>Current Condition Unknown</p>

30	(1) Keating Warming Light	115 Volts - 500 Watts - Model: 210R Current Condition Unknown
31	(Lot) Dispensers	(Approx. 4 Pallets) Including: Paper Towel, Toile Paper, & Soap Current Condition Unknown
32	(Lot) Lunch Trays	(Approx. 500) (1 Pallet) Used - Color: Solid & Translucent Green Current Condition Unknown
33	(1) Lincoln AC 225 Arc Welder	Electric - Model: AC225 Current Condition Unknown
34	(1) Lincoln AC 225 Arc Welder	Electric - Model: AC226 Current Condition Unknown
35	(1) Lincoln AC 225 Arc Welder	Electric - Model: AC227 Current Condition Unknown
36	(Lot) Stationary Trampolines	(Approx. 2) Used For Walking In Place - Some Tears On Canvas Current Condition Unknown
37	(1) Roper Washer	HD Capacity - 2 Speed - Super Capacity - Worked At Time Of Removal Current Condition Unknown
38	(1) Frigidaire Freezer	Worked At Time Of Removal Current Condition Unknown
39	(1) Yamaha Upright Piano	Left Outside & Has Water Damage On Left Side - Some Keys Have Damage - All Keys Are Working Current Condition Unknown
40	(Lot) Bar Bells	(Approx. 24) Assorted Sizes & Weights Current Condition Unknown
41	(Lot) Athletic Lockers	(approx. 6) Color: Green - Has Under Seat Stocker - Mfg: Wildcat Fitness Equipment - Tahoka Tx Current Condition Unknown
42	(Lot) Paper Towel Dispensers	Qty: Unknown Current Condition Unknown
43	(Lot) File Cabinets	(Approx. 3) 4 Drawer - Legal & Letter Current Condition Unknown
44	(Lot) File Cabinets	(Approx. 8) Letter & Legal - 4 Drawer Current Condition Unknown
45	(Lot) Kitchen Items	Including: Measuring Spoons, Food Processors, Coffee Maker, Blenders, Waffle Maker, Wooden Spoons & Misc. Current Condition Unknown
46	(Lot) Wood Bookcases	(Approx. 3) W/ Coat Hooks - Double Sided - Shop Made Current Condition Unknown
47	(Lot) Computer Carts	(Approx. 3) Current Condition Unknown
48	(Lot) Metal Carts	(Approx. 5) Plastic & Metal Current Condition Unknown
49	(Lot) Computer Stands	Including: (Approx. 4) Portable, (1) Stationary Current Condition Unknown
50	(Lot) Furniture & Misc.	Including: (Approx. 2) Pre-K Book Racks - Double Sided, (1) Educational Material Rack/Box - Portable Current Condition Unknown

51	(1) Groen Kettle	Buyer Must Bring Own Removal Equipment Current Condition Unknown
52	(1) Cleveland Steamer	SteamCraft Power 10 - Buyer Must Bring Own Removal Equipment Current Condition Unknown
53	(1) Stajac Industries Freezer	Portable - Excellence - Model: Euro-13 - 115 Volts Current Condition Unknown
54	(1) Frame Overhaul Kit	DT/DTA Series For A DT466 - Bought From International Current Condition Unknown
55	(1) Rebuild Engine Kit	For DT 466 - Bought From Chalks Current Condition Unknown